



GC06

Atlanta, Georgia

Mike Jendreas/Dealer Operator-GM

Mike1@emichauto.com

Austin Schutt / Service Manager

Aschutt@emichauto.com

MENU I+A1:E39TEMS Starting 7-16-2025

COMMON SERVICES		Op-code	Labor Time	MENU PRICE
TIRE REPAIR (patch/plug repair only)	Only when necessary	02CVZ07	0.8	\$ 59.99
TPMS REPLACEMENT (PER TPMS)	Only when necessary	46CVZ00	0.5	\$ 49.99
MOUNT AND BALANCE 1 TIRE	Only when necessary	02CVZTIRES1	0.4	\$ 29.99
MOUNT AND BALANCE 2 TIRES	Only when necessary	02CVZTIRES2	0.8	\$ 59.99
MOUNT AND BALANCE 3 TIRES	Only when necessary	02CVZTIRES3	1.2	\$ 89.99
MOUNT AND BALANCE 4 TIRES	Only when necessary	02CVZTIRES4	1.5	\$ 119.99
MOUNT AND BALANCE 5 TIRES	Only when necessary	02CVZTIRES5	1.8	\$ 149.99
MOUNT AND BALANCE 6 TIRES	Only when necessary	02CVZTIRES6	2	\$ 179.99
BATTERY (Battery test and replacment 12V)	Only when necessary	50CVZ07	0.8	SPG
FRONT BRAKES	Only when necessary	SPG	1.6	160/HR
REAR BRAKES	Only when necessary	SPG	1.6	160/HR
REAR BRAKES WITH ELECTRONIC PARKING BRAKE	Only when necessary	SPG	2	160/HR
MPI (FREE WITH SERVICE)	EVERY SERVICE	00CVZ00	0	FREE
BRAKE INSPECTION (No \$/Labor if brakes sold)	when a concern is present	40CVZZ	0.5	\$ 79.99
OIL CHANGE	5,000 miles/ 6 months	02CVZ04	0.4	35.00/LABOR
44k AC Delco GAS FUEL ADDITIVE	5,000 miles/ 6 months	00CVZBG44K	0	\$ 23.99
25G DIESEL FUEL SYSTEM ADDITVE	5,000 miles/ 6 months	00CVZD25G	0	\$ 25.99
45G DIESEL FUEL ADDITIVE	5,000 miles/ 6 months	00CVZD40G	0	\$ 60.99
ROTATE TIRES	5,000 miles/6 months	02CVZ08	0.3	\$ 24.99
ROTATE AND BALANCE WHEELS	10,000 miles/1 year	00CVZ29	0.8	\$ 99.99
REPLACE FRONT WIPER BLADES	10,000 miles/1 year	00CVZ33	0	SPG
REPLACE REAR WIPER	10,000 miles/1 year	00CVZ34	0	SPG
REPLACE REAR WIPER	10,000 miles/1 year	00CVZ34	0	SPG
2 WHEEL ALIGNMENT	10,000 miles/1 year	45CVZ05	0.9	\$ 99.99
4 WHEEL ALIGNMENT	10,000 miles/1 year	45CVZ06	1.6	\$ 139.99
BEST FUEL SERVICE (3-PART)	15,000 miles/ 1.5 years	00CVZ13	1.5	\$ 299.99
DIESEL FUEL SERVICE/2312	15,000 miles/ 1.5 years	00CVZ14	2	\$ 469.99
GDI FUEL SERVICE (2-PART)	15,000 miles/ 1.5 years	00CVZ15	1.5	\$ 249.99
BRAKE FLUID FLUSH/85032	20,000 miles/ 2 years	00CVZ16	1	\$ 199.99
POWER-STEERING FLUSH/3050	20,000 miles/ 2 years	00CVZ23	1	\$ 234.99
CABIN/POLLEN FILTER LABOR	20,000 miles/2 years	11CVZ00	0.5	34.99/LABOR
FUEL FILTER	30,000 miles/3 years	10CVZ04	0.8	SPG
AIR FILTER	40,000 miles/4 years	00CVZAIRFILTER	0.3	24.99/LABOR
TRANSFER CASE SERVICE over 8600lbsGVW	25,000 miles/ 2.5 years	30CVZZ	SPG	SPG
TRANSFER CASE SERVICE under 8600 lbs GVW	45,000 miles/ 4.5 years	30CVZZ	SPG	SPG
AUTO TRANS FLUSH/3020	45,000 miles/ 5 years	00CVZ06	SPG	SPG
BEST AUTO TRANS FLUSH/3020	45,000 miles/ 5 years	00CVZ10	SPG	SPG
BEST DIESEL TRANS FLUSH	45,000 miles/ 5 years	00CVZ12	SPG	SPG
DIESEL TRANS SERVICE	45,000 miles/ 4.5 years	00CVZ20	SPG	SPG
4X4 SERVICE/ 5-752/328(T-case, both diffs)	45,000 miles/ 4.5 years	00CVZ4X4	SPG	SPG
4X4 BEST SERVICE/5-752/328/3020(trans,t-case,both diffs)	45,000 miles/ 4.5 years	00CVZ4X4BEST	SPG	SPG
FRONT DIFF SERVICE	45,000 miles/ 4.5 years	47CVZ06	SPG	SPG
REAR DIFF SERVICE	45,000 miles/ 4.5 years	47CVZ07	SPG	SPG
COOLANT FLUSH/ 3050	60,000 miles / 6 years	00CVZ19	1	\$ 239.99
SPARK PLUGS	60,000 miles / 6 years	10CVZ07	SPG	SPG
SERPENTINE BELTS	60,000 miles / 6 years	00CVZBELTS	SPG	SPG
PROGRAM KEYS/FOBS(FOR OLDER FOB PROGRAMMINGS 0.5HRS)		50CVZKEY	1	\$ 160.00
OTHER COMMON MENU ITEMS/OP CODES				
CUSTOMER DETAIL		90CVZ05	4	\$ 249.99
CUSTOMER EXTREME DETAIL		90CVZ06	5.5	\$ 349.99
NEW VEHICLE PDI		75CVZ	warranty	warranty
WORRY FREE/CERTIFIED INSPECTION (USED VEHICLE)		80CVZ01	1.5	\$ 295.00

SOP: Special-Order Parts (SOP) List Process for Service Advisors

1. Daily SOP Parts List Distribution

- The Parts Department will send an electronic copy of the SOP Parts List Advisor Group Email DAILY
- Parts will Flag Open Repair Orders in X-Time **Purple** indicating all parts here

2. BDC Support Tasks

- BDC -Will assist, where time permits in scheduling customers back in. This will require a high level of communication from each advisor:
 - How long will the repairs take
 - Will a loaner/rental be provided
 - What the repair consists of (in case the customer cannot remember the details)

3. Advisor Documentation Responsibilities

- Advisors must maintain accurate, up-to-date documentation for every special-order part.
- Notes should clearly reflect the status, such as:
 - "Waiting for customer to find time for a scheduled visit"
 - "Appointment scheduled for 2-15-22"
 - "Customer no longer wants to do repair"
- Documentation must be retained and kept organized for reference

4. Customer Contact & Scheduling Requirements

- Advisors are responsible for contacting customers to schedule return visits once parts arrive.
- All available contact methods must be used: phone calls, text messages, voicemails, and emails.
- 4 Contact attempts (using all contact methods) over a 2-week period Minimum.
- If the customer does not respond after all contact methods have been exhausted, the advisor must notify the customer of the date the part will be released and sold to another customer/dealer
- **No SOP part should remain on the list for more than 90 days.**
- **At 90 Days**, the part must be removed from the SPL sheet. Advisors must ensure they have completed all due-diligence steps before removal.

5. Daily SPL Sheet Maintenance

- Advisors must update and review the SPL sheet every day.
- When a repair is completed, the advisor must ensure the customer and RO are removed from the SPL sheet promptly.
- Advisors are responsible for communicating with Parts to ensure accurate removal.

6. Accountability & Disciplinary Standards

- Failure to perform due diligence may result in disciplinary action. Examples include:
 - A customer called later to discover their part was sold without proper contact attempts.
 - A special-order part customer not being contacted within 30 days of part arrival.
- These situations justify a formal write-up or other disciplinary measures as appropriate.

Initiatives Implemented to Increase Sales/gross

1. Menu Update & Mileage-Based Recommendations

We redesigned our service menu to include approximate mileage recommendations for all maintenance items, and ensured every technician has a copy. This change significantly improved the accuracy and consistency of our ASR recommendations, particularly within the Quick Lube team.

Previously, technicians relied on memory or rough guesses, which often resulted in inaccurate mileage-based recommendations. With the updated menu:

- Technicians can quickly verify when a service should be recommended.
- Advisors double-check service history before sending quotes.
- **Quote utilization (electronically sent quotes) increased by 19.8%.**

2. Increased Return Visits by Fixing X-Time / Reynolds & Reynolds Workflow Issues

We identified a major issue mid-2025 involving the interaction between Reynolds & Reynolds and X-Time. In some cases, declined quotes were not receiving a “thumbs down,” causing the ASR to disappear entirely.

This mean:

- Declined repairs were not showing up later as customer-declined work.
- X-Time marketing could not trigger reminders to bring customers back.
- Recommendations were lost for future scheduling and follow-up.

How we identified the issue: In X-Time → Inspect Dashboard → Performance Tab → Closed Tab → scroll right → the column labeled “ASRs Undecided” shows ASRs that were neither approved nor denied. These were the missing recommendations.

Impact: By monitoring this closely and holding advisors accountable, we increased the accuracy of recommendations tracked in X-Time by 70%.

3. Quick Lube Pay Structure Redesign

We identified three major opportunities within the Quick Lube department. Previously, the Quick Lube leader was flat rate and received all flagged hours, while the four Quick Lube technicians were hourly. This structure:

- Limited earning potential for the technicians
- Created inefficiencies
- Resulted in a **39% gross profit margin** in Quick Lube

Changes Implemented

- Transitioned all Quick Lube technicians to a **flat-rate pay plan with a guaranteed minimum**.
- The guarantee ensures they earn at least their previous hourly wage, while flat rate allows motivated technicians to earn more through efficiency.
- This change increased Quick Lube gross profit margin from **39% to 66% — a 27% improvement**.

Additional Benefits

- Improved visibility into individual technician performance.
- Better ability to evaluate which technicians are strong candidates for apprenticeship programs.
- Avoids investing years into apprentices who ultimately do not want to work flat rate.