

Rysunek zlozeniowy / lista czesci - YG-05322

PDF roboczy wygenerowany automatycznie z folderu: YG-05322

Zrodla w folderze: DOC/DOCX: 2, PDF: 2, obrazy: 0. Oryginalne pliki robocze pozostaja w archiwum/Drive; ta wersja ujednolica dane do aplikacji.

Poz.	Indeks SAP	Nazwa PL	Nazwa EN
1	ZG05322-01	CABINET	CABINET
2	ZG05322-02	STOPY	FEET
3	ZG05322-03	WŁĄCZNIK	POWER SWITCH
4	ZG05322-04	KONTROLER	CONTROLLER
5	ZG05322-05	SKRAPLACZ	CONDENSER
6	ZG05322-06	RURKA	CAPILLARY
7	ZG05322-07	OSUSZACZ	DRYER FILTER
8	ZG05322-08	COOLING UNIT BOARD	COOLING UNIT BOARD
9	ZG05322-09	CZUJNIK	PROBE
10	ZG05322-10	WENTYLATOR	COND. FAN
11	ZG05322-11	COND. FAN CONNECT METAL SHEET	COND. FAN CONNECT METAL SHEET
12	ZG05322-12	COMPRESSOR	ZUG-000083
13	ZG05322-13	SUPPORT BOARD FOR COMPRESSOR UNIT	SUPPORT BOARD FOR COMPRESSOR UNIT
14	ZG05322-14	LARGE PLASTIC BUTTON	LARGE PLASTIC BUTTON
15	ZG05322-15	RIGHT SIDE COVER	RIGHT SIDE COVER
16	ZG05322-16	POWER CORD	POWER CORD
17	ZG05322-17	TOP COVER	TOP COVER
18	ZG05322-18	CACHEPOT	CACHEPOT
19	ZG05322-19	GLASS FIXED (WITH SCREW)	GLASS FIXED (WITH SCREW)
20	ZG05322-20	SZYBA BOCZNA	SIDE GLASS
21	ZG05322-21	GUMOWY WKŁAD	RUBBER SLEEVE
22	ZG05322-22	ŁACZNIK	GLASS CONNECT
23	ZG05322-23	SZYBA GÓRNA	TOP GLASS
24	ZG05322-24	SZYBA CZOŁOWA	REAR GLASS
25	ZG05322-25	ŚRUBA I NAKRĘTKA	GLASS CONNECT SCREW AND NUT