
12 11 10 9 8 7 6 5 4 3 2

Notes

- 1. ALL DIMENSIONS ARE MM
- 2. THE MATERIALS AND MANUFACTURING METHODS USED MUST COMPLY WITH ROHS 2002/95/EC.
- 3. ALL DIMENSIONS SHOWN SHALL BE CONSIDERED CRITICAL TO FUNCTION AND CHECKED DURING FIRST ARTICLE INSPECTION.
- 4.ALL CUT/SHARP EDGES WILL BE TREATED FOR OXYDATION PREVENTION.
- 5. COMPONENT SHALL BE CLEAN AND FREE FROM FOREIGN MATERIAL. DIRT,OIL,GREASE,OR OTHER CONTAMINANTS ARE NOT ALLOWED



| No. ARTICLE | NUMERO DE PIECE | Part number | DESCRIPTION | QTE |
|----------------|--|-------------------|--------------------|-----|
| 1 | cubby19_base | C19_0201_0101_001 | | 1 |
| 2 | SKC-F1.5- PennEngineering_key hole | SKC_F1.5 | Keyhole standoff | 6 |
| 3 | F-M3-1- PennEngineering | F_M3_1 | Inserted flush nut | 2 |

| FINISH: | DEBURR AND | do not scale drawing revision B | | | В | L | |
|------------------|----------------------|--|-------|--------|---|---|--|
| | BREAK SHARP EDGES | Unless otherwise specified Dimensions are in millimet General tolerances: ISO | ERS | | |] | |
| NAME | DATE | TITLE | | | | 1 | |
| JJ Chanut | 11/23/2021 | | | | | | |
| € ITRENEW | | cubby19_base | | | | A | |
| MATERIAL: | | C19_0100_001 | | | | | |
| | | scale: 1:5 | SHEET | 1 OF 2 | | | |
| 3 | | 2 | | • | 1 | _ | |

