

<b>SRI</b>	ISO 9001: 2015 Quality Management System Quality Procedure Manual	
Document No: SRI-QPM 009(1a) Date Issued : 01/12/2018 Revision date:30/01/2025	<b>DSI Tyres®</b>	Revision No :02 Page No : 1 of 5
Title : Procedure for HSP		

## **9.1 PROCEDURE FOR HANDLING, STORAGE, PRESERVATION**

### **9.1.1 SCOPE**

This manual describes the procedure for

- Acceptance, handling and storage of incoming material (raw material, chemicals oils and packing material)
- Issue of materials from stores.

### **9.1.2 RESPONSIBILITY**

Head of the Department is overall responsible, Functional responsibilities are identified under each activity given below.


### **9.1.3 INCOMMING MATERIAL**

#### **9.1.3.1 Acceptance and storage procedure**

Flow	Activity	Responsibility	Ref
<b>RECEIVING MATERIAL</b> 	1. Receipt of rubber to raw material stores with AOD/Invoice 1.i.Receipt Deforestation free rubber (EUDR) with identification	QCA	IT FORM-VI
	2. Conduct Impurity check for rubber lots from direct suppliers. if unacceptable impurity level found, return the lot	"	"
	3. Receipt of Other material according to the dispatch note/ packing list.	WHO/WHO Ex/Supp:Ex	
	4. Collect sample for testing (other material)	QM/QCA	IT-WI-S-01 IT-FORM-01
	5. Raise GRN for All material	WHO/WHO Ex/Supp:Ex	PP-NOTE-01 IFS System
	6. Sent Copy to Relevant Section <ul style="list-style-type: none"> <li>• 1<sup>st</sup> copy to supplier</li> <li>• 2<sup>nd</sup> copy to account section</li> <li>• Retain copy for reference</li> </ul>	"	

If MR signature is absent this will not be a controlled document.	Signature of Management Representative	
	Date	

Title : Procedure for HSP



If MR signature is absent this will not be a controlled document.

Signature of Management Representative

Date

<b>SRI</b>	ISO 9001: 2015 Quality Management System Quality Procedure Manual	
Document No: SRI-QPM 009(1a) Date Issued : 01/12/2018 Revision date:30/01/2025	<b>DSI Tyres®</b>	Revision No :02 Page No : 3 of 5


Title : Procedure for HSP

### **9.1.3.2 Handling and packaging**

1. Some incoming materials are manually handled
2. Some incoming materials are palletised
3. Pale crape is received in bales.
4. Rubber is received in bales or sheet
5. Chemicals are received from bag or pallets.
6. Oils re received from drums, cans & bulk tank
7. All materials are handled manually or use fork lift depending on the weight.

### **9.1.4 ISSUE OF MATERIALS**

#### **9.1.4.1 Issuing materials to the factory**



If MR signature is absent this will not be a controlled document.	Signature of Management Representative	
	Date	

**9.1.5. PROCEDURE FOR PURCHASING, STORAGE AND ISSUING OF PACKING MATERIALS  
AND SEMI FINISHED GOODS AND TUBE VALVES**


Flow	Activity	Responsibility	Ref
<b>PLANNING &amp; ORDERING</b>	1. Receive material consumption report from planning department (Forecast, Actual, Requirement)	WHO/WHO Ex/Supp:Ex	PC-MRP-02
	2. Calculate the required quantity.	„	PP-FORM-02A
	3. Raise purchase order to approved suppliers	„	PP-ORDER-01
<b>RECEIVING &amp; STORING</b>	1. Take over materials with invoice/ packing list Delivery note under supervisor of security guard.	WHO/WHO Ex/Supp:Ex	WI-025
	2. Raise GRN/RMA	„	PP/NOTE-01
	3. Enter yellow tags and inform laboratory to collect sample. (Only for Selected Items)	WHO/QCA	IT-WI-S-01
	4. If the test results are OK enter green tag and store designated area	„	IT-FORM-01
<b>ISSUING</b>	1. Receive requisition, purchase order (out side)	WHO/WHO Ex/Supp:Ex	System
	2. Enter details to computer	„	„
	3. Issue goods with issue note/AD/Delivery note	„	„
	4. Obtain endorsement from each section managers	„	„
<b>REJECTION</b>	1. If the lots are not approved insert red tag	WHO/WHO Ex/Supp:Ex	WI-025
	2. Inform to supplier	„	„
	3. Return good with AOD to supplier. for collect credit note or get replacement.	„	System
	4. If it is imported item, inform to import department.		

If MR signature is absent this will not be a controlled document.

Signature of Management Representative

Date

Title : Procedure for HSP

**9.1.6 PROCEDURE FOR HANDLING AND ISSUING OF SPARE PARTS AND SUNDRY ITEMS.**

If MR signature is absent this will not be a controlled document.

Signature of Management Representative

Date