

Worst gap 2.38 pts vs 0.55 pts (4.3× better)

points below FP2 digital ceiling

- BatchNorm recalibration
- per-column calibration

32

64

128

256

$B = M$ (tile height)

