













MCU and IC power supply

## NOTES:

- 1. Solenoid power caps Place the 3 caps close to solenoid power line
- 2. C39, C40, C41 and C42 are all tantalum capacitors
- 3. R37, R38, R39 and R40 should all be 1%

TITLE: Power	delivery	REV: 1.1
<b>EasyEDA</b>	Company: rnd-ash@github.com	Sheet: 5/5
	Date: 2022-06-16 Drawn By: Ashcon	Mohseninia