













MCU and IC power supply

## NOTES:

- 1. Solenoid power caps Place the 3 caps close to solenoid power line
- 2. C39, C40, C41 and C42 are all tantalum capacitors
- 3. R37, R38, R39 and R40 should all be 1%

	TITLE: Power delivery				REV:	1.1
	<b>⇔</b> EasyEDA	Company: rnd-ash@github.com			Sheet:	5/5
		Date:	2022-06-16	Drawn By:	Ashcon N	Mohseni