

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96020	BF South West Fire Stairwell (3A)	1	1	Carpark	Single-Leafed Side-Hung Fire Door	156937	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96021	BF Void Access adj Sprinkler Valve Room	2	2	Carpark	Single-Leafed Side-Hung Fire Door	.	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door and frame are damaged beyond repair, will require full inspection and specific quote to repair.								
96022	BF West Fire Stairwell (4A)	3	3 / 256	Carpark	Single-Leafed Side-Hung Fire Door	105708	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96023	BF North Fire Stairwell (5A)	4	4 / 258	Carpark	Single-Leafed Side-Hung Fire Door	04427	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96024	BF North East Fire Stairwell (8A)	5	5 / 259	Carpark	Single-Leafed Side-Hung Fire Door	104429	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96025	BF East Fire Stairwell (9A)	6	6 / 260	Carpark	Single-Leafed Side-Hung Fire Door	156935	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	1.9e - Door frame in poor condition - 12.4.3.1								
Notes	Door frame severely corroded. Requires repair.								

Asset Register - 06.1A Fire Resistant Doorsets Service Record						
Asset ID	Building - Location	Equipment Number	Install # / Sub	Date	Service	Pass / Fail
93522	Entire Site	-	-	24/04/2026	Yearly	Fail
Test Readings	Work Order Number: APR 24 SM		Site Attendance Record Number:: A106719		--- TABLE 12.4.3.1 SIX-MONTHLY SERVICE SCHEDULE HINGED AND PIVOTED FIRE-RESISTANT DOORSETS: 2026-04-24	
	--- 1.1 Location INSPECT to determine if the fire-resistant doorset has been modified since the previous routine service.: Pass		--- 1.2 Marking—Tags and signage (a) INSPECT door leaves and door frames are tagged in accordance with AS 1905.1.: Fail		--- 1.2 Marking—Tags and signage- (b) INSPECT to ensure relevant statutory signage has been applied and that the location of the signage is in accordance with regulatory requirements.: Pass	
	--- 1.3 Clearances in the closed position (a) CHECK that gaps between the edge of the door leaf and the door frame are in accordance with AS 1905.1 or the relevant test report.: Fail		--- 1.3 Clearances in the closed position - (b) CHECK that the gap between the bottom edge of the door leaf and the finished floor level is in accordance with AS 1905.1 or the relevant test report.: Fail		--- 1.4 Hardware general— Locksets and latches, closers and pivots, hinges and sequence selectors (a) INSPECT all hardware required for suspension, closing and latching is fitted and is a make and model that has been fire-tested for the specific fire resistant door.: Fail	

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	--- 1.4 Hardware general— Locksets and latches, closers and pivots, hinges and sequence selectors- (b) INSPECT all hardware is located correctly, securely attached and operational with the correct fittings in accordance with the requirements of AS 1905.1 or the relevant test report.: Fail	--- 1.4 Hardware general— Locksets and latches, closers and pivots, hinges and sequence selectors - (c) INSPECT the door leaf and door frame are free from non-approved fittings, fixings or attachments and free from damage caused by relocation of hardware items.: Pass	--- 1.5 Frictional forces and self-closing and self-latching function (a) VERIFY the opening and closing forces are such that the doors can be easily opened and closed in normal conditions and in fire mode, taking into account any pressurization systems within the building.: Pass
	--- 1.5 Frictional forces and self-closing and self-latching function - (b) INSPECT the doorset is self-closing and selflatching, if appropriate.: Pass	--- 1.5 Frictional forces and self-closing and self-latching function -(c) Where passage sets or knobs are incorporated, INSPECT that the minimu: Pass	--- 1.6 Door closers and pivots (a) CHECK closers are free from oil leakages.: Pass
	--- 1.6 Door closers and pivots - (b) INSPECT the door closer (body and arm) is free from obstruction by walls, fixtures and is operating freely throughout its swing.: Pass	--- 1.7 Door seals INSPECT any installed door seals are approved for use on the proprietary door type, functioning as intended and are not damaged.: Pass	--- 1.8 Door leaves (a) CHECK doors for any visible delamination, buckling, warping, bowing, twisting or significant damage.: Pass
	--- 1.8 Door leaves- (b) CHECK door edges are in good condition and free from any splitting or damage on all sides.: Pass	--- 1.9 Door frames - (a) CHECK door stop dimensions are approved for the proprietary door type and FRL.: Pass	--- 1.9 Door frames -(b) CHECK steel door frames are back-filled as required for the proprietary door type and FRL. NOTE: See AS 1905.1.: Pass
	--- 1.9 Door frames - (c) CHECK door frame is free from excessive distortion at any point along frame sections.: Pass	--- 1.9 Door frames-(d) CHECK to ensure doorframe incorporates a door striker plate.: Pass	--- 1.9 Door frames- (e) CHECK condition of frame.: Pass
	--- 1.10 Vision panels (where fitted) (a) CHECK proprietary door type is approved for use of a vision panel.: Pass	--- 1.10 Vision panels (where fitted) - (b) CHECK to ensure glass is approved for the proprietary door type, in a sound condition and free from cracks.: Fail	--- 1.10 Vision panels (where fitted) - (c) CHECK to ensure perimeter trim and framing are secure and in sound condition, and all fixing screws are in place and consistent with the fire test approvals for the propriety door type.: Fail
	--- 1.11 Fire-rated air transfer grilles or fire dampers (where fitted) CHECK proprietary door type is approved for use with the fire-resistant air transfer grille or fire damper and is installed as per manufacturer's instructions. NOTE: Where a damper is incorporated in a fire door it is considered to be a fire-rated air transfer grille.: Pass	--- 1.12 Travel limiting device Where required, VERIFY travel limiting device is installed in accordance with AS 1905.1.: N/A	--- 1.13 Other features (a) INSPECT the threshold for the door leaf is free from the addition of any combustible covering since installation or previous inspection.: N/A
	--- 1.13 Other features - (b) INSPECT kickplates are securely fixed (where fitted): N/A	--- 1.14 Meeting stiles for pairs of doors (where fitted) INSPECT to ensure that meeting stile astragals are correct for the proprietary door type, installed as per manufacturer's instructions, are in good working order and incorporate seals where required.: Fail	--- 1.15 Doors held in the open position TEST that doors held in the open position, which require activation of detection system to close, to ensure the door closes satisfactorily upon power failure or detector activation.: Pass
	--- SIX-MONTHLY 2.2 Location INSPECT against drawings and all schedules (see Clause 12.2.5) to ensure that no fire doors has been added, removed or modified.: Pass	--- 2.3 Marking—Tags and signage (a) INSPECT door leaves and door frames (where applicable) are tagged in accordance with AS 1905.1.: N/A	--- 2.3 Marking—Tags and signage - (b) INSPECT to ensure relevant statutory signage has been applied and that the location of the signage is in accordance with regulatory requirements.: N/A
	--- 2.4 Clearances and overlaps in the closed position INSPECT clearances and overlaps of door panel(s) are in accordance with AS 1905.1.: N/A	--- 2.5 Frictional forces, operation and self-closing ability CHECK forces to open and close door leaves do not exceed maximum 110 N for a door in the path of travel to an exit and 180 N from the closed position and 135 N through its full travel in other places.: Pass	--- 2.6 Restraint brackets and interlocking steel sections (flame guards) INSPECT restraint brackets and/or interlocking steel sections are as per manufacturer's specifications, fixed adequately and functional.: Pass
	--- 2.7 Hardware (a) INSPECT hardware required for suspension and operation is fitted and is as per manufacturer's specifications.: Pass	--- 2.7 Hardware - (b) INSPECT hardware is securely attached with the correct fittings in accordance with the requirements of AS 1905.1.: Pass	--- 2.8 Automatic operations (a) CHECK fusible links, where fitted, are intact and unpainted.: N/A
	--- 2.8 Automatic operations - (b) CHECK pulley cables are free from fraying, kinks, excessive stretching and corrosion.: N/A	--- 2.8 Automatic operations - (c) CHECK pulleys are free to rotate.: Pass	--- 2.8 Automatic operations -(d) REPLACE all fusible links every 25 years from the date of manufacture. NOTE: In lieu of replacing all fusible links, a representative sample may be tested as per Section 2.: N/A
	--- 2.8 Automatic operations - (e) PERFORM a full operational test (mechanically and electrically) as appropriate to ensure correct automatic closing of the door is achieved.: N/A	--- 2.8 Automatic operations - (f) CHECK operation to ensure the door fully closes from one intermediary position.: Fail	--- 2.8 Automatic operations - (g) TEST operation of illuminated sliding doors, warning signs, sounders and release delays, as appropriate.: Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	--- 2.9 Door guides, stops and restraints INSPECT floor and/or track and/or wall-mounted guides and stops and all travel-limiting devices at door open and close locations are adequate and soundly mounted.: Pass	--- 2.10 Other fittings and accessories (a) CHECK arrows indicating opening direction are fixed to each side of the door leaves.: Pass	--- 2.10 Other fittings and accessories - (b) CHECK flush pulls, handles or grips are securely fixed.: N/A
	--- 2.11 Door leaf (a) INSPECT door leaf or leaves are free from any delamination, any other damage and all perimeter edge capping is complete and sound.: N/A	--- 2.11 Door leaf - (b) CHECK door leaf or leaves is/are free from any non-approved fittings, fixings and attachments.: N/A	--- 2.12 Door frame (where applicable) CHECK door frame is adequately anchored to the opening.: Pass
	--- 2.13 Other features (a) CHECK service access panels for cavity sliders are suitable and accessible.: Pass	--- 2.13 Other features - (b) CHECK the sill under the door leaf is free from the addition of any combustible covering since installation or previous inspection.: N/A	--- 2.14 Multiple-leaf doors In addition to the above, INSPECT overlaps or jointing of individual door leaf panels at meeting stiles are in proper alignment and comply with manufacturer's specifications.: N/A
	--- 2.15 Wicket doors or personnel access doors INSPECT wicket or personnel access doors operate satisfactorily in accordance with the hinged door leaf requirements, and in accordance with the manufacturer's test approval. NOTE: These doors are usually found integrated within the sliding door leaf or leaves and are typically side-hung doors.: N/A	--- 2.16 Power-assisted sliding doors Power-assisted sliding doors are to be serviced in accordance with the manufacturer's maintenance procedures.: N/A	--- TABLE 12.4.4 SIX-MONTHLY SERVICE SCHEDULE HINGED AND PIVOTED SMOKE DOORS: 2026-04-24
	--- 4.1 Location INSPECT against drawings and all schedules (see Clause 12.2.5) that no smoke doors have been added, removed or modified.: Pass	--- 4.2 Door type and signage (a) CHECK that the smoke door complies to appropriate door design specification, is at least 35 mm thick solid core door or in accordance with the requirement of the 'building approval':. Pass	--- 4.2 Door type and signage - (b) CHECK that doors are self closing.: Pass
	--- 4.2 Door type and signage - (c) INSPECT to ensure relevant statutory signage has been applied and that the location of the signage is in accordance with regulatory requirements.: Pass	--- 4.3 Clearance in the closed position (a) CHECK perimeter—gaps between the door leaf and the door frame are as per door assembly and seal manufacturers' recommendations.: Pass	--- 4.3 Clearance in the closed position - (b) CHECK bottom—gaps between the door bottom and threshold are as per door assembly and seal manufacturers' recommendations.: Pass
	--- 4.4 Smoke seals (a) CHECK smoke seals are suitable for use on the door/assembly type.: Pass	--- 4.4 Smoke seals - (b) CHECK that any seal is in good condition and not damaged.: Pass	--- 4.4 Smoke seals - (c) CHECK perimeter and bottom—perimeter and door bottom seals are correctly fitted in accordance with manufacturer's recommendations and that the sealing elements are in continuous contact with the door/frame/floor.: Pass
	--- 4.5 Meeting stiles for pairs of doors (a) CHECK to ensure meeting stile astragals or door meeting edges incorporate smoke seals.: Fail	--- 4.5 Meeting stiles for pairs of doors - (b) CHECK seals are securely fixed.: Pass	--- 4.5 Meeting stiles for pairs of doors - (c) CHECK smoke seals do not impede the correct operation of the door.: Pass
	--- 4.6 Doors held in the open position TEST smoke doors held in the open position, which require activation of detection system to close, to ensure that they close satisfactorily upon power failure or detector activation.: Pass	--- 4.7 Hardware— General (a) CHECK all essential hardware required for suspension, closing and latching (as appropriate) is fitted.: Pass	--- 4.7 Hardware— General- (b) CHECK all hardware is attached and is securely fixed.: Pass
	--- 4.8 Frictional forces and self-closing and self-latching function VERIFY the opening and closing forces are such that the doors can be easily opened and closed in normal conditions and in fire mode, taking into account any pressurization systems within the building.: Pass	--- 4.9 Door closers and pivots (a) CHECK the door closer (body and arm) is free from obstructions by walls or fixtures and is operating freely throughout its swing.: Pass	--- 4.9 Door closers and pivots - (b) CHECK any closer free from oil leakages.: Pass
	--- 4.9 Door closers and pivots - (c) CHECK screw fixing and mounting arrangements for door closer are secured to the door leaf and door frame.: Pass	--- 4.10 Hinges (a) CHECK hinges are free from any undue wear and tear and are correctly aligned and operating smoothly and freely.: Pass	--- 4.10 Hinges - (b) CHECK hinges are securely fixed to the door leaf and frame.: Pass
	--- 4.11 Door leaves (a) INSPECT that door is free from any visible delamination, buckling, warping, bowing, twisting or significant damage.: Pass	--- 4.11 Door leaves - (b) INSPECT that door edges are in good condition and free from any splitting or damage on all sides.: Pass	--- 4.12 Door frames (a) CHECK door frames are adequately anchored to the walling and restrained against rotational movement about their longitudinal axes.: Pass
	--- 4.12 Door frames - (b) CHECK door frame is free from excessive distortion at any point along frame sections.: Pass	--- 4.13 Glazing panels (a) CHECK glass to ensure it is in sound condition, and free from cracks.: Fail	--- 4.13 Glazing panels- (b) CHECK perimeter trim and framing to ensure they are secure and in sound condition and that all fixings are

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

			in place.: Fail
	--- 4.13 Glazing panels - (c) CHECK to ensure clear glass panels are appropriately identified.: Fail	--- 4.14 Kickplates CHECK to ensure kickplates are securely fixed.: Pass	--- 4.15 Sequence selectors CHECK for doors that require correct sequencing to self close and ensure the sequencing device operates correctly.: Pass
	--- 4.16 Meeting stiles for pairs of doors CHECK to ensure any essential meeting stile astragals are installed and in good working order and incorporate smoke seals where required.: Pass	Have all previously reported defects been rectified: N/A	Queensland Buildings Only: I hereby acknowledge that the mentioned system above has been routinely serviced in accordance with Australian Standard AS1851-2012 Amendment 1 & AS2293.2 and that the information on this report is true and correct. This record does not infer compliance of all applicable building and fire legislation within the relevant jurisdiction - Queensland Buildings Only - Maintenance complies with QDC, MP6.1.: Yes
	Queensland Buildings Only: I hereby acknowledge that the mentioned system above has been routinely serviced in accordance with Australian Standard AS1851-2012 Amendment 1 & AS2293.2 and that the information on this report is true and correct. This record does not infer compliance of all applicable building and fire legislation within the relevant jurisdiction - Queensland Buildings Only - System is in proper working order.: N/A		
Failure Points	Performed 12 Monthly Testing and Maintenance - Issues Found - Refer to Assets for Defects / Failures and/or Recommendations. - 12.4.3.1, 12.4.3.2, 12.4.5		
Notes	Completed annual fire door inspection. 148 assets failed. See individual asset notes for further details.		

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012

Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96030	BF Service Tunnel Access (Park 1)	8	8 / 263	Carpark	Single-Leafed Side-Hung Fire Door	.	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door closer requires readjustment, fails to self close and/or latch properly. Door frame rusting, requires surface treatment to prevent further damage.								
96031	BF Service Tunnel Access (Park 11)	9	9 / 262	Carpark	Single-Leafed Side-Hung Fire Door	404307	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door closer requires readjustment, fails to self close and/or latch properly. Door frame rusting, requires surface treatment to prevent further damage.								
96032	BF Shopping Centre Lift	10	10 / 266	Carpark	Single-Leafed Side-Hung Fire	03473	24/04/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
	Machine Room				Door				
Test Readings	Attendance Record No. (If Applicable):								
96033	BF Carpark Pay Station	11	11 / 268	Carpark	Double-Leafed Side-Hung Fire Door	157959	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Vision panels not likely to be fire rated. Door leaf has >3mm clearance from door frame jamb and head, gap too large to be repaired with intumescent seal. Door will likely have to be replaced. No sequence selector or latch installed.								
96034	Horizon room 20	12	20	Horizon room	Soild core	807031	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96035	Horizon room 36	13	36	Horizon	Soild core	007015	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96036	Horizon room 37	14	37	Horizon	Soild core	007014	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door split at bottom. Requires new door								
96037	Horizon room 42	15	42	Horizon	Soild core	007047	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Hinges pulled out. Requires thicker gauge screws to grab door								
96038	Horizon room 10	15	10	Horizon	Soild core	007042	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96051	Horizon room 11	17	11	Horizon	Soild core	007041	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96074	Horizon room 12	18	12	Horizon	Soild core	007040	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96079	Horizon room 13	19	13	Horizon	Soild core	007039	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96080	Horizon room 14	20	14	Horizon	Soild core	007037	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Drop down seal removed. Requito be replaced								
96081	Horizon room 15	21	15	Horizon	Soild core	007036	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap Larger than 3 mm. Requires IS								
96082	Horizon room 16	22	16	Horizon	Soild core	007035	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96083	Horizon room 17	23	17	Horizon	Soild core	007034	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door split at lock. Requires to be replaced								
96084	MF Horizon Corridor to Engineering Corridor	24	24 / 273	Horizon	Single-Leafed Side-Hung Fire Door	03476	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Perimeter smoke seal damaged, requires replacement.								
96085	Horizon room 18	25	18	Horizon	Soild core	007033	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96086	Horizon 19	26	19	Horizon	Soild core	007032	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Intumescent seal required on head								
96087	Horizon room 21	27	21	Horizon	Soild core	007030	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96088	Horizon room 22	1	22	Horizon	Soild core	007029	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96089	Horizon room 23	29	23	Horizon	Solid core	007023	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door split and exposing internal elements. Requires to be replaced								
96090	Horizon room 24	30	24	Horizon	Soild core	007027	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96091	Horizon room 25	31	25	Horizon	Soild core	007026	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96092	Horizon room 26	32	26	Horizon	Soild core	007025	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96093	Horizon room 27	33	27	Horizon	Soild core	007024	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96094	Horizon Room 28	34	28	Horizon	Soild core	007023	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Loose door handle. Missing drop down seal Door requires to be replaced								
96095	Horizon room 29	35	29	Horizon	Soild	007022	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96096	Horizon room 30	36	30	Horizon	Solid core	007021	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96099	Horizon room 31	37	31	Horizon	Solid core	007020	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96100	Horizon room 32	38	31	Horizon	Soild core	007019	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96101	Horizon room 33	39	33	Horizon	Soild core	007018	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96102	Horizon room 34	40	34	Horizon	Solid core	007017	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96103	Horizon room 35	41	35	Horizon	Soild core	007014	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96104	Horizon room 38	42	38	Horizon	Soild core	007013	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96105	Horizon room 39	43	39	Horizon	Soild core	007011	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96106	Horizon room 40	44	40	Horizon	Solid core	007049	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96107	Horizon room 41	45	41	Horizon level	Solid core	007048	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96108	Horizon room 43	46	43	Horizon	Solid core	007046	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96109	Horizon room 44	47	44	Horizon	Solid core	007045	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96110	Horizon room 45	48	45	Horizon	Soild core	007044	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96111	MF Horizon Corridor adj Room 43	49	49	Horizon	Single-Leafed Pivot Smoke Door	N/A	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door binding on ceiling. Requires adjustment								
96112	MF Horizon Corridor adj Room 32	50	50	Horizon	Single-Leafed Pivot Smoke Door	N/A	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96113	MF Horizon Corridor adj Room 24	51	51	Horizon	Single-Leafed Pivot Fire Door	N/A	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96114	MF Horizon	52	52	Horizon	Single-Leafed	N/A	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
	Corridor adj Room 16				Pivot Smoke Door				
Test Readings	Attendance Record No. (If Applicable):								
96115	MF Horizon Corridor opp Room 21 to Loading Dock Fire Exit (9)	53	53	Horizon	Single-Leafed Side-Hung Fire Door	000917	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Binding on top corner. Door not self latching. Requires adjustment of hinges or possibly plane door down								
96116	MF Horizon Corridor opp Room 22 to Loading Dock Fire Exit (9)	54	54	Horizon	Single-Leafed Side-Hung Fire Door	Not installed	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	No metal tag on door frame. No metal tag on door leaf. Door requires to be replaced								
96117	MF Horizon Corridor opp Room 28 to North East Fire Exit (8)	55	55 / 275	Horizon	Double-Leafed Side-Hung Fire Door	002340/002341	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96118	MF Horizon Corridor to Events Amenities	56	56	Horizon	Double-Leafed Side-Hung Fire Door	002343/002344	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door sequence selector faulty. Requires replacement								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96119	MF Events Amenities Access	57	57	Events Amenities	Single-Leafed Side-Hung Fire Door	035507	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96126	MF North West Fire Stairwell (6) to Balcony	58	58	Events Amenities	Single-Leafed Side-Hung Fire Door	001056	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill instal.								
96026	BF South Fire Exit (10) adj Park 48	7	7 /261	Carpark	Single-Leafed Side-Hung Fire Door	01641	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	As previously reported Not latching shut non compliant frame required to be replaced and door as has holes drilled it it that required fire mastic filled and sanded								
96120	MF Loading Dock to Shopping Centre	245	245	Loading Dock	Double-Leafed Side-Hung Fire Door	7451/7452	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Requires fdbu20 door seal and new sequence selector								
96130	L1 room 1086	Entry	1086	L1	Fire door	104350	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap above. 3mm. Requires Intumescent seal								
96131	L1 room 1083	62	1083	L1	Fire door	104344	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96132	L1 room 1074	63	1074	L1	Fire door	104334	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Fdbu20 door seal installed Intumescent seal required on lock side								
96133	L1 room 1073	64	1073	L1	Fire door	104329	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96134	L1 room 1068	65	1068	L1	Fire door	10704	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96135	L1 room 1038	66	1038	L1	Fire	104147	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96136	L1 room 1033	67 front door	1033	L1	Fire	003169	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96138	L1 room 1027 service riser	68	1027	L1	Fire	03232	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others								
96139	L1 room 1024 entry	69	1024	L1	Fire	104028	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96140	L1 room 1023	70	1023	L1	Fire	104087	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96141	level 2 2098 interconnecting door	71	2098	L2	Fire	104294/104295	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96143	L1 room 1021 interconnecting door	72	1021	L1	Fire	104070	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96144	L1 room 1019	74	1019	L1	Fire	04073	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96145	L1 room 1018	75	1018	L1	Fire	104072	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96150	L1 room 1001 service riser	76	1001	L1	Fire	104006	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Requires fdbu20 door seal								
96149	L1 room 1001 service riser	75	1001	L1	Fire door	104005	30/03/2026	Yearly	Fail

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Requires fdbu20 door seal								
96152	L1 room 1002	78	1002	L1	Fire	5283	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96153	L1 room 1002 interconnecting door	79	1002	L1	Fire	104017	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96154	L1 room 1003 entry	80	1003	L1	Fire	104019	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96155	L1 room 1003 interconnecting door	81	1003	L1	Fire	104016	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96156	L1 room 1004	82	1004	L1	Fire	104018	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96158	L1 room 1005 entry	83	1005	L1	Fire	104008	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96161	L1 room 1006 entry	85	1006	L1	Fire	104050	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96159	L1 room 1005 interconnecting door	84	1005	L1	Fire	104021	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96165	L1 room 1006 interconnecting door	86	1006	L1	Fire	104058	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96166	L1 room 1007- entry	87	1007	L1	Fire	104059	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96157	L1 room 1004	83	1004	L1	Fire	104020	30/03/2026	Yearly	Pass

Lewie Fire Protection

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Asset Record - Job No. 98870

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026**Contact:** Michelle Davis**Phone:**

Test Readings	Attendance Record No. (If Applicable):								
96167	L1 room 1007	89	1007	L1	Fire	104060	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96169	L1 room 1008-entry	91	1008	L1	Fire	104053	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96170	L1 room 1008 interconnecting door	92	1008	L1	Fire	104054	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96171	L1 room 1009	93	1009	L1	Fire	104056	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96172	L1 room 1010 entry	94	1010	L1	Fire	107009	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96148	L1 room 1001 - entry	75	1001	L1	Fire	No tag	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	No tag on door frame or door Door requires to be replaced								
96137	L1 room 1027 entry	68	1027	L1	Fire	03234	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others								
96122	Leading into events centre	61	.	.	Fire doors double door	035505/035506	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Requires new sequence selector								
96173	L1 room 1010 interconnecting door	.	1010	L1	Fire	104055	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96174	L1 room 1011	.	1011	.	Fire	104057	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96175	L1 room 1012	.	1012	.	Fire	104075	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96176	L1 room 1013	.	1013	.	Fire	104076	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96177	L1 room 1014	.	1014	.	Fire	104065	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96178	L1 room 1015 entry	.	1015	.	Fire	107908	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96181	L1 room 1016	.	1016	.	Fire	105071	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96182	L1 room 1017	.	1017	.	Fire	104068	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96183	L1 room 1017 interconnecting door	.	1017	.	Fire	104066	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96184	L1 room 1020	.	1020	.	Fire	04086	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96185	L1 room 1021	.	1021	.	Fire	104071	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96186	L1 room 1022	,	1022	.	Fire	104025	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96187	L1 room 1023 interconnecting door	.	1023	.	1 hour	104023	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96189	L1 room 1025 entry	.	1025	.	Fire	104024	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96190	L1 room 1025 interconnect door	.	1025	.	Fire	104010	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96191	L1 room 1026	.	1026	.	Fire	104026	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96192	L1 room 1028 entry	.	1028	.	Fire	104027	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96193	L1 room 1028 interconnecting door	.	1028	.	Fire	104022	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96200	L1 room 1030 entry	.	1030	.	Fire	104115	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96201	L1 room 1030 interconnecting door	.	1030	.	Fire	104127	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96203	L1 room 1031 entry	.	1031	.	Fire	104129	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96204	L1 room 1031 interconnecting door	.	1031	.	Fire	104128	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96205	L1 room 1032	.	1032	.	Fire	.	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96206	L3 3003 interconnecting door	.	1033	.	Fire	104400/104401	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96208	L1 room 1033 interconnecting door	.	1033	.	Fire	104135	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96210	L1 room 1034	Front door	1034	.	1034	104138	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96226	L1 room 1039	.	1039	.	Fire	104145	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96227	L1 room 1039 interconnecting door	.	1039	.	Fire	104146	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96228	L1 room 1040	Front door	1040	.	Fire	104148	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96232	L1 room 1041	Front door	1041	.	Fire	104152	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Requires Fdbu20 door seal								
96233	L1 room 1042	Front door	1042	.	Fire	104154	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96234	L1 room 1042 interconnecting door	.	1042	.	Fire	104153/ 101152	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96236	L1 room 1043	.	1043	.	Fire	104159	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96238	L1 room 1044	Entry	1044	.	Fire	03233	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others								
96241	L1 room 1045	.	1045	.	Fire	104160	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96242	L1 room 1046	Entry	1046	.	Fire	107048	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96243	L1 room 1046	.	1046	.	Fire	104158	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96245	L1 room 1047	.	1047	.	Fire	104163	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96249	L1 room 1048	Entry	1048	.	Fire	.	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96250	L1 room 1049	.	1049	.	Fire	03235	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door has been replaced by others								
96252	L1 room 1050	Entry	1050	.	Fire	104167	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96254	L1 room 1051	Entry	1051	.	Fire	104170	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96255	L1 room 1052	.	1052	.	Fire	104171	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96257	L1 room 1053	.	1053	.	Fire	104169	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Requires a fdbu20 door seal								
96261	L1 room 1055	.	1055	.	Fire	104176	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96262	L1 room 1056	.	1056	.	Fire	104179	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96263	L1 room 1057	.	1057	.	Fire	104178	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96264	L1 room 1058	.	1058	.	Fire	104181	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96265	L1 room 1060	Entry	1060	.	Fire	104182	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96266	L1 room 1060	Bed side	1060	.	Fire	107046	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96267	L1 room 1060	Left	1060	.	Fire	107045	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96268	L1 room 1061	.	1061	.	Fire	107044	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96269	L1 room 1062	.	1062	.	Fire	107043	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap exceeds 50mm at base								
	Door to be replaced. Gap to large to use intumescent seal								
96270	L1 room 1063	.	1063	.	Fire	107042	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96271	L1 room 1064	.	1064	.	Fire	107041	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96272	L1 room 1065	.	1065	.	Fire	104189	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96273	L1 room 1066	.	1066	.	Fire	104185	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Fdbu20 door seal installed								
	Requires Intumescent seal on lock side								
96274	L1 room 1067	.	1067	.	Fire	104186	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Fdbu20 door seal installed								
	Intumescent seal for head required								
96276	L1 room 1069	Entry	1069	.	Fire	104330	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Repaired by others								
96278	L1 room 1070	.	1070	.	Fire	104332	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gaps around all edges exceed maximum allowable. Requires Intumescent seal								
96286	L1 room 1072	.	1072	.	Fire	8537	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96289	L1 room 1075	Entry	1075	.	Fire	104335	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96290	L1 room 1076	.	1076	.	Fire	No tag	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Fdbu20 door seal installed								
	Striker plate screw snapped off. Requires removing and new screw. Striker plate restricting door from self latching								
96291	L1 room 1077	.	1077	.	Fire	104336	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap on hinge side is over maximum allowable distance. - Hinge is physically damaged Door of self latching due to hinge								
96292	L1 room 1078	.	1078	.	Fire	107039	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96293	L1 room 1079	.	1079	.	Fire	107038	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	No striker plate installed								
96294	L1 room 1080	.	1080	.	Fire	104341	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal and seal installed								
96295	L1 room 1081	.	1082	.	Fire	104342	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96296	L1 room 1082	.	1082	.	Fire	104344	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96298	L1 room 1084	.	1084	.	Fire	104346	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96299	L1 room 1085	.	1085	.	Fire	104348	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
Notes	fdbu20 door seal INSTALLED								
96300	L1 room 1086 interconnecting	.	1086	.	Fire	104351/104352	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96301	L1 room 1087	.	1087	.	Fire	104353	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96302	L1 room 1088	.	1088	.	Fire	104355	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96303	L1 room 1089	.	1089	.	Fire	104358	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96304	L1 room 1090	Entry	1090	.	Fire	101037	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	fdbu20 installed								
96305	L1 room 1090 interconnecting door	.	1090	.	Fire	104362	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96306	L1 room 1091	Entry	1091	.	Fire	107036	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	FDBU20 installed								
96307	L1 room 1091 interconnecting door	.	1091	.	Fire	104363	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96308	L1 room 1092	.	1092	.	Fire	104368	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Hinges damaged, bolts coming loose Requires new 100 mm weld in hinges								
96309	L1 room 1093	.	1093	,	Fire	104371	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	FDBU20 installed								
96310	L1 room1094	.	1094	.	Fire	104367	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96311	L1 room 1095	.	1095	.	Fire	107035	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	fdbu20 door seal 20 installed								
96312	1F Corridor Plumbing Riser opp Health Club	11	11	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	104043	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96313	1F Corridor Plumbing Riser adj Room 1007	12	12	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	104052	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96314	1F Corridor Plumbing Riser adj Room 1009	13	13	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	03453	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96315	L2 room 2054	.	2054	L2	Fire rated door	104234	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Requires intumescent seal on lock side. Gap greater than 3 mm								
96316	L2 room 2055	Entry	2055	L2	Fire rated door	104236	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96317	L2 room 2056	Entry	2056	L2	Fire rated door	104235	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96318	L2 room 2057	Entry	2057	L2	Fire rated door	404303	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door hinges completely fallen off. Door unable to use at all. Requires new hinges and fdbu20 door seal to be installed								
96319	L2 room 2058	Entry	2058	L2	Fire rated door	.	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	No door tag. Requires to be replaced								
96320	L2 room 2059	Entry	2059	L2	Fire rated door	104242	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96321	L2 room 2060	Entry	2060	L2	Fire rated door	104243	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96322	L2 room 2061	Entry	2061	L2	Fire rated door	104245	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96323	L2 room 2063	Entry	2063	L2	Fire rated door	104246	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96324	L2 room 2064	Entry	2064	L2	Fire rated door	104250	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96325	L2 room 2065	Entry	2064	L2	Fire rated door	104251	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96326	L2 room 2066	.	2066	L2	Fire rated door	107032	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap at bottom of door is over 10mm requires fdbu20 door seal								
96327	L2 room 2067	Entry	2067	L2	Fire rated door	03241	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others								
96328	L2 room 2068	Entry	2068	L2	Fire rated door	03239	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others								
96329	L2 room 2069	Entry	2069	L2	Fire rated door	104254	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96330	L2 room 2070	Entry	2070	L2	Fire rated door	03242	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others								
96331	L2 room 2071	Entry	2071	L2	Fire rated door	104259	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96332	L2 room 2072	Entry	2072	L2	Fire rated door	104260	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96333	L2 room 2073	Entry	2073	L2	Fire rated door	104258	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96334	L2 room 2074	Entry	2074	L2	Fire rated door	104261	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96335	L2 room 2075	Entry	2075	L2	Fire rated door	104390	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door split at lock and base. Requires new door								
96336	L2 room 2076	.	2076	L2	Fire rated door	104264	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96337	L2 room 2077	Entry	2077	L2	Fire rated door	104263	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96338	L2 room 2078	Entry	2078	L2	Fire rated door	104265	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal Intsalled								
96339	L2 room 2079	Entry	2079	L2	Fire rated door	104268	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96340	L2 room 2080	Entry	2080	L2	Fire rated door	104270	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96341	L2 room 2081	.	2081	L2	Fire rated door	204269	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96342	L2 room 2082	Entry	2082	L2	Fire rated door	104271	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96343	L2 room 2083	Entry	2083	L2	Fire rated door	03236	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door replaced by others								
	Requires intumescent seal on head, no stricter plate								
96344	L2 room 2084	.	2084	L2	Fire rated door	107034	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap at floor larger than 10mm. Requires fdbu20 door seal 20 door seal								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96346	L2 room 2085	Entry	2085	L2	Fire rated door	104277	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96348	L2 room 2086	Entry	2086	L2	Fire rated door	104278	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96351	L2 room 2087	.	2087	L2	Fire rated door	104391	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap larger than 10mm at bottom. Requires fdbu20 door seal								
96354	L2 room 2088	Entry	2088	L2	Fire rated door	104279	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96356	L2 room 2089	Entry	2089	L2	Fire rated door	104282	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96362	L2 room 2090	Entry	2090	L2	Fire rated door	104392	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96366	L2 room 2091	Entry	2091	L2	Fire rated door	104393	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96368	L2 room 2092	.	2092	L2	Fire rated door	104283	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Gap larger than 10mm. Requires fdbu20 door seal								
96372	L2 room 2093	Entry	2093	L2	Fire rated door	104288	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96373	L2 room 2094	Entry	2094	L2	Fire rated door	104289	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96374	L2 room 2095	Entry	2095	L2	Fire rated door	104285	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96375	L2 room 2095	.	2095	L2	Fire rated door	104287/104286	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96376	L2 room 2096	Entry	2096	L2	Fire rated door	104290	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96377	L2 room 2097	Entry	2097	L2	Fire rated door	107027	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96378	L2 room 2098	.	2098	L2	Fire rated door	104293	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap larger than 10mm at bottom. Requires fdbu20 door seal								
96379	L2 room 2099	Entry	2099	L2	Fire rated door	104301	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96380	L2 room 2099 interconnecting	.	2099	L2	Fire rated door	104300	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96381	L2 room 2100	Entry	2100	L2	Fire rated door	104298	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96382	L2 room 2100 interconnecting door	.	2100	L2	Fire rated door	104299	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96383	L2 room 2101	Entry	2101	L2	Fire rated door	104307	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96384	L2 room 2101 interconnecting door	.	2101	L2	Fire rated door	104306	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96385	L2 room 2102	Entry	2102	L2	Fire rated door	104304	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96386	L2 room 2102 interconnecting door	.	2102	L2	Fire rated door	104305	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96387	L2 room 2103	Entry	2103	L2	Fire rated door	104309	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96388	L2 room 2104	Entry	2104	L2	Fire rated door	104310	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96389	L2 room 2105	Entry	2105	L2	Fire rated door	.104315	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96390	L2 room 2106	Entry	2106	L2	Fire rated door	104316	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96391	L2 room 2107	Entry	2107	L2	Fire rated door	104321	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96392	L2 room 2108	Entry	2108	L2	Fire rated door	104317	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96393	L2 room 2109	Entry	2109	L2	Fire rated door	104318	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96394	L2 room 2109	.	2109	L2	Fire rated door	104319	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Gap at base of door exceeds maximum allowable								
	Requires fdbu20 door seal								
96395	L2 room 2109	.	2109	L2	Fire rated door	104320	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap at base of door exceeds maximum allowable								
	Requires fdbu20 door seal								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96396	L2 server rises	1387	1387	L2	Fire rated door	104034	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed								
96397	L2 server rises	1388	1388	L2	Fire rated door	104092	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96398	L2 server rises	1389	1389	L2	Fire rated door	104009	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96399	L2 server rises	1390	1390	L2	Fire rated door	104088	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Top of door leaf has >3mm clearance from door frame head, requires intumescent seal installed.								
96400	L2 server rises	1391	1391	L2	Fire rated door	104080	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96401	L2 server rises	1392	1392	L2	Fire rated door	04029	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96402	L2 server rises	1393	1393	L2	Fire rated door	104031	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96403	L2 server rises	.	1394	L2	Fire rated door	104041	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96404	L2 server rises	1395	1395	L2	Fire rated door	104103	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	- Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed								
96405	L2 server rises	1396	1396	L2	Fire rated door	104117	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96406	L2 server rises	.	1397	L2	Fire rated door	104104	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96407	L2 server rises	1398	1398	L2	Fire rated door	104111	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96408	L2 server rises	1399	1399	L2	Fire rated door	8532	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed								
96409	L2 server rises	1400	1400	L2	Fire rated door	104126	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed								
96410	L2 server rises	1401	1401	L2	Fire rated door	104114	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96411	L2 cleaners room adjacent 2033	1402	1402	L2	Fire rated door	8533	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Done by others								
96412	L2 server rises	1403	1403	L2	Fire rated door	104194	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96413	L2 server rises	1404	1404	L2	Fire rated door	104195	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96414	L2 server rises	.	1405	L2	Fire rated door	104203	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96415	L2 server rises	1406	1406	L2	Fire rated door	104202	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96416	L2 server rises	1407	1407	L2	Fire rated door	104211	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96417	L2 server rises	1408	1408	L2	Fire rated door	104210	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96418	L2 server rises	1409	1409	L2	Fire rated door	104216	31/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96419	L2 server rises	1410	1410	L2	Fire rated door	104217	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96420	L2 server rises	1411	1411	L2	Fire rated door	104224	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96421	L2 server rises	1412	1412	.	Fire	104225	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96428	1F Corridor Plumbing Riser adj 1004	10	10	Hotel Rooms 1001-1095	Single-Leafed Side- Hung Fire Door	104007	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96429	L1 service doors in corridor	14	.	L1	Service doors	104100	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96430	L1 service doors in corridor	16	1396	L1	Service doors	104067	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96431	L1 service doors in corridor	15	.	L1	Service doors	104062	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96432	L1 service doors in corridor	18	.	L1	Service doors	104064	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96433	L1 service doors in corridor	17	.	L1	Service doors	104063	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96434	L1 service doors in corridor	20	.	L1	Service doors	104083	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96438	L1 service doors in corridor	1402	.	L1	Service doors	104156	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Unable to open door as head is jammed in door frame. Requires prying open and adjustment.								
96440	L1 service doors in corridor	33	.	L1	Service doors	104161	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96442	L1 service doors in corridor	34	.	L1	Service doors	104162	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96446	L1 service doors in corridor	35	.	L1	Service doors	104172	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96448	L1 service doors in corridor	36	.	L1	Service doors	104168	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96451	L1 service doors in corridor	29	.	L1	Service doors	104144	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96452	L1 service doors in corridor	30	.	L1	Service doors	104149	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96453	L1 service doors in corridor	31	.	L1	Service doors	104155	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96454	L1 service doors in corridor	37	.	L1	Service doors	104174	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96455	L1 service doors in corridor cleaners	38	.	L1	Service doors	104437	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Excessive damage on door leaf. Requires replacement door								
96456	L1 service doors in corridor	39	.	L1	Service doors	104177	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96457	L1 service doors in corridor	40	.	L1	Service doors	104180	31/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96458	L1 service doors in corridor	44	.	L1	Service doors	104441	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96459	L1 service doors in corridor	41	.	L1	Double leaf	03455/03456	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Remove barrel bolt. Install chain bolt No selector installed								
96460	L1 service doors in corridor	46	.	L1	Service doors	104184	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Top of door leaf has >3mm clearance from door frame head, requires intumescent seal installed								
96461	L1 service doors in corridor	47	.	L1	Service doors	104187	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96463	L1 service doors in corridor	48	.	L1	Service doors	104188	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96464	L1 service doors in corridor	49	.	L1	Service doors	104444	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96465	L1 service doors in corridor	50	.	L1	Service doors	104443	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96466	L1 service doors in corridor	51	.	L1	Service doors	104446	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96467	L1 service doors in corridor	53	.	L1	Service doors	104339	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96468	L1 service doors in corridor	52	.	L1	Service doors	104445	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96469	L1 service doors in corridor	54	.	L1	Service doors	104338	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96470	L1 service doors in corridor	55	.	L1	Service doors	104343	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96471	L1 service doors in corridor	56	.	L1	Service doors	104347	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96472	L1 service doors in corridor	57	.	L1	Service doors	104349	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96473	L1 service doors in corridor	58	.	L1	Service doors	104354	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96474	L1 service doors in corridor	61	.	L1 plumbing riser beside room 1091	Single leaf	104364	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96475	L1 service doors in corridor	60	.	L1	Service doors	104361	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96476	L1 service doors in corridor	62	.	L1	Service doors	104365	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96449	L1 service doors in corridor	28	.	L1	Service doors	104141	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96447	L1 service doors in corridor	26	.	L1	Service doors	104133	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96445	L1 service doors in corridor	27	.	L1	Service doors	104140	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96443	L1 service doors in corridor	25	.	L1	Service doors	104132	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96437	L1 service doors in corridor	21	.	L1	Service doors	104084	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96441	L1 service doors in corridor	23	.	L1	Service doors	104037	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96439	L1 service doors in corridor	22	.	L1	Service doors	104085	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96435	L1 service doors in corridor	19	.	L1	Service doors	104097	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96371	L2 server rises	1462	1462	L2	Fire rated door	104232	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96369	L2 server rises	1463	1463	L2	Fire rated door	104233	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96363	L2 server rises	1466	1466	L2	Fire rated door	04301	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Door binding. Requires to be planed down								
96360	L2 server rises	1468	1468	L2	Fire rated door	104241	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96357	L2 server rises	1469	1469	L2	Fire rated door	104224	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96350	L2 server rises	1474	1474	L2 Adj room 2066	Fire rated door	104249	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96345	L2 server rises	1475	1475	L2	Fire rated door	104252	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96259	L1 room 1054	.	1054	.	Fire	104175	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96247	L1 room 1048 interconnecting door	.	1048	.	Fire	104166	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96212	L1 room 1035	Front door	1035	.	Fire	104134	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96221	L1 room 1037 entry	Front door	1037	.	Fire	104142	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96214	L1 room 1035 interconnecting	Side door	1035	.	Fire	104136	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96218	L1 room 1037 interconnecting	Side door	1037	.	Fire	104143	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96216	L1 room 1036	Front door	1036	.	Fire	104139	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96194	L1 room 1029 interconnecting door	.	1029	.	Fire	104094	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96195	L1 room 1029 entry	.	1029	.	Fire	03243	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others								
96179	L1 room 1015 interconnecting door	.	1015	.	Fire	104069	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96505	L2 server rises	1555	1555	L2	Fire door	104257	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96506	L2 server rises	1556	1556	L2	Fire door	104256	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96507	L2 server rises	1557	1557	L2	Fire door	104262	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96508	L2 server rises	1558	1558	L2	Fire door	104451	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed								
96509	L2 room 2001	Entry	2001	L2	Fire door	.	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	No door or frame tag. Requires to be replaced								
96512	L2 server rises	1560	1560	L2	Fire door	104266	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96511	L2 room 2002	Entry	2002	L2	Fire door	104077	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96517	L2 server rises	1562	1562	L2	Fire door	104267	31/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96520	L2 server rises	1563	1563	L2	Fire door	104272	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96523	L2 server rises	.	1564	L2	Fire door	104273	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed								
96526	L2 server risee	1565	1565	L2	Fire door	104275	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96529	L2 server rises	1566	1566	L2	Fire door	104276	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96531	L2 server rises	1567	1567	L2	Fire door	104280	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96545	L2 server rises	1573	1573	L2	Fire door	104281	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96551	L2 server rises	1575	1575	L2	Fire door	104284	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96552	L2 room 2011	Entry	2011	L2	Fire door	104048	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96555	L2 room 2012	Entry	2013	L2	Fire door	104040	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96557	L2 room 2015	.	2015	L2	Fire door	104042	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96558	L2 room 2016	.	2016	L2	Fire door	104029	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96559	L2 room 2017	Entry	2017	L2	Fire door	104030	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96560	L2 room 2018	.	2018	L2	Fire door	104112	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96561	L2 room 2019	Entry	2019	L2	Fire door	03231	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
Notes	Replaced by others								
96562	L2 room 2020	.	2020	L2	Fire door	104113	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96563	L2 room 2021	Entry	2021	L2	Fire door	104106	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96564	L2 room 2022	Entry	2022	L2	Fire door	.	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96565	L2 room 2023	.	2023	L2	Fire door	104118	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96566	L2 room 2024	Entry	2024	L2	Fire door	104105	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96567	L2 room 2025	Entry	2025	L2	Fire door	104109	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96568	L2 room 2026	Entry	2026	L2	Fire door	104122	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96569	L2 room 2026	.	2026	L2	Fire door	104124	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Base on hinge side is 15mm. Requires adjusting Requires FDBU20								
96570	L2 room 2027	Entry	2027	L2	Fire door	104107	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96571	L2 room 2028	Entry	2028	L2	Fire door	104125	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96572	L2 room 2028	.	2028	L2	Fire door	104123	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96573	L2 room 2029	Entry	2029	L2	Fire door	104108	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96574	L2 room 2029 interconnecting door	.	2029	L2	Fire door	104120	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96575	L2 room next to 2029	.	.	L2	Fire door	104110	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96577	L2 room 2030	.	.	L2	Fire door	104116	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96578	L2 room 2032	Entry	2032	L2	Fire door	104119	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96579	L2 room 2032	.	2032	L2	Fire door	104121	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96580	L2 room 2033	Entry	2033	L2	Fire door	104190	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96581	L2 room 2033 interconnecting door	.	2033	L2	Fire door	104191	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96582	L2 room 2034	Entry	2034	L2	Fire door	104193	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96583	L2 room 2034 interconnecting door	.	2034	L2	Fire door	104192	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96584	L2 room 2035	.	2035	L2	Fire door	107030	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96589	L2 room 2038	Entry	2038	L2	Fire door	104198	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96590	L2 room 2039	Entry	2039	L2	Fire door	104202	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96591	L2 room 2040	Entry	2040	L2	Fire door	104207	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96592	L2 room 2040	.	2040	L2	Fire door	104205	30/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96593	L2 room 2041	Entry	2041	L2	Fire door	107031	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Fdbu20 door seal installed								
96594	L2 room 2042	Entry	2042	L2	Fire door	104204	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96595	L2 room 2042 interconnecting door	.	2042	L2	Fire door	104206	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96596	L2 room 2043	Entry	2043	L2	Fire door	104209	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Non fire rated weather seal stopping door from self latching. Remove								
96597	L2 room 2044	Entry	2044	L2	Fire door	104215	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96598	L2 room 2044 interconnecting door	.	2044	L2	Fire door	104214	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96599	L2 room 2045 entry	.	2045	L2	Fire door	104212	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96600	L2 room 2045 interconnecting door	.	2045	L2	Fire door	104213	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96601	L2 room 2046	Entry	2046	L2	Fire door	104223	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96602	L2 room 2047	Entry	2047	L2	Fire door	104221	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96603	L2 room 2047 interconnecting door	.	2047	L2	Fire door	104220	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96604	L2 room 2048	Entry	2048	L2	Fire door	104222	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96605	L2 room 2049	Entry	2049	L2	Fire door	104218	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96606	L2 room 2049 interconnecting door	.	2049	L2	Fire door	104219	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96607	L2 room 2050	.	2050	L2	Fire door	104226	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96608	L2 room 2051	Entry	2051	L2	Fire door	104227	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96609	L2 room 2051 interconnecting door	.	2051	L2	Fire door	104229	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96610	L2 room 2052	Entry	2052	L2	Fire door	104231	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96611	L2 room 2053	Entry	2053	L2	Fire door	02194	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others								
96612	L2 room 2053 interconnecting door	.	2053	L2	Fire door	104228	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96613	L2 server rises	.	1630	L2	Fire door	5294	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96588	L2 room 2038 entry	.	2038	L2	Fire door	104199	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96587	Level 2 2037	.	2035	L2	Fire door	104200	30/03/2026	Yearly	Fail

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door delaminating, requires to be replaced								
96586	L2 room 2036 interconnecting door	.	2036	L2	Fire door	104197	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96585	L2 room 2036 entry	.	2036	L2	Fire door	104196	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96556	L2 room 2014	.	2014	L2	Fire door	104045	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96554	L2 room 2013	.	2013	L2	Fire door	104013	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96553	L2 room 2013	.	2013	L2	Fire door	104046	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96550	L2 server rises	1638	1638	L2	Fire door	104291	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96549	L2 room 2011	.	2011	L2	Fire door	104098	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96547	L2 server rises	1640	1640	L2	Fire door	104292	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96546	L2 room 2010	.	2010	L2	Fire door	107028	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96543	L2 room 2009 inter door	.	2009	L2	Fire door	104090	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96541	L2 server rises	.	1644	L2	Fire door	5293	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96540	L2 room 2009 entry	.	2009	L2	Fire door	104047	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96538	L2 room 2008	Entry	2008	L2	Fire door	104032	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96536	L2 room 2007 interconnecting door	.	2007	L2	Fire door	104035	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96534	L2 room 2007 entry	.	2007	L2	Fire door	104091	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96532	L2 room 2006	Entry	2006	L2	Fire door	104011	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96530	L2 room 2005 interconnecting door	Entry	2005	L2	Fire door	104099	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96527	L2 room 2005 entry	.	2005	L2	Fire door	104082	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96524	L2 room 2004 interconnecting door	.	2004	L2	Fire door	104096	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96671	L2 server rises	1656	1656	L2	Fire door	5293	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96673	L2 server rises	1657	1657	L2	Fire door	104303	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96676	L2 server rises	.	1658	L2	Fire door	5292	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96684	L2 server risesm	.	1660	L2	Fire door	104308	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96685	L2 server rises	1661	1661	L2	Fire door	104312	31/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96686	L2 server rises	1662	1662	L2	Fire door	104314	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96687	L3 room 3006	.	3006	L2	Fire door	02193	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others								
96688	L3 room 3007	.	3007	L3	Fire door	02197	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others.								
96689	L3 server rises	1665	1665	L3	Fire door	104377	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96690	L3 room 3008	.	3008	L3	Fire door	14382	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door stop to be relocated s to far back. Closer hitting wall								
96692	L3 room 3009	.	3009	L3	Fire door	14381	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Closer replaced by others. Door binding at top. Requires to be plained								
96693	L3 room 3010 entry	.	3010	L3	Fire door	104378	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96694	L3 room 3010	.	3010	L3	Fire door	104380	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96696	L3 room 3010	.	3010	L3	Fire door	104379	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96698	L4 room 4006	.	4006	L4	Fire door	5281	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Missing hinge screws								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

	Gap at bottom to large. Requires bottom seal upgrade								
96699	L4 server rises	1672	1672	L4	Fire door	104384	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96700	L4 room 4007	.	4007	L4	Fire door	104387 & 104389	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96701	L4 room 4008 entry	.	4008	L4	Fire door	8540	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96703	L4 room 4008	.	4008	L4	Fire door	104385	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96704	L4 room 4008	.	4008	L4	Fire door	104386	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96705	5F South Fire Stairwell (10)	1677	1677	North Tower Plant Room	Single-Leafed Side-Hung Fire Door	104462	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96706	MF Horizon Lift Lobby to Housekeeping Corridor	1678	1678	Horizon	Single-Leafed Side-Hung Fire Door	007043	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96708	MF Laundry Room to Standby Generator	1679	1679	Loading Dock	Single-Leafed Side-Hung Fire Door	105707	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96709	MF Loading Dock Fire Exit (9) Access	1680	1680	Loading Dock	Single-Leafed Side-Hung Fire Door	03470	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96710	MF Loading Dock Fire Exit (9) to Office	1681	1681	Loading Dock	Single-Leafed Side-Hung Fire Door	03465	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	As previously reported								
96711	MF Main Plant Room to Loading	1682	1682	Loading Dock	Double-Leafed Side-Hung Fire	B03472/404312	31/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
	Dock				Door				
Test Readings	Attendance Record No. (If Applicable):								
96707	MF Loading Dock to Offices Corridor	1683	1683	Loading Dock	Double-Leafed Side-Hung Fire Door	001378/001377	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Requires new sequence selector								
96702	MF Toilet Corridor near Lift	1684	1684	Mezzanine Retail	Single-Leafed Side-Hung Fire Door	001635	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96697	4F South Fire Stairwell (10)	1685	1685	Hotel Rooms 4006-4008	Single-Leafed Side-Hung Fire Door	104383	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96695	3F South Fire Stairwell (10)	1686	1686	Hotel Rooms 3006-3010	Single-Leafed Side-Hung Fire Door	104374	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96691	2F South Fire Stairwell (10)	1687	1687	Hotel Rooms 2001-2109	Single-Leafed Side-Hung Fire Door	104313	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96682	1F South Fire Stairwell (10)	1689	1689	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	104372	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96680	1F South Fire Stairwell (10) to Comms / Gen Room	1691	1691	Hotel Services	Single-Leafed Side-Hung Fire Door	-	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96678	MF South Fire Stairwell (10)	1692	1692	Horizon	Single-Leafed Side-Hung Fire Door	104419	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96674	GF South Fire Stairwell (10)	1695	1695	Shopping Centre	Single-Leafed Side-Hung Fire Door	007555	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Requires intumescent seal on lock side								
96521	L2 room 2004 entry	.	2004	L2	Fire door	104095	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96518	L2 room 2003	Entry	2003	L2	Fire door	104039	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96516	L2 room 2003 interconnecting door	.	2003	L2	Fire door	104078	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96513	L2 room 2002 interconnecting door	.	2002	L2	Fire door	104079	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96510	GF South Fire Exit (10) to Meter Room	1704	1704	Shopping Centre	Single-Leafed Side-Hung Fire Door	301099	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96778	GF South Fire Exit (10) to Shopping Centre	1705	1705	Shopping Centre	Double-Leafed Side-Hung Fire Door	03478/03479	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door repaired by others								
96779	GF Shopping Centre to East Entry Foyer	1706	1706	Shopping Centre	Sliding Fire Door	Unable to see	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	As previously reported. Unable to test as manual release facility is inaccessible/not installed.								
96780	GF Shopping Centre to Hotel Lobby	1707	1707	Shopping Centre	Sliding Door	.	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	As previously reported Unable to test as manual release facility is inaccessible/not installed.								
96782	Shopping centre to	.	1708	.	Sliding door	.	24/04/2026	Yearly	Fail

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
	lobby								
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	As previously reported. Unable to test as manual release facility is inaccessible/not installed.								
96801	L4 room 4005	,	4005	.	Fire door	104410	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Gap at bottom of door larger than 10mm Requires fdbu20 door seal								
96802	L4 service tower	,	1710	.	Fire door	104408	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96803	L4 room 4001 entry	,	4001	.	Fire door	104404	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96804	L4 room 4001 service riser	,	4001	.	Fire door	104405	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Combustible material used to pack up under door. Option 1) remove and install non combustible materials Option 2) remove and install new door to correct height								
96805	L4 room 4001 service riser	,	4001	.	Fire door	104403	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Combustible material used to pack up under door. Option 1) remove and install non combustible materials Option 2) remove and install new door to correct height								
96806	L4 room 4002	,	4002	.	Fire door	104406	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Gap at bottom of door larger than 10mm Requires fdbu20 door seal								
96807	L4 room 4003	,	4002	.	Fire door	104407	31/03/2026	Yearly	Fail

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Gap at bottom of door larger than 10mm Requires fdbu20 door seal Intumescent seal on lock side								
96808	4F North Fire Stairwell (7)	1716	1716	Hotel Rooms 4001-4005	Single-Leafed Side-Hung Fire Door	5289	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96809	5F North Fire Stairwell (7)	1717	1717	North Tower Plant Room	Single-Leafed Side-Hung Fire Door	104466	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96810	3F North Fire Stairwell (7)	1718	1718	Hotel Rooms 3001-3005	Single-Leafed Side-Hung Fire Door	5290	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Gap at bottom of door larger than 10mm Requires fdbu20 door seal								
96813	L3 room 3004	.	3004	.	Fire door	104398	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Gap under door larger than 10mm Requires fdbu20 door seal								
96814	L3 service tower	172	.	Adj doom 3005	Fire door	104399	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96815	L3 room 3003	.	3003	.	Fire door	104402	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Gap under door larger than 10mm Requires fdbu20 door seal								
96816	L3 room 3002	.	3002	.	Fire door	5280	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96817	L3 room 3001	.	3001	.	Fire door	02182	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96818	L3 room 3001 service tower	.	3001	.	Fire door	104395	31/03/2026	Yearly	Fail

Lewie Fire Protection

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Asset Record - Job No. 98870

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026**Contact:** Michelle Davis**Phone:**

Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Combustible material used under door. Option 1) remove and install non combustible material under door Option 2) revolve and replace door to correct height								
96819	L3 room 3001 service tower	.	3001	.	Fire door	104396	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Combustible material used under door. Option 1) remove and install non combustible material under door Option 2) revolve and replace door to correct height								
96820	2F North Fire Stairwell (7)	1739	1739	Hotel Rooms 2001-2109	Single-Leafed Side-Hung Fire Door	104456	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96821	1F North Fire Stairwell (7)	1740	1740	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	104183	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96822	MF North Fire Stairwell (7)	1741	1741	Horizon	Single-Leafed Side-Hung Fire Door	000970	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Hinge adjustment and plan door. Door binding								
96842	GF North Fire Stairwell (7) to Verandah	1742	1742	Shopping Centre	Single-Leafed Side-Hung Fire Door	002369	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96860	2F North West Fire Stairwell (6)	1743	1743	Hotel Rooms 2001-2109	Single-Leafed Side-Hung Fire Door	104237	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Requires new striker plate								
96861	1F North West Fire Stairwell (6)	1744	1744	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	104173	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96862	MF North West Stairwell (6) to Toilets	1745	1745	Events Amenities	Single-Leafed Side-Hung Fire Door	035508	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96863	3F North West Fire Stairwell (6)	1746	1746	Roof Space Plant Rooms	Single-Leafed Side-Hung Fire Door	A104471	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96864	MF Main Plant Room to Service Corridor	1747	1747	Loading Dock	Single-Leafed Side-Hung Fire Door	105715	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	As previously reported								
96865	MF Main Switch Room to Service Corridor	1748	1748	Loading Dock	Single-Leafed Side-Hung Fire Door	105732	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96866	MF Offices Corridor to Events	240	240	Events	Double-Leafed Side-Hung Fire Door	B001375/B001376	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Meeting stiles have been damaged by trolleys and bent in, preventing doors from closing fully. Stiles require replacement and bollard installed in front on leading leaf side (to match bollard installed on trailing leaf side). Requires new sequence selector								
96969	MF Services Corridor to Substation Corridor	1750	1750	Loadong Dock	Single-Leafed Side-Hung Fire Door	157940	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96970	MF South West Fire Stairwell (3)	1751	1751	Loading Dock	Single-Leafed Side-Hung Fire Door	105734	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96971	3F Engineering Fire Stairwell (11) to Projection Room	1752	1752	Hotel Services	Single-Leafed Side-Hung Fire Door	104416	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Notes	Requires Intumescent seal on hinge side gap large than 3mm								
96972	3F Ballroom Projection Room	1753	1753	Hotel Services	Single-Leafed Side- Hung Fire Door	104470	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96973	3F Engineering Fire Stairwell (11) to Plant Room	1754	1754	Roof Space Plant Rooms	Single-Leafed Side- Hung Fire Door	03466	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96981	1F Engineering Fire Stairwell (11)	1756	1756	Hotel Services	Single-Leafed Side- Hung Fire Door	B03468	30/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door leaf requires hinge adjustment straightening in door frame to improve clearances								
96980	MF Engineering Fire Stairwell (11)	1757	1757	Hotel Services	Single-Leafed Side- Hung Fire Door	105703	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96983	MF Main Switch Room to Substation Corridor	1750	1750	Loading Dock	Single-Leafed Side- Hung Fire Door	105733	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	As previously reported								
96982	3F East Fire Stairwell (9)	1758	1758	Roof Space Plant Rooms	Single-Leafed Side- Hung Fire Door	A104412	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96979	MF PABX Room	165	165	Loading Dock	Single-Leafed Side- Hung Fire Door	B03452	24/04/2026	Yearly	Not Tested
Test Readings	Attendance Record No. (If Applicable):								
Notes	Unable to access								
96974	2F Engineering Fire Stairwell (11)	1755	1755	Hotel Services	Single-Leafed Side- Hung Fire Door	B03467	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96823	L3 room 3005	.	3005	L3	Fire door	01205	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Gap under door larger than 10mm Requires fdbu20 door seal								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
96811	L4 room 4004	,	4004	.	Fire door	104409	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap at bottom of door larger than 10mm Requires fdbu20 door seal								
96924	1F East Fire Stairwell (9)	1759	1759	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	104448	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96925	MF East Fire Stairwell (9)	1760	1760	Loading Dock	Single-Leafed Side-Hung Fire Door	01454	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap under door greater than 10mm requires fdbu20 door seal								
96926	GF East Fire Exit (9) to Shopping Centre	1762	1762	Shopping Centre	Single-Leafed Side-Hung Fire Door	B001853	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96928	3F North East Fire Stairwell (8)	1763	1763	Roof Space Plant Rooms	Single-Leafed Side-Hung Fire Door	104468	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96929	2F North East Fire Stairwell (8)	1764	1764	Hotel Rooms 2001-2109	Single-Leafed Side-Hung Fire Door	104450	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96930	1F North East Fire Stairwell (8)	1765	1765	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	104340	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96931	GF North East Fire Stairwell (8)	1767	1767	Hotel Services	Single-Leafed Side-Hung Fire Door	105725	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96932	GF North East Fire Stairwell (8A)	1768	1768	Carpark	Single-Leafed Side-Hung Fire Door	105726	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96933	MF Events Fire Stairwell (5) to Foyer	1769	1769	Events	Single-Leafed Side-Hung Fire Door	001124	31/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
96937	2F East Fire Stairwell (9)	1568	1568	Hotel Rooms 2001-2109	Single-Leafed Side-Hung Fire Door	5291	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96934	MF Events Meter Room	1770	1770	Events	Single-Leafed Side-Hung Fire Door	009389	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96935	MF Events Fire Stairwell (5) to Meter Room	1771	1771	Events	Single-Leafed Side-Hung Fire Door	02189	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door replaced by others								
96936	1F Events Fire Stairwell (5)	1772	1772	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	104150	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed								
96938	2F Events Fire Stairwell (5)	1773	1773	Hotel Rooms 2001-2109	Single-Leafed Side-Hung Fire Door	5288	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96939	3F Events Fire Stairwell (5)	1774	1774	Roof Space Plant Rooms	Single-Leafed Side-Hung Fire Door	104472	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96940	3F West Fire Stairwell (4)	1775	1775	Roof Space Plant Rooms	Single-Leafed Side-Hung Fire Door	104473	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap on hinge side of door greater than 3mm requires Intumescent seal								
96941	2F West Fire Stairwell (4)	1776	1776	Hotel Rooms 2001-2109	Single-Leafed Side-Hung Fire Door	104457	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door closer pulling away from door, requires refixing or replacing.								
	No striker plate. New to be installed								
96942	1F West Fire	1777	1777	Hotel Rooms	Single-Leafed	104033	31/03/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
	Stairwell (4)			1001-1095	Side-Hung Fire Door				
Test Readings	Attendance Record No. (If Applicable):								
96943	MF West Fire Stairwell (4) to Events Kitchen	1779	1779	Events	Single-Leafed Side-Hung Fire Door	001495	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Top of door has gap larger than 3mm. Requires Intumescent seal								
96944	MF West Fire Stairwell (4) to Function Room	1778	1778	Events	Single-Leafed Side-Hung Fire Door	001123	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96945	GF West Fire Stairwell (4) to Meter Room	1780	1780	Shopping Centre	Single-Leafed Side-Hung Fire Door	03463	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96946	GF South West Fire Exit (3) to Verandah	1781	1781	Shopping Centre	Single-Leafed Side-Hung Fire Door	00539	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96948	MF Offices Corridor to Services Corridor	1749	1749	Hotel Services	Loading Dock	157936	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96947	GF South West Fire Stairwell (3A)	1782	1782	Shopping Centre	Single-Leafed Side-Hung Fire Door	104424	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96950	GF South West Fire Exit (3) to Shopping Centre	1784	1784	Shopping Centre	Single-Leafed Side-Hung Fire Door	404308	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96951	GF Shopping Centre PWD/Baby	1785	1785	Shopping Centre	Single-Leafed Side-Hung Fire Door	404309	24/04/2026	Yearly	Fail

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
	Change Toilet Corridor to Bin Room								
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door leaf has >3mm clearance from door frame jamb, requires intumescent seal installed.								
	Top of door leaf has >3mm clearance from door frame head, requires intumescent seal installed.								
96952	GF Shopping Centre PWD/Baby Change Toilet Corridor to Gym Tenancy	1786	1786	Shopping Centre	Single-Leafed Side-Hung Fire Door	001583	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
96953	1F South West Fire Stairwell (3)	1787	1787	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	104436	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96954	2F South West Fire Stairwell (3)	1788	1788	Hotel Rooms 2001-2109	Single-Leafed Side-Hung Fire Door	104044	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96955	3F South West Fire Stairwell (3)	1789	1789	Cooling Towers	Single-Leafed Side-Hung Fire Door	00077	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door leaf rotting at bottom hinges side, requires replacement.								
	Door frame rusted out completely on bottom hinged side, requires capping and rust treatment.								
	Door latch does not return back to position and door can be pushed open, requires replacement.								
96956	3F Foyer Void Roof Space Access North	1790	1790	Roof Space Plant Rooms	Single-Leafed Side-Hung Fire Door	104477	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Door leaf requires straightening in door frame to improve clearances.								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

	Non fire rated latch. Requires to be replaced								
96957	3F Foyer Void Roof Space Access East	1792	1792 / 155	Roof Space Plant Rooms	Single-Leafed Side- Hung Fire Door	104478	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Not fire rated handle. Requires to be replaced								
	Door split, requires new door and new hardware								
96958	3F Main Hotel (1-4) Lift Motor Room	1791	1791	Roof Space Plant Rooms	Single-Leafed Side- Hung Fire Door	104413	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Door gap at head too large to put intumescent seal on. Door requires to be replaced								
96959	2F Staff Entry Fire Stairwell (2) to Lift Lobby	1793	1793	Hotel Lobby	Single-Leafed Side- Hung Fire Door	104322	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96961	GF South West Fire Stairwell (3) to Shopping Centre Fire Exit	1795	1795	Shopping Centre	Single-Leafed Side- Hung Fire Door	001852	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	As previously reported								
96960	2F Staff Entry Fire Stairwell (2) to Hotel Rooms	1794	1794	Hotel Rooms 2001-2109	Single-Leafed Side- Hung Fire Door	104015	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door leaf has >3mm clearance from door frame jamb, requires intumescent seal installed.								
96962	1F Staff Entry Fire Stairwell (2) to Hotel Rooms	1796	1796	Hotel Rooms 1001-1095	Single-Leafed Side- Hung Fire Door	104003	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96963	1F Staff Entry Fire Stairwell (2) to Lift Lobby	1797	1797	Hotel Lobby	Single-Leafed Side- Hung Fire Door	104326	31/03/2026	Yearly	Fail

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.3 - Other (Non Conformance) - 12.4.3.1								
Notes	Door leaf requires straightening on frame to improve clearances.								
96964	MF Staff Entry Fire Stairwell (2)	1798	1798	Hotel Services	Single-Leafed Side-Hung Fire Door	03461	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
96965	GF Staff Entry Fire Stairwell (2) to Hotel Lobby Toilets Foyer	1799	1799	Hotel Services	Single-Leafed Side-Hung Fire Door	105718	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Failure Points	0.2 - Other (Non Critical Defect) - 12.4.3.1								
Notes	Gap under door larger than 10mm requires fdbu20 door seal								
96966	GF Staff Entry Fire Stairwell (2) to Garbage Room	1800	1800	Hotel Services	Single-Leafed Side-Hung Fire Door	5286	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
102709	Lvl 1 1019 interconnecting	-	104074	-	Single leaf	104074	30/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
117128	BF Sprinkler Valve Room	253	253	Carpark	Single-Leafed Side-Hung Fire Door	A002388	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Intumescent seal damaged around latch, requires repair/replacement.								
117240	BF South Fire Exit (10) to Outside	272	272	Carpark	Single-Leafed Side-Hung Fire Door	405076	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door frame rusting, requires surface treatment to prevent further damage. Bottom of frame requires capping on both sides as it has completely rusted out. Door not sitting square in frame, likely due to frame damage. Top hinge is missing pin. Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
117260	BF Shopping Centre Stairs West	269	269	Carpark	Single-Leafed Side-Hung Fire Door	A105701	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
117293	BF Shopping Centre Stairs East	270	270	Carpark	Single-Leafed Side-Hung Fire	157934	24/04/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
					Door				
Test Readings	Attendance Record No. (If Applicable):								
117326	GF East Fire Stairwell (9A)	205	205	Shopping Centre	Single-Leafed Side-Hung Fire Door	A105710	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
117524	GF Shopping Centre to Bin Room	280	280	Shopping Centre	Double-Leafed Side-Hung Fire Door	H00130/1	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door leaf does not close from fully open position due to rubbing on concrete floor. Doors do not completely close due to overlapping over door leaves. Attention required. See photos								
117557	GF South West Fire Exit (3) to PWD/Baby Change Toilet Corridor	208	208	Shopping Centre	Single-Leafed Side-Hung Fire Door	04422	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
117590	GF South Fire Exit (10) to The Backyard Dining	214	214	Shopping Centre	Single-Leafed Side-Hung Fire Door	A002347	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
117623	GF East Fire Exit to Verandah	213	213	Shopping Centre	Single-Leafed Side-Hung Fire Door	A007553	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
117656	3F Staff Entry Fire Stairwell (2) to Plant Rooms West	159	159	Roof Space Plantrooms	Single-Leafed Side-Hung Fire Door	A104475	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
117657	3F Staff Entry Fire Stairwell (2) to Plant Rooms East	158	158	Roof Space Plant Rooms	Single-Leafed Side-Hung Fire Door	A104476	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
Notes	125mm back set for handle. All good								
117359	GF East Fire Stairwell (9)	1761	1761 / 206A	Shopping Centre	Single-Leafed Side-Hung Fire Door	A105724	24/04/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
117392	GF Staff Lift Lobby to Garbage Room	288	288	Hotel Services	Double-Leafed Side-Hung Fire Door	H00345	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Deep chips and gouges on leading leaf door face. Has gone beyond first layer so door may need to be replaced rather than repaired.								
	Meeting stile lip has been cut out in sections for unknown reason, leaving gap between door leaves.								
	Top of door leaf has >3mm clearance from door frame head, requires intumescent seal installed.								
117755	3F Kitchen Lift (5) Motor Room	226	226	Roof Space Plant Rooms	Single-Leafed Side-Hung Fire Door	A104411	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
117788	5F North Tower Lift (8) Motor Room	145	145	North Tower Plant Room	Single-Leafed Side-Hung Fire Door	A104467	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door been cut short and packed. Can not remove more than 6 mm of face of door, requires to be replaced								
117821	GF West Fire Stairwell (4) to Pier Bar BOH	172	172	Pier Bar	Single-Leafed Side-Hung Fire Door	B03464	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door frame rusted out at bottom, requires capping on one side.								
117920	MF Loading Dock Meter Room	234	234	Loading Dock	Single-Leafed Side-Hung Fire Door	B03469	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed.								
	Door leaf requires hinge adjustment straightening in door frame to improve clearances.								
	Frame rusted out at bottom, requires repair and capping on hinged side.								
	Door closer requires readjustment, fails to self close and/or latch properly.								
117986	GF South Fire Exit (10) to The Backyard Kitchen	215	215	Shopping Centre	Single-Leafed Side-Hung Fire Door	H00602	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
118019	GF South Fire Exit (10) to Waterbar	200	200	Shopping Centre	Single-Leafed Side-Hung Fire Door	B001342	24/04/2026	Yearly	Fail

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
	Dining								
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door leaf has >3mm clearance from door frame jamb, requires intumescent seal installed.								
118054	GF South Fire Exit (10) to Female Toilet	281	281	Shopping Centre	Single-Leafed Side-Hung Fire Door	A002349	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door leaf requires hinge adjustment straightening in door frame to improve clearances. No metal tag on door frame. No latch installed. No fire door signage								
118056	GF South Fire Exit (10) to Male Toilet	282	282	Shopping Centre	Single-Leafed Side-Hung Fire Door	A002350	24/04/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door leaf has >3mm clearance from door frame jamb, requires intumescent seal installed. Top of door leaf has >3mm clearance from door frame head, requires intumescent seal installed. No metal tag on door frame. No latch installed. No fire door signage								
118085	GF South Fire Exit (10) to Waterbar Kitchen	266	266	Shopping Centre	Single-Leafed Side-Hung Fire Door	B03480	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door leaf has >3mm clearance from door frame jamb, requires intumescent seal installed. Door leaf requires hinge adjustment straightening in door frame to improve clearances.								
118118	MF Horizon Club Corridor to Engineering	286	286	Horizons	Single-Leafed Side-Hung Fire Door	H00475	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
119669	L1 Staff Lift Lobby adj Rm 1004	150	-	L1 Staff Lift Lobby	Solid Core - Double Leaf	B03452/B03451	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door leaf severely damaged. Large section of laminate is separating from door. Door latch door not automatically self-latch. Door knob is non-compliant type. New door to incorporate lever type. Signage not present. Spacing at door head and between doors exceeds maximum of 3mm gap. Requires new hinges.								
119703	L1 Corridor adj Staff Lift Lobby & Rm 1004	7	.	.	Solid core - Single Leaf	A104002	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	No closer installed. Won't self latching Non fire rated handle fitted. Remove and replace								
119735	L1 Service doors	5	.	Beside staff elevator Adj room 1004	Double leaf	104435/104434	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Bottom of door leaf is >10mm above finished floor level, requires compliant sill installed. Remove barrel bot, install chain bolt Non fire rated lock No closers attached to seal latch								
119801	L1 corridor adjacent room 1041	244	244	Adj room 1041	Single leaf	035503	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Gap under door over 10mm requires fdbu20 door seal								
119834	L1 corridor	24	.	Laundry cupboard Adj room 1030	Single leaf	104131	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
119702	L1 service doors	6	.	Beside staff elevator Adj room 1004	Single leaf	104001	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	No slower installed. Not self latching Non fire rated lock. Requires new to be installed								

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset Register - 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - AS1851.2012									
Asset ID	Location	Equipment Number	Door Number	Building Number	Door Type	Tag Number	Date	Service	Pass / Fail
118349	5F South Tower Lift (7) Motor Room	225	225	South Tower Plant Room	Single-Leafed Side-Hung Fire Door	A104463	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Door been cut down on bottom. Requires new door								
118679	MF North East Fire Stairwell (8)	1766	1766	Horizon	Single-Leafed Side-Hung Fire Door	A105720	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
118712	1F Health Club	242	242	Hotel Rooms 1001-1095	Single-Leafed Side-Hung Fire Door	A104051	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
119901	L1 Kitchen	290	.	Ramp between kitchen and pool	Sliding Fire door	6990077	24/04/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
119966	L2 Corridor to Kitchen adj Rm 2101	128	.	L2 Kitchen	Solid core	A104302	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
120000	L2 Shangri-La Academy Rm adj Rm 2065	105	.	L2 Shangri-La Academy Rm	Solid core	A104454	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
120066	L2 Corridor-Service riser adj Rm 2004	67	.	L2 services riser	Solid core	A104038	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	No door closer. Door not self latching								
119867	L1 kitchen to corridor	64	.	Kitchen to corridor ocean side	Single leaf	104328	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
119933	L2 Corridor to kitchen	133A	133A	Ocean side corridor to kitchen	Single leaf	104311	31/03/2026	Yearly	Pass
Test Readings	Attendance Record No. (If Applicable):								
119900	L1 kitchen	289	.	Walkway between kitchen and pool	Automatic sliding	6990077	24/04/2026	Yearly	Pass

Lewie Fire Protection
 4 Schmid Street
 Garbutt, 4814
 Ph: 07 4728 3622
 ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Test Readings	Attendance Record No. (If Applicable):								
120032	L2 service door	100	100	L2 laundry store Adj room 2057	Single leaf	104235	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Top of door leaf has >3mm clearance from door frame head, requires intumescent seal installed.								
119999	L2 service door	104	104	L2 academy room	Double leaf	104452/104453	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	Requires selector, old on broken Remover barrel bolt and chain latch Requires chain bolt installed								
120067	L2 service doors	68	68	Comms riser Adj room 2004	Single leaf	104081	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	No closer on door. Not self latching								
120069	L2 Service doors	66	66	Staff lift doors Adj room 2004	Double leaf	03458	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	No selector installed Barrel bolt to be removed Chain bolt to be installed Intumescent seal across head								
120065	L2 Service doors	69	69	Comms riser Adj room 2004	Double leaf	104093	31/03/2026	Yearly	Fail
Test Readings	Attendance Record No. (If Applicable):								
Notes	No closers on either doors. Not self latching								

Description Of Work

Asset ID 96020 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level Yearly (Includes 6 Monthly) - Service Due Date 01/04/2026
 Asset ID 96021 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level Yearly (Includes 6 Monthly) - Service Due Date 01/04/2026
 Asset ID 96022 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level Yearly (Includes 6 Monthly) - Service Due Date 01/04/2026
 Asset ID 96023 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level Yearly (Includes 6 Monthly) - Service Due Date 01/04/2026
 Asset ID 96024 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level Yearly (Includes 6 Monthly) - Service Due Date 01/04/2026
 Asset ID 96025 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level Yearly (Includes 6 Monthly) - Service Due Date 01/04/2026
 Asset ID 93522 - Asset Type 06.1A Fire Resistant Doorsets Service Record - Service Level Yearly (Includes 6 Monthly, 3 Monthly) - Service Due Date 01/04/2026
 Asset ID 96030 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level Yearly (Includes 6 Monthly) - Service Due Date 01/04/2026
 Asset ID 96031 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level Yearly (Includes 6 Monthly) - Service Due Date 01/04/2026
 Asset ID 96032 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level Yearly (Includes 6 Monthly) - Service Due Date 01/04/2026

Lewie Fire Protection
4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

Lewie Fire Protection
4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

Lewie Fire Protection

Garbutt. 4814

ABN 18 146 907 511

ADN 13 13 001 011

Shangri-La Hotel - Pierpoint Road Cairns

Pierpoint Road

Cairns OLD 487

Inspection Date: 24/04/2026

Contact: Michelle Davis

Phone:[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

Lewie Fire Protection
4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Asset Record - Job No. 99870
Shangri-La Hotel - Pierpoint Road Cairns
 Pierpoint Road
 Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

[illegible]

Lewie Fire Protection

Garbutt, 4814

Ph: 07 4728 3622

ABN 18 146 907 511

Shangri-La Hotel - Pierpoint Road Cairns

Pierpoint Road

Pierpoint Road

Cairns QLD 4870

Inspection Date: 24/04/2026

Contact: Michelle Davis

Phone:[illegible]

Lewie Fire Protection
4 Schmid Street
Garbutt, 4814
Ph: 07 4728 3622
ABN 18 146 907 511

Asset Record - Job No. 98870
Shangri-La Hotel - Pierpoint Road Cairns
Pierpoint Road
Cairns QLD 4870

Inspection Date: 24/04/2026
Contact: Michelle Davis
Phone:

Asset ID 120069 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level 6 Monthly - Service Due Date 01/04/2026
Asset ID 120065 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level 6 Monthly - Service Due Date 01/04/2026
Asset ID 120131 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level 6 Monthly - Service Due Date 01/04/2026
Asset ID 126368 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level 3 Monthly - Service Due Date 01/04/2026
Asset ID 126369 - Asset Type 06.1 Passive Fire and Smoke Systems - Fire Resistant Doorsets - Service Level 3 Monthly - Service Due Date 01/04/2026

Comments / Recommendations

All works above have been routinely serviced and maintained in accordance with AS1851.2012 amendment 1 & AS2293.2 and the information on this data report is true and correct. This record does not infer compliance with all applicable building and fire safety legislation within the relevant jurisdiction.

Technician (Print Name):

Licence No.

Customer (Print Name):

Technician (Signature):

Customer (Signature):