No.	Status	Date
HIS-2007-0388-DFR-1	Issued	2007-09-18

Daily Field Report 1 - UT Thickness Survey and Fitting Scans - Regenerator Overhead Circuit

Scope of Work

Kevin Doucette performed a UT thickness survey on the regenerator overhead circuit within ATU-100. The scope included thickness measurements and fitting scans on lines 3-RV-101 and 2-RV-102 to assess wall loss and integrity.

The activities were conducted under the requirements of QSCP-NDT-001 Rev 0 and HIS-UT-002 Rev 1. All measurements were executed in accordance with ASTM E797.

Equipment and Calibration

Thickness measurements were obtained using a Krautkrämer DMS 2 0317. The instrument calibration is verified by HIS-CAL-07-015.

Field calibration and standardization were performed using HIS-STB-02 to ensure measurement accuracy across the required thickness range.

Inspection of Line 3-RV-101

UT thickness data was collected for 3-RV-101, an A106 Gr.B line with a nominal thickness of 7.62 mm. The survey focused on identifying areas of wall thinning relative to the retirement thickness of 3.56 mm.

The line is classified as Class 1 due to its service as regenerator overhead sour gas, requiring a maximum inspection interval of 5 years.

Inspection of Line 2-RV-102

Thickness measurements were performed on 2-RV-102, an A106 Gr.B line with a nominal thickness of 5.54 mm and a retirement thickness of 2.79 mm.

Specific attention was given to the 90° elbow where a pinhole leak was reported. This work was performed under QSCP-WP-2007-09311, which records the isolation of the line and the installation of a leak clamp at the elbow location.

Sign-off	Name	Function	Date	Signature
Prepared	Kevin Doucette	lead UT technician, SNT-TC-1A UT Level II	2007-09-18	_____