Carrow Integrity Engineering Ltd.

Transmittal

Site: Hamilton Plant

No.	Status	Date
CIE-TR-2025-011	Issued	2025-02-24

Transmittal - FFS Reports CIE-FFS-2025-004-R0 and CIE-FFS-2025-005-R0

Distribution Details

To: QSCP Hamilton Inspection Department

Attn: Department Manager

From: Carrow Integrity Engineering Ltd.

Date: 2025-02-24

Project: ATU-100 Amine Treating Unit

Enclosures

CIE-FFS-2025-004-R0: Fitness-for-Service Assessment - 4-RA-101 Local Metal Loss (Level 2), dated 2025-02-17.

CIE-FFS-2025-005-R0: Fitness-for-Service Assessment - 6-RA-103-11 Local Metal Loss (Level 2), dated 2025-02-24.

Purpose and Summary

Purpose: For Review and Action.

CIE-FFS-2025-004-R0: Level 2 assessment of local metal loss at CML-06. Attack attributed to flashing downstream of let-down valve following 2019 trim change without MOC.

CIE-FFS-2025-005-R0: Level 2 assessment of local metal loss. Acceptable for service provided let-down valve trim is restored. Re-measurement required at 12 months.

Acknowledgement of Receipt

Please acknowledge receipt by signing and returning a copy of this transmittal CIE-TR-2025-011 to Carrow Integrity Engineering Ltd.