| No. | Status | Date |
|---|---|---|
| QSCP-WP-2010-06044 | Issued | 2010-06-07 |

# Work Permit - Profile RT and Insulation Repair, 4-RA-104 / 4-LA-104

## General Information

Permit Number: QSCP-WP-2010-06044

Date: 2010-06-07

Location: Hamilton Plant, ATU-100

Issuer: Tom Bradley, Area Operator

Receiver: Maintenance / NDE Contractor

Time Window: 07:00 to 18:00

## Work Description

Scope: Profile RT for CUI assessment on 4-RA-104 and 4-LA-104 following QSCP-INS-2010-021.

Insulation: Removal of wet insulation and damaged jacketing on 4-LA-104; renewal in kind following NDE.

Subject 4-RA-104: Rich side L/R exchanger piping, A106 Gr.B, 114.3 mm OD, 8.56 mm t_nom, 862 kPa(g) / 127 °C.

Subject 4-LA-104: Lean side L/R exchanger piping, A106 Gr.B, 114.3 mm OD, 6.02 mm t_nom, 2758 kPa(g) / 138 °C.

## Isolations and Precautions

Radiography: Controlled area barriers and signage required for profile RT.

CUI Criteria: Retirement thickness t-min 3.81 mm for 4-RA-104 and 3.18 mm for 4-LA-104; readings below t-min require NCR.

PPE: Standard site requirements plus specific handling for wet insulation removal.

Access: Scaffolding required for external visual and jacketing repair per QSCP-INS-2010-021.

| Sign-off | Name | Function | Date | Signature |
|---|---|---|---|---|
| Prepared | Tom Bradley | Area Operator (permit issuer) | 2010-06-07 | _____ |