No.	Status	Date
QSCP-RBI-NR21-2018	Issued	26.11.2018

Risk-Based Inspection Review - Anlage 21

Executive Summary

This document summarizes the first Risk-Based Inspection review for ANLAGE-21, conducted by Daniel Hartmann to ensure compliance with QSCP-CIS-001 Rev 0. The review incorporates historical damage mechanisms and recent inspection results to establish a re-baselined integrity strategy for the solvent recovery unit.

Technical Review and Inspection History

The assessment reviewed RLW-PB-2018-0152, which documented periodic wall-thickness measurements and NDT strength testing. Further validation was provided by ANG-DA-2018-04033, a periodic ZÜS inspection covering external examination and strength testing, which reported no deficiencies. These results satisfy the CML re-baseline and data requirements mandated by the corporate integrity standard.

Risk Drivers and Damage Mechanisms

Integrity planning accounts for NR-UA-2014-01, a root-cause analysis regarding chloride-induced stress corrosion cracking on line NR-21-L-0412. The failure was attributed to external chlorides under insulation following rain ingress through damaged cladding, exacerbated by a 2011 process change where K-2101 bottoms temperature increased from 95. This mechanism is classified per API RP 571. Future inspection intervals are set within code maxima per QSCP-CIS-001 Rev 0, requiring Fitness-For-Service assessments by a qualified engineer where applicable.

Sign-off	Name	Function	Date	Signature
Prepared	Daniel Hartmann	Integrity Engineer, QSCP Corporate Asset Integrity, based at Werk Niederrhein	26.11.2018	_____