


Method 2: Bracket Installation (For Selected Models)

Bracket Installed Separately


Note: The bracket is used to secure the supplemental light to the main fixture, keeping it stable and preventing any movement or accidental falls.



(A) Embedded Installation


Note: UV30 and IR16 models are compatible with G/SE 4500 and 5000 fixtures.

- 1. Inserting the supplemental light bar into the bracket.
- 2. Position the bracket, with the light bar attached, between the two bars of the main light.
- 3. Secure the bracket and adjust for stability.
- 4. connect the light bar to the power source.



(B) Auxiliary Support Suspension Installation

- 1. Insert the supplemental light bar into the bracket.
- 2. Place the bracketed light bar on both sides of the main light, ensuring one end of the bracket rests securely on the main light for added stability.
- 3. Install the ratchet hanger following the Hanging Installation Method 1 to suspend the light.



DE

Option 2

- 1. Setzen Sie die Zusatzlichtleiste in die Halterung ein.
- 2. Positionieren Sie die Halterung mit der befestigten Lichtleiste zwischen den beiden Leisten des Hauptlichts.
- 3. Befestigen Sie die Halterung und justieren Sie sie für Stabilität.
- 4. Schließen Sie die Lichtleiste an die Stromquelle an.

IT

Opzione 2

- 1. Inserire la barra luminosa supplementare nella staffa.
- 2. Posizionare la staffa, con la barra luminosa fissata, tra le due barre della luce principale.
- 3. Fissare la staffa e regolare per garantire stabilità.
- 4. Collegare la barra luminosa alla fonte di alimentazione.

FR

Option 2

- 1. Insérez la barre lumineuse supplémentaire dans le support.
- 2. Positionnez le support, avec la barre lumineuse fixée, entre les deux barres de la lumière principale.
- 3. Fixez le support et ajustez-le pour assurer sa stabilité.
- 4. Connectez la barre lumineuse à la source d'alimentation.

ES

Opción 2

- 1. Inserte la barra de luz suplementaria en el soporte.
- 2. Coloque el soporte, con la barra de luz adjunta, entre las dos barras de la luz principal.
- 3. Asegure el soporte y ajuste para garantizar la estabilidad.
- 4. Conecte la barra de luz a la fuente de alimentación.

NL

Optie 2

- 1. Plaats de aanvullende lichtbalk in de beugel.
- 2. Positioneer de beugel, met de lichtbalk bevestigd, tussen de twee balken van het hoofdlampje.
- 3. Bevestig de beugel en stel deze af voor stabiliteit.
- 4. Sluit de lichtbalk aan op de stroombron.

USAGE GUIDELINES

Light Type	Growth Stage	Typical Duration	Schedule Suggestions
UV	Vegetative and Flowering	1 to 2 hours	Mid and late vegetative: 1 hour Final 2 to 3 weeks of vegetative: 1 to 1.5 hours Mid flowering: 1.5 to 2 hours Final 2 to 3 weeks of flowering: 2 hours
IR	Flowering	30 minutes	Wake Up: Turn on IR 15 minutes before the main light Plant Sleep: Keep IR on for 10-15 minutes after the main light turns off
General Tips	1.Increase UV duration gradually and monitor plants for any signs of stress or damage. 2. Wear protective glasses when using the light.		

SAFETY GUIDELINES

- 1. Read all instructions carefully and ensure the power source meets the product's electrical requirements.
- 2. Handle all wiring with care during installation and keep cables away from sharp edges.
- 3. Do not use this product in hazardous environments such as flammable, explosive, chemical, or wet areas.
- 4. Keep power cords exposed and free from rugs, fabrics, or other coverings.
- 5. Follow all safety precautions during installation, operation, and maintenance.
- 6. Do not block or tamper with the product to avoid the risk of electric shock, fire, or damage.
- 7. Always unplug the unit before installing, servicing, or relocating it.
- 8. Do not operate the product if the cord is damaged, or if it has been dropped, malfunctioning, or otherwise compromised.
- 9. Wear protective goggles and gloves when handling LED fixtures or UV lamps to protect your eyes and skin.

WARRANTY

Spider Farmer provides warranty services in the United States, Canada, the United Kingdom, Europe, and Australia.

30-Day Return Policy

Returns or exchanges are accepted within 30 days of delivery if the product remains in its original condition. All return shipping costs are covered by Spider Farmer.

2-Year Limited Warranty

Within 1 Year: Free repair or replacement for product defects. Customers are responsible for shipping costs.

From 1 to 2 Years: Customers may receive free accessories or a trade-in discount. Repair services remain available; however, all associated costs, including parts and shipping, are the responsibility of the customer.

Exclusions


This warranty does not cover damage caused by misuse, abuse, or normal wear and tear (such as scratches). Any unauthorized repairs, modifications, or improper use will void the warranty.

Limitation of Liability

Spider Farmer is not responsible for any consequential or incidental damages arising from the use or inability to use this product.

Spider Farmer
USER MANUAL
Supplemental Light Bars

Revolutionize Your Harvest with Supply Series



UV30 & IR16 SUPPLEMENTAL LIGHTS

SUPP-UV30 PPF: 12.31μmol/s

Spectrum	365-370nm	Power Draw	15 W ±5% per bar
Core Coverage	3ft x 2ft	Light Size	23.62" × 1.31" × 1.22" (60 × 3.32 × 3.1 cm)
Input Voltage	AC100-277V	LED Quantity	60 pcs per bar
Current	0.1829A @ AC120V 0.1052A @ AC240V 0.09803A @ AC277V	Frenquency	50/60HZ

SUPP-IR16 PPF: 33.15μmol/s

Spectrum	730-745nm	Power Draw	8 W ±5% per bar
Core Coverage	3ft x 2ft	Light Size	23.62" × 1.31" × 1.22" (60 × 3.32 × 3.1 cm)
Input Voltage	AC100-277V	LED Quantity	44 pcs per bar
Current	0.1358A @ AC120V 0.08062A @ AC240V 0.0767A @ AC277V	Frenquency	50/60HZ

折
叠
线

折
叠
线

UV60 & IR30 SUPPLEMENTAL LIGHTS


SUPP-UV60 PPF: 30.92μmol/s

Spectrum	365-370nm	Power Draw	27 W ±5% per bar
Core Coverage	4ft x 2ft	Light Size	35.43" × 1.31" × 1.22" (90 × 3.32 × 3.1 cm)
Input Voltage	AC100-277V	LED Quantity	120 pcs per bar
Current	0.4447A @ AC120V 0.2429A @ AC240V 0.2214A @ AC277V	Frenquency	50/60HZ

折
叠
线

折
叠
线

PACKAGE INCLUDES




INSTALLATION

Method 1: Hanging Installation (Universal)

Suitable for all models, including SF, G, and SE series.

1. Attach End A of the ratchet hanger to the hole at one end of the first light bar.
2. Loop the rope over the hanging rod and secure it by attaching End B of the ratchet hanger to the rope.
3. Pull the rope to adjust the light bar to the desired height.
4. Repeat steps 1-3 for the remaining light bars.
5. Connect all light bars to a power source.



折
叠
线

折
叠
线

- DE Option 1**
1. Befestigen Sie Ende A des Ratschenaufhängers am Loch an einem Ende der ersten Lichtleiste.
 2. Führen Sie das Seil über die Aufhängestange und sichern Sie es, indem Sie Ende B des Ratschenaufhängers am Seil befestigen.
 3. Ziehen Sie am Seil, um die Lichtleiste auf die gewünschte Höhe einzustellen.
 4. Wiederholen Sie die Schritte 1-3 für die verbleibenden Lichtleisten.
 5. Schließen Sie beide Lichtleisten an eine Stromquelle an.

- IT Opzione 1**
1. Collega l'estremità A del cricchetto al foro a un'estremità della prima barra luminosa.
 2. Passa la corda sopra l'asta di sospensione e fissala collegando l'estremità B del cricchetto alla corda.
 3. Tira la corda per regolare la barra luminosa all'altezza desiderata.
 4. Ripeti i passaggi 1-3 per le altre barre luminose.
 5. Collega entrambe le barre luminose a una fonte di alimentazione.

- FR Option 1**
1. Fixez l' extrémité A du crochet à cliquet dans le trou à une extrémité de la première barre lumineuse.
 2. Passez la corde par-dessus la tringle de suspension et fixez-la en attachant l' extrémité B du crochet à cliquet à la corde.
 3. Tirez sur la corde pour régler la hauteur de la barre lumineuse à la hauteur souhaitée.
 4. Répétez les étapes 1 à 3 pour les autres barres lumineuses.
 5. Branchez les deux barres lumineuses à une source d' alimentation. entation.

- ES Opción 1**
1. Fije el extremo A del colgador de carraca al orificio en un extremo de la primera barra de luz.
 2. Pase la cuerda sobre la barra de suspensión y asegúrela conectando el extremo B del colgador de carraca a la cuerda.
 3. Tire de la cuerda para ajustar la barra de luz a la altura deseada.
 4. Repita los pasos 1-3 para las barras de luz restantes.
 5. Conecte ambas barras de luz a una fuente de energía.

- NL Optie 1**
1. Bevestig uiteinde A van de ratelophanging aan het gat aan een uiteinde van de eerste lichtbalk.
 2. Leid het touw over de ophangstang en bevestig uiteinde B van de ratelophanging aan het touw.
 3. Trek aan het touw om de lichtbalk op de gewenste hoogte af te stellen.
 4. Herhaal stappen 1-3 voor de overige lichtbalken.
 5. Sluit beide lichtbalken aan op een stroombron.

YOUR RELIABLE INDOOR GROW PARTNER

折
叠
线

折
叠
线

Follow Us on Social Media



Email:
support@spider-farmer.com
info@spider-farmer.com