#Write an assembly language program toconvert a binary number into packed BCD OR Write an assembly language program to convert a Hexa-Decimal number into decimal number.

LDA 8200H MVI B,00H MOV C,B; **CPI 64H**; **JC HUNT SUI 64H** INR B **JMP HUNT: CPI 0A JC UNIT** SUI OA INR C JMP HUNT **UNIT:STA 8201** MOV A,C; **STA 8202** MOV A,B **STA 8203**

HLT