## #Write an assembly language program tocount from 0 to 9 with appropriate delaybetween count. MVI C, 00H; LOOP: CALL DELAY; INR C; MVI A, 09H; CMP C; JZ DONE; JZ DONE; JMP LOOP; DELAY: MVI B, FFH; DELAY\_LOOP: DCX B; MOV A, B CPI 00H; JNZ DELAY\_LOOP; RET; DONE: HLT;