			JP1
		+5V	1
		GND	2
TX1up	D4	GPI02	3
up.	D3	GPI00	4
'	D2	GPI04	$5\bigcirc$
	D1	GPI05	6
		RX	$7\bigcirc$
		TX	8

JP2				
$\bigcirc^1$	+3V3			
$\mathcal{C}_2$	GPI015	D8	down	SS
$\mathcal{L}_3$	<u>GPI013</u>	D7		MOSI
$\sim$ 4	GPI012	D6		MISO
$\sum_{5}$	GPIO14	D5		CLK
$\sim_6$	<u>GPI016</u>	DØ		
$\bigcirc_7$	<u>A0</u>			
$\mathcal{S}_8$	RST		up	
			•	

## 1-Button Shield

WeMos.cc

