Tutorial - 2: Modeling an Electromagnet


ELL851 - Computer Aided Design of Electrical Machines

Problem Description:

A ferromagnetic material, wound by a current carrying conductor, behaves as an electromagnet.

What'll you understand: Assigning material properties, winding assignment

Reference Model for electromagnet: (consider copper wire gauge at 10 SWG, single conductor at 10A)



Define Initial Design Parameters (Known)

```
clc; clear all;
freq = 0; %frequency of the problem, Hz
CoreW = 20; CoreH = 10; %core width and core height, mm
CoilW = 8; CoilH = 3; %coil width and coil height, mm
gap = 0.5; %gap between core and coil
boundary_rad = 2.5*CoreW; % boundary radius, 2.5xCoreW
```

Open FEMM and Define Initial Settings

```
openfemm(); newdocument(0); % for Magnetostatic problems
messagebox('Tutorial-II, Electromagnet'); %display name of tutorial
mi_probdef(freq,'millimeters','planar',1.e-8,0,30); %problem definition
```

Geometry Definition

```
mi_drawrectangle ([-CoreW/2 0; CoreW/2 CoreH]) %Core
mi_drawrectangle ([-CoreW/2+1 CoreH + gap; CoreW/2-1 CoreH + gap + CoilH;])%top_Coil
mi_drawrectangle ([-CoreW/2+1 -gap; CoreW/2-1 -(gap + CoilH);])%bot_Coil
mi_drawarc(boundary_rad, CoreH/2, -boundary_rad, CoreH/2, 180, 5) %boundary arc 1
mi_drawarc(-boundary_rad, CoreH/2, boundary_rad, CoreH/2, 180, 5) %boundary arc 2
mi_zoomnatural
```

Boundary Assignment

Use repeatable code sections wherever possible

```
mi_addboundprop('Air',0,0,0,0,0,0,0,0,0);
mi_selectarcsegment(0,boundary_rad); mi_selectarcsegment(0,-boundary_rad); %Select boundary
mi_setarcsegmentprop(5, 'Air', 0, 1); %group 1
mi_clearselected
```

Material Assignment


```
% Get materials and set materials to labels
mi_getmaterial('M-50'); mi_addblocklabel(0, CoreH/2); mi_selectlabel(0, CoreH/2);
mi setblockprop('M-50',1,0,'None',0,1,0); %M-50, group 2
mi clearselected();
mi getmaterial('Air');mi addblocklabel(0,boundary rad/2); mi selectlabel(0,boundary rad/2);
mi_setblockprop('Air',1,0,'None',0,3,0); %Air, group 3
mi_clearselected();
turns = 1;
mi_getmaterial('10 SWG'); mi_addblocklabel(0,CoreH+gap+CoilH/2);
mi selectlabel(0,CoreH+gap+CoilH/2); mi addcircprop('Winding', 10, 1);
mi_setblockprop('10 SWG',1,0,'Winding',0,0,turns); %Air, group 3
mi_clearselected();
mi getmaterial('10 SWG'); mi addblocklabel(0,-(gap+CoilH/2));
mi selectlabel(0,-(gap+CoilH/2)); mi addcircprop('Winding', 10, 1);
mi setblockprop('10 SWG',1,0,'Winding',0,0,-turns); %Air, group 3
mi_clearselected();
```

Analyze

```
%Save before analyzing
mi_saveas('Assignment2.FEM'); mi_createmesh; mi_analyze;
mi_loadsolution; mi_zoomnatural;
mo_showdensityplot(1,0,0.1,0.0,'bmag'); %outputs flux density
mo_setgrid(0.5, 'cart');
```

Assignment 2 - Questions:

1. Plot B_x and B_y at the contours shown in Fig. along 'A' and 'C' (contours in a single plot), 'B' and 'D' (contours in a single plot).



2. Vary the current (2.5A, 5A, 10A...) and the number of turns (10, 50, 100, 200...) and plot B_x @Cvs current & B_x @Cvs turns. Explain your findings.

(Additional work: Try testing out an axisymmetric solution for the same problem !)