
# **Feedback from Akebono**

1) There shouldn't be the gray line above the Akebono logo.

## 2) In Mold Identification System:

- Mold ID has to be manually filled. When the Mold ID is filled, it should display all the remaining fields.
- Mold ID has to be on the top. Remaining parameters after that.
- Change Mold Name to Model Name.
- Change the GUI so that the user knows which field has to be filled and which field will be from DB.
- Apart from Mold ID, all the remaining field will be fetched from DB.
- Make buttons conspicuous. It doesn't look like button now.

#### Change buttons:



- Reset Mold Current Short → Clean Switch
- Reset Mold Hard Chrome Short → Hard Chrome
- Reset Custom Mold Physical Specific → Die Change Switch
- Show This Mold Historical → History of Mold

#### Functionality of buttons:

- a) **Clean Switch:** When clicked on clean switch, it takes to Maintenance Control Mold page.
- Maintenance Control Mold page has 3 buttons.
- Save: When clicked on save, it resets current short & displays the report.

- Hard Chrome Switch & Save: When clicked on Hard Chrome Switch and Save, it resets Hard Chrome data and Current data/shot and displays the report.
- Die Change & Save: When click on the Die Change & Save, it resets all and displays the report.
- **b)** Hard Chrome Switch: When clicked on Hard Chrome Switch, it shows the report.
- c) Die Change: When clicked on Die Change, it shows the report.

## 3) Status History Display:

No search by Mold ID.

# 4) Forecast Setting page missing.

## 5) Forecast:

- Should have a field/drop down to select the year passed to view the details/report of that year.
- Year in Forecast is dynamic.

#### 6) Clean History:

- When Shot is selected → Header of the trend change to Shot.
- When Hard Chrome is selected → Header of the trend change to **Hard Chrome**.
- When Die Change is selected → Header of the trend change to **Die Change**.

#### 7) Temperature & Pressure:

- Show trends
- Graph select by time