


## Workshop practice :quiz, Date: 05/07/2021


Total points 22/40

The respondent's email (20je0206@me.iitism.ac.in) was recorded on submission of this









## The image shown below is used in fitting shop for the purpose of 0/2




- Marking the sample
- punching the sample
- Cutting the sample
- all of the above

## Correct answer

Marking the sample

X




In the image below, molten metal is being poured from a\_\_\_\_\_ 0/2 Furnace Laddle Mould X Basin Correct answer Laddle

✓ In the image, the molten metal is being poured into	2/2
Pouring basin	<b>✓</b>
Runner	
Riser	
None of the above	
★ Which of the following metal can not cast:	0/2
Brass	
Cast iron	×
Aluminium	
None of the above	
Correct answer	
None of the above	

0/2

X

X Identify the component shown in the image below, mainly used in \_ of a lathe:




- Tail stock
- Head stock
- Carriage
- all of the above


Correct answer


Head stock


The image below indicate that the operator is working on \_\_\_\_\_ of a 2/2 lathe.




- head stock
- tail stock
- tool post
- all of the above









The image below is used for making\_

2/2





- External Thread
- Internal thread
- Hole
- All of the above

!

Workshop practice :quiz, Date:05/07/2021 The image below is a \_\_\_\_\_machine. 2/2 Drilling

- slotting
- shaping
- none of the above





This form was created inside of Indian Institute of Technology (Indian School of Mines), Dhanbad.

Google Forms