


DCS process loop & ADC interface

CONNECTIONS.md rev E · SCH-DCS-003 rev H · unused pins omitted · F1 amp rating TBD



Designators

PS1=PSU_MW · F1=FU_HESI · J1=TT_RM · R1=RS250 · U2=U_ADS · U3=U_LLC · U1=U_PI
+24V_PSU □ F1 □ +24V_LOOP □ Rosemount. Fuse amp TBD. No Fluke/relay/software on sheet.

DCS — Distributed Control System (bench)		
PS1 · F1 · loop · 250R · ADS1115 · LLC · Pi 4		
SCH-DCS-003	REV H	1 / 1
2026-09-28	NTS	A3L
Truth: CONNECTIONS.md · hand-drawn SVG (no KiCad)		