ShiaanX — Investor Demo Video Plan

Internal use only · v2

OBJECTIVE

Show investors the AI learning in action using real data from our vendor integrations. Target length: 3–4 minutes.

BEFORE — The Broken Process

Step 1: Drawing shared with 3 vendors

- Same drawing sent to Vendor A, B, C — all 3 have complete integrations with us
- Three different people going through the same drawing in three different environments
- Different quotes, different time to quote, different approach, different cycle time

Production: Actually shoot — 3 separate locations, phone camera

Step 2: Three different outputs from the digital layer

- Programs of all 3 vendors side by side + corresponding cycle times
- Vendor A vs Vendor B vs Vendor C ranked by efficiency from our digital layer

Production: Screen recording of actual programs from our system

Step 3: Goes into manufacturing

- All three go to production

Step 4: Vendor A has defects in first article

- Drawing specified a 3.2mm hole — QC showed it came out at 3.0mm
- Part is rejected — does not match the design

Production: Shoot — physical part + QC report showing the deviation

THE AI — What We Did

Step 5: Analyse the closed loop

System looks at all 4 data points collected for this job:

- Drawing — what was asked for (3.2mm hole)
- Program — how the machinist planned to make it
- Machine data — what actually happened on the machine
- QC report — what came out (3.0mm, 0.2mm short)

Production: Screen recording of closed loop analysis on dashboard

Step 6: Root cause identified

- System identifies: the cutting tool was moving too fast
- At high speed, a small cutting tool bends slightly under pressure — causing it to cut less material than planned, making the hole come out smaller than designed
- Fix identified: slow the cutting speed down

Production: Screen recording of closed loop analysis on dashboard

Step 7: Fix applied — rule added to rule sheet

RULE ADDED: When making a 3.2mm hole with a 2mm cutting tool — slow the cutting speed from 1000 to 400. At higher speed, the small tool bends slightly under pressure and the hole comes out smaller than designed. Slowing down removes the bending effect.

Production: Screen recording showing rule being added to rule sheet

Step 8: Next parts come out correct

- Same job, corrected speed — hole within tolerance

Production: Shoot — correct part, clean QC report

AFTER — The ShiaanX Capability

Step 9: Everything fed into AI engine

- All data from 3 vendors, this part, these runs — fed into the model

Step 10: Now we can generate an instant quote

- Upload the same drawing — quote appears in seconds

Production: Screen recording of instant quote feature — use a part already manufactured

Step 11: Make this part or any similar part with any vendor

- System knows the right approach, right settings, right vendor to route to
- Next time a similar hole appears in any drawing — the fix is already built in

Production: Screen recording showing system recommendation

THE CENTREPIECE MOMENT — Voiceover Script

"Vendor A's first article came out wrong.
The drawing asked for a 3.2mm hole. QC measured it at 3.0mm.
We looked at all four data points — the drawing, the program, the machine data, and the QC report.
The root cause: the cutting tool was moving too fast.
At high speed, a small tool bends slightly under pressure — and cuts less than it should.
The fix: slow it down.
Next parts came out correct.
That rule is now in the system permanently.
It will never make that mistake on this feature again."

PRODUCTION APPROACH

Section	Medium	Tool / Method
3 vendors, 3 environments	Actual shoot	Phone camera, 3 locations
Programs + cycle times	Screen recording	Loom or OBS
Defective part + QC report	Actual shoot	Close-up, physical report
Closed loop + root cause	Screen recording	Loom or OBS
Rule added to rule sheet	Screen recording	Loom or OBS

Correct part output	Actual shoot	Part on table, clean QC
Instant quote feature	Screen recording	Loom or OBS — known part

WHAT WE NEED BEFORE FILMING

- ■ Screen recording of programs (Vendor A, B, C) with cycle times visible
- ■ Access to 3 vendor locations for brief shoot footage
- ■ The defective first article from Vendor A (3.2mm hole came out 3.0mm) + its QC report
- ■ The corrected parts from the fixed run
- ■ Closed loop dashboard showing the deviation data
- ■ Rule sheet screenshot showing the new rule added
- ■ Instant quote feature ready to demo — use a part already manufactured