



<u>図中、穴位置公差は精度穴のみ必要</u>
<u>HOLE POS. TOLERANCE NEED ONLY</u>
<u>ACCURACY HOLE IN DRAWING</u>
<u>接合部は溶接構造とする</u>
<u>MAKE THIS PART BY WELDING</u>

指示無き角部はC0. 5面取りの  
ALL CORNERS SHALL  
BE CHAMFERED C0.  
EXCEPT WHERE NOT