



B (1 : 1)
2ヶ所(等配)
2 PLACES
(AT EQUAL INTERVALS)

注記
NOTE

- 荒加工後焼入焼戻し 硬さ HB212～248
QUENCH AND TEMPER AFTER ROUGH MACHINING
HARDNESS HB212～248
- 油穴は十分に洗浄後盲栓の事
PLUG IN AFTER CLEANED OIL HOLE SUFFICIENTLY