

## Ultrasonic sensor






The following table shows the connections you need to make:

Ultrasonic Sensor HC-SR04	Arduino
vcc	5V
Trig	Pin 11
Echo	Pin 12
GND	GND



Pin No	Pin Name	Description
1	VCC	+5 v power supply Input Pin
2	GND	Ground (-) power supply Input Pin
3	DO	Digital Output Pin
4	AO	Analog Output Pin



## Pir sensor

