## WORKPLACE RISK ASSESSMENT SYSTEM PRINT RISK ASSESSMENT

Print | Close

## To export as PDF, Please follow the steps: 1. Right-click on the browser; 2. Select the print option and select LANDSCAPE layout; 3. Set the scale to 75% under more settings and save it as a PDF.

Risk Assessment Details ID: RA_EEE_79930 Rev No: 1						
User's School/ Department/ Student Activity Group:	School of Electrical & Electronic Engineering	Project Title:	E016 - A Particle Detector for Air Quality Monitoring			
Workplace:	School of Electrical & Electronic Engineering	Other workplace:	-			
Location:	Project Lab S2 B4-02	Conducted By:	HO KOK PIN(KHO017@e.ntu.edu.sg);CHUA JIAN MING(CHUA1000@e.ntu.edu.sg);XU JIE(E200152@e.ntu.edu.sg);JOE CHENG KIM WEI(E190168@e.ntu.edu.sg);CHUA BENG CHOON(CHUA0981@e.ntu.edu.sg);SRIVASTAV KANISHK(KANISHK002@e.ntu.edu.sg);DHUWARAGISH RAVICHANDRA KUMAR(DHUW0001@e.ntu.edu.sg)			
Approved By:	Chan Pak Kwong (EPKCHAN@ntu.edu.sg)	Submitted By/Submitted Date:	CHUA JIAN MING/24-Jan-22			
Approved Date:	24-Jan-22	Next Review Date:	23-Jan-25			
Status:	Approved	Comments:	It is fine for the assessment			

1. Hazard Identification					
1a.	1b.	1c.	1d.	1e.	2a.
No.	Work Activity	Hazard	Sub Hazard	Possible Accident/III Health & Person-at-Risk	Existing Risk (
1	Soldering of wires and circuit boards	Physical	Contact with heated surface	Burns/ scalds	Briefing by Lab before usage
		Physical	Others:Inhalation of Harmful Gases	Occupational asthma or respiratory illness	Solder Fume Al remove harmfu during the solds
2	Use of electrical equipment	Electrical	Contact with electrical energy	Electrocution	Briefing by Lab before usage
		Physical	Others:Sparks	Burns/ scalds	Use of low-volta devices to redu damage to com that might caus

3	Walking on wet floor	Physical	Slips, trips and falls hazard	Back injury	Warning to have
		Physical	Slips, trips and falls hazard	Sprains, strains	Wear non-slip s
4	Working with small fans (~5cm x 7cm)	Mechanical	Cut	Limbs injury	Design of guard prevent limbs e fan.
5	Operating hand tools	Mechanical	Cut	Limbs injury	Proper PPE usa
6	Testing of prototype with different air quality	Physical	Others:Testing of PM2.5/PM10/C02/Alcohol	Occupational asthma or respiratory illness	Testing the prot an open enviror good air ventila
		Physical	Fire	Burns/ scalds	Use of small ca mimic fire to tes prototype away highly combusti material. Bucket of water present during case of an eme