CARCHECK AGENT

CONDITION SCREENING REPORT

Inspection ID: insp_878231829a
Date: 2026-10-22 21:06 UTC

MANDATORY SCREENING DISCLAIMER: Screening tool only. Never claim certification or accident-free status. This automated report identifies possible cosmetic, paint, and panel alignment discrepancies from smartphone video. Always confirm all flagged items with an independent professional mechanic prior to purchase or settlement.

Vehicle: 2025 Honda Civic
Summary: Significant physical wear, panel misalignment, or paint differences detected.

35/100
Condition Score

VERIFIED
Trust Layer Integrity

Trust Layer Verification Details:
- Captured in-app via device camera stream.
- Video SHA-256 checksum verified against client computation.
- Single-use capture challenge successfully verified in-frame.
- Continuous video stream with no unexplained hard cuts.
- Vehicle identification and plates consistent throughout.
- Body color and vehicle appearance consistent across 360 walkaround.

Video SHA-256: `f3039a0dc54f1135e6f5929473d038799f3380eb303b732597083ca98a8aaa60`

Handover Mode: Baseline vs Return Comparison

Change Status	Item / Panel	Confidence	Alignment / Note
PRE-EXISTING	Scratch (front bumper)	86%	Pre-existing scratch on front bumper verified from baseline pickup inspection. (align: 99%)
PRE-EXISTING	Scratch (front bumper)	86%	Pre-existing scratch on front bumper verified from baseline pickup inspection. (align: 99%)
PRE-EXISTING	Scratch (front-left fender)	86%	Pre-existing scratch on front-left fender verified from baseline pickup inspection. (align: 100%)
PRE-EXISTING	Scratch (front-left fender)	86%	Pre-existing scratch on front-left fender verified from baseline pickup inspection. (align: 100%)
PRE-EXISTING	Scratch (left door)	86%	Pre-existing scratch on left door verified from baseline pickup inspection. (align: 99%)
PRE-EXISTING	Scratch (left door)	86%	Pre-existing scratch on left door verified from baseline pickup inspection. (align: 99%)
PRE-EXISTING	Scratch (rear-left quarter panel)	86%	Pre-existing scratch on rear-left quarter panel verified from baseline pickup inspection. (align: 100%)
PRE-EXISTING	Scratch (rear-left quarter panel)	86%	Pre-existing scratch on rear-left quarter panel verified from baseline pickup inspection. (align: 100%)
PRE-EXISTING	Scratch (rear bumper & boot)	86%	Pre-existing scratch on rear bumper & boot verified from baseline pickup inspection. (align: 100%)
PRE-EXISTING	Scratch (rear bumper & boot)	86%	Pre-existing scratch on rear bumper & boot verified from baseline pickup inspection. (align: 100%)

PRE-EXISTING	Scratch (rear-right quarter panel)	80%	Pre-existing scratch on rear-right quarter panel verified from baseline pickup inspection. (align: 100%)
PRE-EXISTING	Scratch (rear-right quarter panel)	80%	Pre-existing scratch on rear-right quarter panel verified from baseline pickup inspection. (align: 100%)
PRE-EXISTING	Scratch (right door)	80%	Pre-existing scratch on right door verified from baseline pickup inspection. (align: 99%)
PRE-EXISTING	Scratch (right door)	80%	Pre-existing scratch on right door verified from baseline pickup inspection. (align: 99%)
PRE-EXISTING	Scratch (front-right fender)	80%	Pre-existing scratch on front-right fender verified from baseline pickup inspection. (align: 100%)
PRE-EXISTING	Scratch (front-right fender)	80%	Pre-existing scratch on front-right fender verified from baseline pickup inspection. (align: 100%)

Flagged Findings (21)

ID	Type	Panel	Severity	Conf.	Agent Note
`fnd_33f3b79d`	Scratch	front bumper	Moderate	92%	Possible moderate scratch detected on front bumper (80% confidence). Reconciled by vision agent.
`fnd_63411682`	Scratch	front bumper	Moderate	92%	Possible moderate scratch detected on front bumper (80% confidence). Reconciled by vision agent.
`fnd_13c62ba1`	Scratch	front-left fender	Moderate	92%	Possible moderate scratch detected on front-left fender (80% confidence). Reconciled by vision agent.
`fnd_77c112ed`	Scratch	front-left fender	Moderate	92%	Possible moderate scratch detected on front-left fender (80% confidence). Reconciled by vision agent.
`fnd_e56ba200`	Scratch	left door	Moderate	92%	Possible moderate scratch detected on left door (80% confidence). Reconciled by vision agent.
`fnd_b082cb79`	Scratch	left door	Moderate	92%	Possible moderate scratch detected on left door (80% confidence). Reconciled by vision agent.
`fnd_a2fcd8fe`	Scratch	rear-left quarter panel	Moderate	92%	Possible moderate scratch detected on rear-left quarter panel (80% confidence). Reconciled by vision agent.
`fnd_b79075f2`	Scratch	rear-left quarter panel	Moderate	92%	Possible moderate scratch detected on rear-left quarter panel (80% confidence). Reconciled by vision agent.
`fnd_37b59e5b`	Scratch	rear bumper & boot	Moderate	92%	Possible moderate scratch detected on rear bumper & boot (80% confidence). Reconciled by vision agent.

fnd_44d2e32a	Scratch	rear bumper & boot	Moderate	92%	Possible moderate scratch detected on rear bumper & boot (80% confidence). Reconciled by vision agent.
fnd_cfefbba1	Scratch	rear-right quarter panel	Moderate	80%	Possible moderate scratch detected on rear-right quarter panel (80% confidence).
fnd_f074e941	Scratch	rear-right quarter panel	Moderate	80%	Possible moderate scratch detected on rear-right quarter panel (80% confidence).
fnd_b764d923	Scratch	right door	Moderate	80%	Possible moderate scratch detected on right door (80% confidence).
fnd_fab1fc31	Scratch	right door	Moderate	80%	Possible moderate scratch detected on right door (80% confidence).
fnd_3fcc288e	Scratch	front-right fender	Moderate	80%	Possible moderate scratch detected on front-right fender (80% confidence).
fnd_6ff0845b	Scratch	front-right fender	Moderate	80%	Possible moderate scratch detected on front-right fender (80% confidence).
fnd_27f3a448	Panel gap asymmetry	front	Moderate	88%	Panel gap asymmetry (18.46 mm) detected along front_seam.
fnd_15cc22db	Panel gap asymmetry	rear	Moderate	72%	Panel gap asymmetry (None mm) detected along rear_seam.
fnd_32b0790b	Tyre wear	tyre (left)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.
fnd_4cab3d43	Tyre wear	tyre (right)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.
fnd_83e84953	Tyre wear	tyre (rear)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.

Recommended Questions for Seller / Inspector

- [fnd_33f3b79d] What was the cause of the moderate scratch on the front bumper?
- [fnd_63411682] What was the cause of the moderate scratch on the front bumper?
- [fnd_13c62ba1] What was the cause of the moderate scratch on the front-left fender?
- [fnd_77c112ed] What was the cause of the moderate scratch on the front-left fender?
- [fnd_e56ba200] What was the cause of the moderate scratch on the left door?
- [fnd_b082cb79] What was the cause of the moderate scratch on the left door?
- [fnd_a2fcd8fe] What was the cause of the moderate scratch on the rear-left quarter panel?
- [fnd_b79075f2] What was the cause of the moderate scratch on the rear-left quarter panel?
- [fnd_37b59e5b] What was the cause of the moderate scratch on the rear bumper & boot?
- [fnd_44d2e32a] What was the cause of the moderate scratch on the rear bumper & boot?
- [fnd_cfefbba1] What was the cause of the moderate scratch on the rear-right quarter panel?
- [fnd_f074e941] What was the cause of the moderate scratch on the rear-right quarter panel?
- [fnd_b764d923] What was the cause of the moderate scratch on the right door?
- [fnd_fab1fc31] What was the cause of the moderate scratch on the right door?
- [fnd_3fcc288e] What was the cause of the moderate scratch on the front-right fender?
- [fnd_6ff0845b] What was the cause of the moderate scratch on the front-right fender?
- [fnd_27f3a448] Has the vehicle experienced any front/side collision impacting front alignment?
- [fnd_15cc22db] Has the vehicle experienced any front/side collision impacting rear alignment?

• [fnd_32b0790b] When were the tyres on the tyre (left) last replaced or aligned?
• [fnd_4cab3d43] When were the tyres on the tyre (right) last replaced or aligned?
• [fnd_83e84953] When were the tyres on the tyre (rear) last replaced or aligned?

Cryptographic Report Integrity (ECDSA P-256):
Report Digest (SHA-256): `ab5a8fb51e11b8ec9dd6c4cf3461558d5854717998dbbfe21c4c1ef33086cba6`
ECDSA Signature: `MEYCIQC8tWP/4wqFH9Rf5tgt8C7qpopr5siPJE+QcEbaCf1N...`
Public Verification URL: /reports/insp_878231829a/verify