

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

PROPERTY & LOSS SUMMARY

FIELD	VALUE
Policy Number	PROP-2026-88231
Insured	James Okafor
Property Address	142 Birchwood Lane, Riverton
Date of Loss	06/10/2026
Cause of Loss	Wind-driven rain / roof penetration
Probable Total Loss	\$41,850.00

CAUSE OF LOSS VERIFICATION

☒ Wind	☐ Hail
☐ Fire	☐ Water - Plumbing
☒ Water - Weather	☐ Theft
☐ Vandalism	☐ Other

ROOM INSPECTION -- LIVING ROOM

FIELD	READING
Room / Area	Living Room
Moisture Reading	25%
Damage Type	Water intrusion
Photo Reference	IMG-2001.jpg through IMG-2003.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- KITCHEN

FIELD	READING
Room / Area	Kitchen
Moisture Reading	32%
Damage Type	Drywall staining
Photo Reference	IMG-2002.jpg through IMG-2004.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- PRIMARY BEDROOM

FIELD	READING
Room / Area	Primary Bedroom
Moisture Reading	39%
Damage Type	Mold growth (visible)
Photo Reference	IMG-2003.jpg through IMG-2005.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BEDROOM 2

FIELD	READING
Room / Area	Bedroom 2
Moisture Reading	46%
Damage Type	Flooring buckling
Photo Reference	IMG-2004.jpg through IMG-2006.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BATHROOM

FIELD	READING
Room / Area	Bathroom
Moisture Reading	53%
Damage Type	Insulation saturation
Photo Reference	IMG-2005.jpg through IMG-2007.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BASEMENT -- UTILITY

FIELD	READING
Room / Area	Basement -- Utility
Moisture Reading	20%
Damage Type	Structural warping
Photo Reference	IMG-2006.jpg through IMG-2008.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BASEMENT -- STORAGE

FIELD	READING
Room / Area	Basement -- Storage
Moisture Reading	27%
Damage Type	Ceiling sag
Photo Reference	IMG-2007.jpg through IMG-2009.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- ATTIC

FIELD	READING
Room / Area	Attic
Moisture Reading	34%
Damage Type	Electrical exposure risk
Photo Reference	IMG-2008.jpg through IMG-2010.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- GARAGE

FIELD	READING
Room / Area	Garage
Moisture Reading	41%
Damage Type	Water intrusion
Photo Reference	IMG-2009.jpg through IMG-2011.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- EXTERIOR -- ROOF

FIELD	READING
Room / Area	Exterior -- Roof
Moisture Reading	48%
Damage Type	Drywall staining
Photo Reference	IMG-2010.jpg through IMG-2012.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- EXTERIOR -- SIDING

FIELD	READING
Room / Area	Exterior -- Siding
Moisture Reading	55%
Damage Type	Mold growth (visible)
Photo Reference	IMG-2011.jpg through IMG-2013.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- CRAWL SPACE

FIELD	READING
Room / Area	Crawl Space
Moisture Reading	22%
Damage Type	Flooring buckling
Photo Reference	IMG-2012.jpg through IMG-2014.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- LIVING ROOM

FIELD	READING
Room / Area	Living Room
Moisture Reading	29%
Damage Type	Insulation saturation
Photo Reference	IMG-2013.jpg through IMG-2015.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- KITCHEN

FIELD	READING
Room / Area	Kitchen
Moisture Reading	36%
Damage Type	Structural warping
Photo Reference	IMG-2014.jpg through IMG-2016.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- PRIMARY BEDROOM

FIELD	READING
Room / Area	Primary Bedroom
Moisture Reading	43%
Damage Type	Ceiling sag
Photo Reference	IMG-2015.jpg through IMG-2017.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BEDROOM 2

FIELD	READING
Room / Area	Bedroom 2
Moisture Reading	50%
Damage Type	Electrical exposure risk
Photo Reference	IMG-2016.jpg through IMG-2018.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BATHROOM

FIELD	READING
Room / Area	Bathroom
Moisture Reading	57%
Damage Type	Water intrusion
Photo Reference	IMG-2017.jpg through IMG-2019.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BASEMENT -- UTILITY

FIELD	READING
Room / Area	Basement -- Utility
Moisture Reading	24%
Damage Type	Drywall staining
Photo Reference	IMG-2018.jpg through IMG-2020.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BASEMENT -- STORAGE

FIELD	READING
Room / Area	Basement -- Storage
Moisture Reading	31%
Damage Type	Mold growth (visible)
Photo Reference	IMG-2019.jpg through IMG-2021.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- ATTIC

FIELD	READING
Room / Area	Attic
Moisture Reading	38%
Damage Type	Flooring buckling
Photo Reference	IMG-2020.jpg through IMG-2022.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- GARAGE

FIELD	READING
Room / Area	Garage
Moisture Reading	45%
Damage Type	Insulation saturation
Photo Reference	IMG-2021.jpg through IMG-2023.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- EXTERIOR -- ROOF

FIELD	READING
Room / Area	Exterior -- Roof
Moisture Reading	52%
Damage Type	Structural warping
Photo Reference	IMG-2022.jpg through IMG-2024.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- EXTERIOR -- SIDING

FIELD	READING
Room / Area	Exterior -- Siding
Moisture Reading	19%
Damage Type	Ceiling sag
Photo Reference	IMG-2023.jpg through IMG-2025.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- CRAWL SPACE

FIELD	READING
Room / Area	Crawl Space
Moisture Reading	26%
Damage Type	Electrical exposure risk
Photo Reference	IMG-2024.jpg through IMG-2026.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- LIVING ROOM

FIELD	READING
Room / Area	Living Room
Moisture Reading	33%
Damage Type	Water intrusion
Photo Reference	IMG-2025.jpg through IMG-2027.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- KITCHEN

FIELD	READING
Room / Area	Kitchen
Moisture Reading	40%
Damage Type	Drywall staining
Photo Reference	IMG-2026.jpg through IMG-2028.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- PRIMARY BEDROOM

FIELD	READING
Room / Area	Primary Bedroom
Moisture Reading	47%
Damage Type	Mold growth (visible)
Photo Reference	IMG-2027.jpg through IMG-2029.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75

TO: Claims Adjuster - Meridian Mutual
FROM: Field Inspector K. Alders, Lic. #IL-4471
SUBJECT: Claim CLM-2026-41207 - Policy PROP-2026-88231 - Property Loss Inspection Report

ROOM INSPECTION -- BEDROOM 2

FIELD	READING
Room / Area	Bedroom 2
Moisture Reading	54%
Damage Type	Flooring buckling
Photo Reference	IMG-2028.jpg through IMG-2030.jpg
Recommended Action	Remove and replace affected material; dry out and monitor 72 hrs.

ITEMIZED CONTRACTOR ESTIMATE -- CONTINUED

LINE ITEM	QTY	UNIT COST	TOTAL
Drywall removal & replacement	45 sq ft	\$6.20	\$279.00
Insulation replacement	60 sq ft	\$2.85	\$171.00
Flooring - subfloor repair	30 sq ft	\$9.10	\$273.00
Mold remediation labor	4 hrs	\$85.00	\$340.00
Dehumidifier rental (per day)	3 days	\$45.00	\$135.00
Paint & finish	45 sq ft	\$1.75	\$78.75