

INCIDENT #INC-2024-0831 - SEVERITY: P1

Date : 2024-08-31 | 03:14 IST

Duration : 47 minutes

Affected : 3 branch sites (Mumbai, Pune, Nashik) - total 840 users

Root Cause : BGP session between PE-MUM-01 and CE-PUN-02 dropped due to interface flap on GigabitEthernet0/0/1 caused by a faulty SFP module.

Timeline:

- 03:14 - NMS alert: BGP neighbor down on PE-MUM-01.
- 03:17 - NOC Tier-1 acknowledged, began ping tests.
- 03:22 - Physical layer checked; CRC errors found on Gi0/0/1.
- 03:31 - Tier-2 escalated; SFP identified as faulty.
- 03:58 - Spare SFP installed; BGP session re-established.
- 04:01 - All traffic restored. Incident closed.

Resolution: Replace SFP-10G-SR on PE-MUM-01 Gi0/0/1 with spare unit.

Prevention: Quarterly SFP health checks added to maintenance schedule.

Lessons Learned: Keep 2x spare SFPs of each type in every PoP.

INCIDENT #INC-2024-1115 - SEVERITY: P2

Date : 2024-11-15 | 14:32 IST

Duration : 2 hours 18 minutes

Affected : SD-WAN overlay - 12 branch sites, partial connectivity

Root Cause : vSmart controller certificate expired. BFD sessions dropped across all WAN Edge routers causing policy push failure.

Timeline:

- 14:32 - Users report slow internet; vManage shows 'Control Down'.
- 14:40 - NOC checks vSmart; certificate expiry error in logs.
- 15:10 - New certificate generated via Cisco PKI portal.
- 15:55 - Certificate pushed to vSmart; control connections restored.
- 16:50 - All BFD sessions re-established. Incident closed.

Resolution: Renew vSmart certificate, restart orchestration services.

Prevention: Certificate expiry monitoring added to Zabbix with 30-day alert.

Lessons Learned: vSmart and vBond certificates must be tracked in CMDB.

INCIDENT #INC-2025-0203 - SEVERITY: P1

Date : 2025-02-03 | 22:55 IST

Duration : 1 hour 12 minutes

Affected : Core MPLS backbone - 100% traffic loss on Delhi-Bangalore link

Root Cause : RSVP-TE tunnel misconfiguration after emergency change. Explicit route configured with wrong next-hop IP causing black-hole routing.

Timeline:

ISRO NOC COPILOT - INCIDENT REPORT ARCHIVE 2024-2025

22:55 - NMS: MPLS tunnel TR-DEL-BLR-01 down, traffic rerouting.

23:02 - Backup tunnel TR-DEL-BLR-02 also failed. Full outage.

23:15 - Change log reviewed; recent TE config change identified.

23:28 - Rollback executed; original tunnel config restored.

23:47 - Tunnel restored. Traffic confirmed via NetFlow.

00:07 - Incident closed.

Resolution: Rollback RSVP-TE explicit route to previous configuration.

Prevention: TE configuration changes now require pre-implementation lab test.

Lessons Learned: Emergency changes still need peer review before applying.

INCIDENT #INC-2025-0419 - SEVERITY: P3

Date : 2025-04-19 | 09:10 IST

Duration : 3 hours 40 minutes

Affected : QoS policy mismatch - VoIP degradation at 4 branches

Root Cause : SD-WAN application-aware routing policy pushed incorrect DSCP markings after vManage template update, causing VoIP traffic to use Best Effort queue.

Timeline:

09:10 - Helpdesk tickets: voice quality poor at HYD/CHN/BLR/KOC branches.

09:45 - NOC confirmed VoIP DSCP EF marking missing post template push.

10:30 - Cisco TAC engaged for vManage template rollback assistance.

12:50 - Correct QoS template re-applied. VoIP quality restored.

Resolution: Rollback SD-WAN QoS policy template to version 2.1.3.

Prevention: QoS template changes to be validated in lab before production push.