
Observer

Wen Yu

Object of observer

(1) prediction


$$\widehat{y}(k+1) = f_1[u(k+1), y(k), \Theta_1]$$



(2) filter (analysis of system)


$$\widehat{y}(k) = f_2[u(k), y(k), \Theta_2]$$

 $y(k) = \overline{y}(k) + \varsigma(k)$



(3) output feedback

$$u(k) = K\widehat{x}(k) = f_3[u(k), y(k), \Theta_3]$$



Conditions for building observer

- (1) The plant is observable
- (2) Input/output are known
- (3) The plant is known (generally)

Linear observer

$$\begin{cases} \dot{x} = Ax + Bu \\ y = Cx \end{cases}$$

The solution for x is

$$x(t) = \phi(t, t_0) x(t_0) + \int_{t_0}^{t} \phi(t, \tau) Bu(\tau) d\tau, \quad \phi(t, t_0) = e^{A(t - t_0)}$$

$$y(t) = C\phi(t, t_0) x(t_0) + C \int_{t_0}^{t} \phi(t, \tau) Bu(\tau) d\tau$$

where ϕ is state transition matrix of $\dot{x} = Ax$.

If $x\left(t_{0}\right)$ is known, $A \rightarrow \phi\left(t,t_{0}\right)$, $B,\,C,\,u\left(t\right)$ are known, $x\left(t\right)$ can be calculated.

If $x(t_0)$ is unknown,

$$C\phi(t, t_0) x(t_0) = y(t) - C \int_{t_0}^t \phi(t, \tau) Bu(\tau) d\tau$$

$$x(t_0) = (C\phi)^{-1} \left[y - C \int_{t_0}^t \phi Bu d\tau \right]$$

$$= f(A, B, C, y, u)$$
(1)

Theorem 1 If and only if $[C\phi(t,t_0)]^{-1}$ exist (has n linear independent column on (t,t_0)), the linear system is observable.

Proof. Multiply $\phi^T C^T$ and integrate from t_0 to t_1 in (1)

$$\left(\int_{t_0}^{t_1} \phi^T C^T C \phi dt\right) x(t_0) = \left[\int_{t_0}^{t_1} (C\phi)^T C \phi dt\right] x(t_0) = V(t_0, t_1) x$$

If all columns of $C\phi$ are linear independent on $[t_0, t_1]$, $V(t_0, t_1)$ is non-singular, so

$$x(t_0) = V^{-1}(t_0, t_1) \int_{t_0}^{t_1} (C\phi)^T \left[y - C \int_{t_0}^t \phi B u d\tau \right] dt$$

For time-invariance case

 $V = \begin{bmatrix} C, CA, \cdots CA^{n-1} \end{bmatrix}^T$, if rank(V) = n, the linear system is observable.

Linear Observer 5

Example 1 Linear system

$$\begin{cases} \dot{x} = \begin{bmatrix} 1 & 0 \\ 0 & 1 \end{bmatrix} x + \begin{bmatrix} 1 \\ 0 \end{bmatrix} u \\ y = \begin{bmatrix} 1 & 0 \end{bmatrix} x \end{cases}$$

 $V = [C, CA] = \begin{bmatrix} 1 & 0 \\ 1 & 0 \end{bmatrix}$, rank(V) = 1, it is not observable. Because

$$y = x_1$$

 $\dot{x}_1 = x_1, \quad \dot{x}_2 = x_2$

we cannot find a relation between y and x_2 . But if $A = \begin{bmatrix} 1 & 1 \\ 0 & 1 \end{bmatrix}$,

 $V = \begin{bmatrix} 1 & 0 \\ 1 & 1 \end{bmatrix}$, rank(V) = 2, it is observable, because

$$y = x_1$$

 $\dot{x}_1 = x_1 + x_2, \quad \dot{x}_2 = x_2$

There exist a relation between y and x_2 .

Luenberger observer

observer=(copy of plant)+(modification term).

For linear plant

$$\begin{cases} \dot{x} = Ax + Bu \\ y = Cx \end{cases} \quad x(t_0) = a$$

Control Automático, CINVESTAV-IPN

Luenberger observer

$$\begin{cases}
\widehat{x} = A\widehat{x} + Bu + L(y - \widehat{y}) & \widehat{x}(t_0) = b \\
\widehat{y} = C\widehat{x}
\end{cases}$$

$$x(0) \qquad x(k) \qquad x(k)$$

Luenberger observer is used only for the initial condition error

Asymptotic observer

observer error is $\widetilde{x} = x - \widehat{x}$,

$$\overset{\cdot}{\widetilde{x}} = (A - LC)\,\widetilde{x}$$

If we select L such that (A-LC) is asymptotic stable (the eigenvalues of (A-LC) are negative), $\lim_{t\to\infty}\widetilde{x}=0$.

Theorem 2 If (A, C) is observable ($rank([C, CA, \cdots CA^{n-1}]^T) = n$), then all eigenvalues of (A - LC) can be arbitrarily assigned by select L.

Example 2

$$\begin{cases} \dot{x} = \begin{bmatrix} 1 & 1 \\ 0 & 1 \end{bmatrix} x + \begin{bmatrix} 1 \\ 0 \end{bmatrix} u \\ y = \begin{bmatrix} 1 & 0 \end{bmatrix} x \end{cases}$$

it is observable.

$$\begin{cases} \hat{x} = \begin{bmatrix} 1 & 1 \\ 0 & 1 \end{bmatrix} \hat{x} + \begin{bmatrix} 1 \\ 0 \end{bmatrix} u + \begin{bmatrix} l_1 \\ l_2 \end{bmatrix} (y - \hat{y}) & \hat{x}(0) = [1, 1] \\ \hat{y} = \begin{bmatrix} 1 & 0 \end{bmatrix} \hat{x} & \hat{x}(0) = [1, 1] \end{cases}$$

$$A - LC = \begin{bmatrix} 1 - l_1 & 1 \\ -l_2 & 1 \end{bmatrix}$$
, eigenvalues satisfy $[sI - (A - LC)] = 0 = s^2 + (l_1 - 2)s + 1 - l_1 + l_2$, we hope $s_1 = -1$, $s_1 = -2$, $L = \begin{bmatrix} 5 \\ 6 \end{bmatrix}$

Reduced order observer

If the linear system can be transformed into

$$\begin{cases} \dot{x} = \begin{bmatrix} A_{11} & A_{12} \\ A_{21} & A_{22} \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix} + \begin{bmatrix} B_1 \\ B_2 \end{bmatrix} u \\ y = \begin{bmatrix} I & 0 \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix}$$

i.e.

$$\begin{cases} \dot{x}_1 = A_{11}x_2 + A_{12}x_2 + B_1u \\ \dot{x}_2 = A_{22}x_2 + A_{21}x_1 + B_2u \\ y = x_1 \end{cases}$$

Control Automático, CINVESTAV-IPN

Linear Observer 8

Define new output

$$\dot{w} = \dot{y} - A_{11}x_2 - B_1 u$$

The plant becomes

$$\begin{cases} \dot{x}_2 = A_{22}x_2 + (A_{21}x_1 + B_2u) \\ w = A_{12}x_2 \end{cases}$$

The reduced order observer

$$\begin{cases} \hat{x}_2 = A_{22}\hat{x}_2 + \overline{U} + L(w - \widehat{w}) \\ \hat{w} = A_{12}\hat{x}_2 \end{cases}$$

where $\overline{U} = A_{21}x_1 + B_2u$. The observability of (A, C) is the same as the observability of (A_{22}, A_{12}) .

Canonical form of observer

Theorem 3 *If* n *dimensional linear time-invariant system is observable, then is can be transformed into*

$$\begin{cases}
\frac{\cdot}{\overline{x}} = \begin{bmatrix} 0 & \cdots & 0 & -\alpha_n \\ 1 & & \vdots & \vdots \\ & \ddots & 0 \\ 0 & & 1 & -\alpha_1 \end{bmatrix} \overline{x} + \begin{bmatrix} \beta_1 \\ \vdots \\ \beta_n \end{bmatrix} u \\
y = \begin{bmatrix} 0 & 1 \end{bmatrix} \overline{x}$$

where α_i and β_i satisfy

$$G(s) = C (sI - A)^{-1} B = \frac{\beta_n s^{n-1} + \dots + \beta_1}{s^n + \alpha_1 s^{n-1} + \dots + \alpha_n}$$

Output feedback

Linear plant

$$\begin{cases} \dot{x} = Ax + Bu \\ y = Cx \end{cases}$$

we hope the state feedback control is u = Kx. If the plant is known, but x is not measurable, Luenberger observer is used

$$\begin{cases} \hat{x} = A\hat{x} + Bu + L(y - \hat{y}) & \hat{x}(t_0) = b \\ \hat{y} = C\hat{x} \end{cases}$$

The control is $u = K\widehat{x}$.

We have two problems: 1) observer

$$\overset{\cdot}{\widetilde{x}} = (A - LC)\,\widetilde{x}$$

2) feedback control

$$\dot{x} = Ax + BK\hat{x} = Ax + BK(x - \tilde{x}) = Ax + BKx - BK\tilde{x}$$

Combine them together

$$\begin{bmatrix} \dot{x} \\ \dot{\tilde{x}} \end{bmatrix} = \begin{bmatrix} A + BK & -BK \\ 0 & A - LC \end{bmatrix} \begin{bmatrix} x \\ \tilde{x} \end{bmatrix}$$

The stability of the system is depended on (A+BK) and (A-LC).

1) we can select K such that (A+BK) is stable if (A,B) is controllable

Linear Observer 10

1) we can select L such that (A-LC) is stable if (A,C) is observable

It is separation property (principle) for linear system