

Inspection Output (IOR)

Generated on 2024.February.01 09:20

Report Filters

Assets All, and including items not linked to any asset.

Results All

Inspection Information

Inspection Name	8615 Petrogas Standard Inspection	Operator(s)	PETROGAS WEST, LLC (39663)	Plan Submitted	01/10/2024
Status	LOCKED	Lead	Derek Norwood	Plan Approval	01/16/2024 by Dennis Ritter
Start Year	2023	Team Members	David Cullom, Lex Vinsel, Anthony Dorrough, Scott Anderson, Jason Hoxit	All Activity Start	12/11/2023
System Type	HL	Observer(s)	John Trier, Marina Rathbun	All Activity End	12/21/2023
Protocol Set ID	WA.HL.2022.02	Supervisor	Dennis Ritter	Inspection Submitted	02/01/2024
		Director	Scott Rukke	Inspection Approval	02/01/2024 by Scott Rukke

Inspection Summary

Inspection Scope and Summary

Staff from the Washington Utilities and Transportation Commission conducted a Standard Inspection of Petrogas West LLC (Petrogas) from December 11 to December 21, 2023. This inspection included a records review and inspection of the pipeline facilities. The inspection indicates five probable violations as noted in the enclosed report.

The inspection was conducted at Petrogas in Ferndale, WA.

Facilities visited and Total AFOD

Staff visited the Petrogas facility in Ferndale, WA where records were reviewed and a field inspection of the propane and butane pipelines and breakout tanks T1 and T2 were inspected.

Total AFODs: 3 days

Summary of Significant Findings

(DO NOT Discuss Enforcement options)

There are five probable violations as noted in the inspection report. The violations were all concerning record keeping issues, most of the missing records were from 2022. Missing records included pressure test record for a 12-inch pipeline to breakout tank T2, in-service inspection records, firefighting equipment inspection records, valve maintenance records and Public Awareness stakeholder communication records.

Primary Operator contacts and/or participants

Michael Evans

Operations Supervisor

Cody Treavor

Operations Manager

Operator executive contact and mailing address for any official correspondence

Derek Vallee

Midstream Operations

Petrogas Energy Corp. Suite 3900

Bow Valley SQ2

205 5th Ave SW

Calgary, Alberta, Canada

Scope (Assets)

#	Short Name	Long Name	Asset Type	Asset IDs	Excluded Topics	Planned	Required	Total Inspected	Required % Complete
1.	86236 (1580)	Petrogas	unit	86236	Pump Stations Offshore GOM Crosses Nav. CO2 Biofuels Reg Rural Gather Rural Low Stress Abandoned	173	173	173	100.0%

1. Percent completion excludes unanswered questions planned as "always observe".

Plans

#	Plan Assets	Focus Directives	Involved Groups/Subgroups	Qst Type(s)	Extent Notes
1.	86236 (1580)	WUTC Standard Inspection	AR, CR, DC, TDC, EP, FS, IM, MO, PD, RPT, SRN, TD, TQ, 114, P, R, O, S GENERIC		Detail --

Plan Implementations

Activity #	Name	SMART Act#	Start Date	End Date	Focus Directives	Involved Groups/Subgroups	Assets	Qst Type(s)	Planned	Required	Inspected	Total	Required % Complete
1.	Records	--	12/11/2023	-- 12/21/2023		all planned questions	all assets	R	124	124	124	124	100.0%
2.	Field	--	12/11/2023	-- 12/12/2023		all planned questions	all assets	O	49	49	49	49	100.0%

1. Since questions may be implemented in multiple activities, but answered only once, questions may be represented more than once in this table.

2. Percent completion excludes unanswered questions planned as "always observe".

Forms

No.	Entity	Form Name	Status	Date Completed	Activity Name	Asset
1.	Attendance List	Records	COMPLETED	01/04/2024	Records	86236 (1580)

Results (all values, 173 results)

201 (instead of 173) results are listed due to re-presentation of questions in more than one sub-group.

CR.CRMRR: Roles and Responsibilities

1. Question Result, ID, References NA, CR.CRMRR.PRESSLIMITS.O, 195.446(b)(2)

Question Text *Are controllers aware of the current MOPs of all pipeline segments for which they are responsible, and have they been assigned the responsibility to maintain those pipelines at or below the MOP?*
Assets Covered 86236 (1580)
Result Notes No control room

CR.LD: Leak Detection (Non-CPM)

2. Question Result, ID, References NA, CR.LD.EVAL.R, 195.444(a) (195.444(b), 195.134(a), 195.134(b),)
Question Text *Do records show that the operator evaluated the capability of its leak detection system to protect the public, property, and the environment and modified as necessary?*
Assets Covered 86236 (1580)
Result Notes Letter from UTC in 2011 stating control room requirements are N/A
3. Question Result, ID, References NA, CR.LD.LDSYSTEM.R, 195.404(c) (195.134(b), 195.444(b))
Question Text *Do records demonstrate the operator's leak detection system is performing within the system design requirements?*
Assets Covered 86236 (1580)
Result Notes Letter from UTC in 2011 stating control room requirements are N/A
4. Question Result, ID, References NA, CR.LD.LDTRAINING.R, 195.507(a) (195.507(b))
Question Text *Do records show that pipeline controllers are trained to recognize leaks using the chosen leak detection method/system?*
Assets Covered 86236 (1580)
Result Notes Letter from UTC in 2011 stating control room requirements are N/A
5. Question Result, ID, References NA, CR.LD.LDTRAINING.O, 195.505
Question Text *Are the Pipeline Controllers trained to recognize leaks?*
Assets Covered 86236 (1580)
Result Notes No control room
6. Question Result, ID, References NA, CR.LD.ALARMDISPLAY.O, 195.444(b)
Question Text *Are the Leak Detection alarms adequate?*
Assets Covered 86236 (1580)
Result Notes No control room
7. Question Result, ID, References NA, CR.LD.LDSTEST.R, 195.134(b) (195.444(b))
Question Text *Have leak detection system testing records and results been retained/available and indicate adequate results?*
Assets Covered 86236 (1580)
Result Notes Letter from UTC in 2011 stating control room requirements are N/A
8. Question Result, ID, References NA, CR.LD.LDSINSTRUMENT.R, 195.444(b) (195.446(j))
Question Text *Do records indicate the calibration of field instrumentation used in the leak detection system was performed?*
Assets Covered 86236 (1580)
Result Notes Letter from UTC in 2011 stating control room requirements are N/A

DC.CO: Construction

9. Question Result, ID, References Sat, DC.CO.ASMECONSTRUCTION.R,
Question Text *Do records indicate that new pipelines are designed and constructed in accordance with ASME B31.4?*
Assets Covered 86236 (1580)

Result Notes Valve replaced in September 2022, included installation of appurtenances which required two welds

Valve is flanged connection

Reviewed equipment sheet and material listed as ASME B31.3

10. Question Result, ID, Sat, DC.CO.VALVEPROTECT.O, 195.258(a)
References

Question Text *Are valves accessible to authorized employees and protected from damage or tampering?*

Assets Covered 86236 (1580)

Result Notes All valves are either secured within the facility or in a locked, fenced enclosure

11. Question Result, ID, Sat, DC.CO.VALVELOCATION.R, 195.266(f) (195.260(a), 195.260(b), 195.260(c), 195.260(d),
References 195.260(e), 195.260(f))

Question Text *Do records indicate that valves are located as specified by 195.260?*

Assets Covered 86236 (1580)

Result Notes Butane line from P66 has MOV 660 within fence, emergency valve and ESD valve from BP

Propane also has MOV from P66 within fence, emergency valve

12. Question Result, ID, Sat, DC.CO.VALVELOCATION.O, 195.260(a) (195.260(b), 195.260(c), 195.260(d), 195.260(e),
References 195.260(f))

Question Text *Are valves located as specified by 195.260?*

Assets Covered 86236 (1580)

Result Notes Valve at entrance to facility and on inlet and outlet to breakout tanks

13. Question Result, ID, Sat, DC.CO.RECORDS.R, 195.266(a) (195.266(b), 195.266(c), 195.266(d), 195.266(e), 195.266(f))
References

Question Text *Do records indicate that construction records are being maintained for the life of each pipeline?*

Assets Covered 86236 (1580)

Result Notes Reviewed construction and hydrotest records for 6"-LH-668-B10 (Butane, Bidirectional, P66, DOT)

DC.COCMP: Construction - Pump Stations

14. Question Result, ID, Sat, DC.COCMP.VALVEPROTECT.O, 195.258(a)
References

Question Text *Are valves accessible to authorized employees and protected from damage or tampering?*

Assets Covered 86236 (1580)

Result Notes All valves are either secured within the facility or in a locked, fenced enclosure

15. Question Result, ID, NA, DC.COCMP.VALVELOCATION.R, 195.266(f) (195.260(a), 195.260(b), 195.260(c), 195.260(d),
References 195.260(e), 195.260(f))

Question Text *Do records indicate that valves are located as specified by 195.260?*

Assets Covered 86236 (1580)

Result Notes No pump stations

16. Question Result, ID, Sat, DC.COCMP.VALVELOCATION.O, 195.260(a) (195.260(b), 195.260(c), 195.260(d), 195.260(e),
References 195.260(f))

Question Text *Are valves located as specified by 195.260?*

Assets Covered 86236 (1580)

Result Notes Valve at entrance to facility and on inlet and outlet to breakout tanks

17. Question Result, ID, NA, DC.COCMP.PMPPROPERTY.R,
References

Question Text *Do records indicate that pump stations are designed, sited, and constructed consistent with the requirements in WAC 480-75-380?*

Assets Covered 86236 (1580)

Result Notes No pump stations

DC.WELDINS: Construction Weld Inspection

18. Question Result, ID, **Sat**, DC.WELDINS.WELDINSPECT.R, 195.228(a) (195.228(b), 195.234) (also presented in: References TDC.WELDINS)
Question Text *Do records indicate welds are inspected to ensure compliance with the requirements of 195.228?*
Assets Covered **86236 (1580)**
Result Notes **Two welds completed on Butane line**

both passed visual inspection
19. Question Result, ID, **NA**, DC.WELDINS.WELDINSPECT.O, 195.228(a) (195.228(b), 195.234) (also presented in: References TDC.WELDINS)
Question Text *Are welds being inspected to ensure compliance with the requirements of 195.228?*
Assets Covered **86236 (1580)**
Result Notes **No such activity/condition was observed during the inspection.**
20. Question Result, ID, **Sat**, DC.WELDINS.WELDNDT.R, 195.234(a) (195.234(b), 195.234(c)) (also presented in: References TDC.WELDINS)
Question Text *Do records indicate adequate nondestructive testing and determination of standards of acceptability?*
Assets Covered **86236 (1580)**
Result Notes **UT performed by Haskell, 2 welds UT tested, both passed**

Radiograph completed by Acuren on 6/8/22

Both welds accepted
21. Question Result, ID, **NA**, DC.WELDINS.WELDNDT.O, 195.234(a) (195.234(b), 195.234(c)) (also presented in: References TDC.WELDINS)
Question Text *Are NDT activities performed in accordance with approved processes?*
Assets Covered **86236 (1580)**
Result Notes **No such activity/condition was observed during the inspection.**
22. Question Result, ID, **Sat**, DC.WELDINS.GIRTHWELDNDT.R, 195.234(d) (195.266(a)) (also presented in: TDC.WELDINS)
Question Text *Do records demonstrate at least 10% of all welds that are made by each welder during each welding day are nondestructively tested over the entire circumference of the welds or that more welds are tested per the operator's own procedures?*
Assets Covered **86236 (1580)**
Result Notes **UT performed by Haskell, 2 welds UT tested, both passed**

Radiograph completed by Acuren on 6/8/22

Both welds accepted
23. Question Result, ID, **Sat**, DC.WELDINS.GIRTHWELDNDTLOCATE.R, 195.234(e) (195.266(a)) (also presented in: References TDC.WELDINS)
Question Text *Do records demonstrate all girth welds installed each day in selected locations specified in 195.234(e) are nondestructively tested over their entire circumference?*
Assets Covered **86236 (1580)**
Result Notes **UT performed by Haskell, 2 welds UT tested, both passed**

Radiograph completed by Acuren on 6/8/22

Both welds accepted
24. Question Result, ID, **Sat**, DC.WELDINS.GIRTHWELDNDTUSED.R, 195.234(f) (195.266(a)) (also presented in: References TDC.WELDINS)
Question Text *Do records demonstrate that when installing used pipe, 100% of the old girth welds are nondestructively tested?*
Assets Covered **86236 (1580)**

Result Notes UT performed by Haskell, 2 welds UT tested, both passed

Radiograph completed by Acuren on 6/8/22

Both welds accepted

25. Question Result, ID, **Sat, DC.WELDINSR.GIRTHWELDNDTTIEIN.R, 195.234(g) (195.266(a))** (also presented in: References **TDC.WELDINSR**)

Question Text *Do records demonstrate 100% of the girth welds have been nondestructively tested at selected pipe tie-ins?*

Assets Covered **86236 (1580)**

Result Notes UT performed by Haskell, 2 welds UT tested, both passed

Radiograph completed by Acuren on 6/8/22

Both welds accepted

DC.WELDERQUAL: Construction Welder Qualification

26. Question Result, ID, **Sat, DC.WELDERQUAL.WELDERQUAL.R, 195.222(a) (195.222(b), 195.214(a), API-1104 Section 6, ASME Boiler & Pressure Vessel Code Section IX)** (also presented in: **TDC.WELDERQUAL**)

Question Text *Do records indicate that welders are qualified in accordance with API-1104 or the ASME Boiler & Pressure Vessel Code?*

Assets Covered **86236 (1580)**

Result Notes **Haskell Corp Welder performed welding in 2022**

Rajesh Jadhav

SMAW exp 11/11/22

DC.WELDPROCEDURE: Construction Welding Procedures

27. Question Result, ID, **Sat, DC.WELDPROCEDURE.WELDPROCEDURE.R, 195.214(b)** (also presented in: **TDC.WELDPROCEDURE**)

Question Text *Do records indicate welding procedures and qualifying tests recorded in detail?*

Assets Covered **86236 (1580)**

Result Notes **Two welds performed by Haskell**

WPS No. 16GTA SMA 11-3 LT

PQR 16 GTA SMA

DC.DN: Design

28. Question Result, ID, **Sat, DC.DN.VALVE.O, 195.116(f) (195.116(b), 195.116(c), 195.116(e))**

Question Text *Do pipeline system valves meet the requirements of 195.116?*

Assets Covered **86236 (1580)**

Result Notes **Valves seem to be consistent with operating conditions at the plant**

Petrogas has had no issues with valves in the past

29. Question Result, ID, **Sat, DC.DN.LDDESIGN.R, 195.134(a) (195.134(b), 195.134(c), 195.444(a), 195.444(b), 195.444(c))**

Question Text *Do records indicate evaluation of the leak detection system for its capability to protect the public, property, and the environment?*

Assets Covered **86236 (1580)**

Result Notes Leak detection on BP pipelines, would notify Petrogas in event of leak

Within the plant there are pressure sensors and LEL monitors that are monitored by control room and would alarm in low flow or pressure conditions

30. Question Result, ID, References **NA, DC.DN.LDDESIGN.O, 195.134(b) (195.134(c), 195.444(b), 195.444(c))**
Question Text *Does the leak detection system perform to the system design requirements?*
Assets Covered **86236 (1580)**
Result Notes **No such activity/condition was observed during the inspection.**

DC.MO: Maintenance and Operations

31. Question Result, ID, References **NA, DC.MO.SAFETY.O, 195.422(a) (195.402(c)(14))**
Question Text *Are pipeline maintenance construction and testing activities performed safely and in accordance with procedures to prevent damage to persons and property?*
Assets Covered **86236 (1580)**
Result Notes **No such activity/condition was observed during the inspection.**
32. Question Result, ID, References **NA, DC.MO.MOVE.R,**
Question Text *Do records indicate that a study was prepared before moving or lowering a hazardous liquid pipeline?*
Assets Covered **86236 (1580)**
Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**
33. Question Result, ID, References **NA, DC.MO.MOVE.O, 195.424(a) (195.424(b), 195.424(c))**
Question Text *Does the operator perform pipeline movements in accordance with 195.424?*
Assets Covered **86236 (1580)**
Result Notes **No such activity/condition was observed during the inspection.**

DC.PT: Pressure Testing

34. Question Result, ID, References **Unsat, DC.PT.PRESSTEST.R, 195.310 (195.305(b))**
Question Text *Are pressure test records available and adequate?*
Assets Covered **86236 (1580)**
Result Issue Summary **Petrogas was not able to produce records showing that line 12"-L/GH-258-B60 had been pressure tested in accordance with the requirements of 49 CFR Part 195 Subpart E.**
Standard Issues **B2 (Moderate or small impact/limited occurrence) : 195.310(a) : Records documenting pressure testing are not available.**
Result Notes **Reviewed pressure test records for 6" butane line to tank T2**

Petrogas could not provide pressure test records for 12" line into butane tank T2

12"-L/GH-258-B60
35. Question Result, ID, References **NA, DC.PT.PRESSTEST.O, 195.302(a) (195.304, 195.305(a), 195.305(b), 195.306(a), 195.306(b), 195.306(c), 195.306(d), 195.307(a), 195.307(b), 195.307(c), 195.307(d), 195.307(e), 195.308)**
Question Text *Is pressure testing being adequately conducted?*
Assets Covered **86236 (1580)**
Result Notes **No such activity/condition was observed during the inspection.**
36. Question Result, ID, References **NA, DC.PT.PRESSTESTTIEIN.R, 195.308**
Question Text *Do records indicate pipe associated with tie-ins has been pressure tested?*
Assets Covered **86236 (1580)**
Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**

37. Question Result, ID, References **NA, DC.PT.PRESSTESTRPT.R,**

Question Text *Do records indicate the operator filed a report with the commission at least 45 days prior to pressure testing when increasing the MOP of the pipeline?*

Assets Covered **86236 (1580)**

Result Notes **No pressure testing during this inspection interval (2020-2023)**

DC.TQOQ: Training and Qualification (OQ)

38. Question Result, ID, References **Sat, DC.TQOQ.OQCONTRACTOR.R, 195.505(b) (Operators OQ program manual)**

Question Text *Are qualification records for contractor personnel maintained?*

Assets Covered **86236 (1580)**

Result Notes **Reviewed qualifications from TEAM for UT Inspections performed throughout the facility**

39. Question Result, ID, References **NA, DC.TQOQ.OQCONTRACTOR.O, 195.505(b) (Operators OQ program manual)**

Question Text *Do selected contractor individuals performing covered tasks demonstrate adequate skills and knowledge?*

Assets Covered **86236 (1580)**

Result Notes **No such activity/condition was observed during the inspection.**

40. Question Result, ID, References **Sat, DC.TQOQ.RECORDS.R, 195.505(b) (Operators OQ program manual)**

Question Text *Does the operator maintain qualification records for operator personnel?*

Assets Covered **86236 (1580)**

Result Notes **Reviewed qualification of operators and maintenance techs**

41. Question Result, ID, References **Sat, DC.TQOQ.OQPLAN.O, 195.505(b) (Operators OQ program manual)**

Question Text *Do selected operator individuals performing covered tasks demonstrate adequate skills and knowledge?*

Assets Covered **86236 (1580)**

Result Notes **All personnel seemed knowledgeable and demonstrated adequate skills**

42. Question Result, ID, References **NA, DC.TQOQ.EXCAVATE.R, 195.505(b) (ADB-06-01)**

Question Text *Do records demonstrate individuals who oversee marking, trenching and backfilling operations are qualified?*

Assets Covered **86236 (1580)**

Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**

43. Question Result, ID, References **NA, DC.TQOQ.EXCAVATE.O, 195.505(b) (ADB-06-01)**

Question Text *Do selected individuals who oversee marking, trenching and backfilling operations demonstrate adequate skills and knowledge?*

Assets Covered **86236 (1580)**

Result Notes **No such activity/condition was observed during the inspection.**

TDC.650REGS: New API 650 Tanks - Part 195 Requirements

44. Question Result, ID, References **NA, TDC.650REGS.TANKSPEC.R, 195.132(b)(3) (API Std 650)**

Question Text *Do the design records and drawings indicate new aboveground atmospheric breakout tanks are designed and constructed to the specifications required by 195.132(b)(3)?*

Assets Covered **86236 (1580)**

Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**

45. Question Result, ID, References **NA, TDC.650REGS.REPAIRSPEC.R, 195.205(b)(1) (API Std 650, API Std 653)**

Question Text *Do records indicate breakout tanks were repaired, altered, or reconstructed in compliance with the requirements of 195.205(b)(1)?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

46. Question Result, ID, NA, TDC.650REGS.CPDESIGN.O, 195.565 (195.563(d), API RP 651, Section 6.3.4, API RP 651, Section 6.3.5, API RP 651, Section 7.2.1)

Question Text *Do field observations confirm new breakout tanks have cathodic protection installed in accordance with 195.565?*

Assets Covered 86236 (1580)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

47. Question Result, ID, NA, TDC.650REGS.OVERFILLPROT.R, 195.428(c) (195.404(a), 195.404(b), 195.404(c), 195.132(b)(3), API Std 2350, Section 4.6, API Std 2350, Section 4.8)

Question Text *Do records indicate product level alarm devices were installed and set to alarm at a level above the normal and overfill protection levels in accordance with 195.428(c)?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

48. Question Result, ID, NA, TDC.650REGS.OVERFILLPROT.O, 195.428(c) (195.132(b)(3), API Std 2350, Section 4.6, API Std 2350, Section 4.8)

Question Text *Do field observations confirm product level alarm devices were installed and set to alarm at the design levels (level above the normal and overfill protection levels) in accordance with 195.428(c)?*

Assets Covered 86236 (1580)

Result Notes No such activity/condition was observed during the inspection.

49. Question Result, ID, Sat, TDC.650REGS.FIREEQUIP.O, 195.430(a) (195.430(b), 195.430(c))

Question Text *Do field observations confirm the necessary firefighting equipment to respond to emergencies is included at the facility's breakout tank area?*

Assets Covered 86236 (1580)

Result Notes Fire monitors, hydrants and extinguishers throughout the plant

EP.ERL: Emergency Response Liquids

50. Question Result, ID, Sat, EP.ERL.LIAISON.R, 195.402(a) (195.402(c)(12), 195.440(c), API RP 1162 Section 4.4) (also presented in: PD.PA)

Question Text *Do records indicate that liaison has been established and maintained with appropriate fire, police, public officials, and utility owners?*

Assets Covered 86236 (1580)

Result Notes Tony Clizbe coordinates with Fire District 7, verifying that information in CAD is accurate

Environmental Specialist, attends LEPC meetings monthly

51. Question Result, ID, NA, EP.ERL.NOTICES.R, 195.402(a) (195.402(e)(1))

Question Text *Do records indicate receiving, identifying, classifying and communicating notices of events requiring immediate response in accordance with procedures?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

52. Question Result, ID, Sat, EP.ERL.AUTHORITIES.R, 195.402(a) (195.402(e)(7))

Question Text *Do records indicate that notifications were made to fire, police, and other appropriate public officials of hazardous liquid emergencies and were coordinated with preplanned and actual responses (including additional precautions necessary for an emergency involving HVLs)?*

Assets Covered 86236 (1580)

Result Notes Tested autodialer system with Instrumentation techs

53. Question Result, ID, NA, EP.ERL.POSTEVTNREVIEW.R, 195.402(a) (195.402(e)(7), 195.402(e)(9))

Question Text *Do records indicate post-accident reviews of employee activities were performed to determine whether the procedures were effective in each emergency and take corrective action where deficiencies are found?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

54. Question Result, ID, References Sat, EP.ERL.COMMSYS.R, 195.408(b)

Question Text *Do records indicate emergency communication system(s) use was as required?*

Assets Covered 86236 (1580)

Result Notes Radio system for emergency communication

Emergency reporting number at the plat

Emergency contacts updated when changes take place

FCC Radio Certificate

EP.ETR: Emergency Training of Personnel

55. Question Result, ID, References Sat, EP.ETR.TRAINING.R, 195.403(a)

Question Text *Do records indicate the operator provided training to its emergency response personnel as required?*

Assets Covered 86236 (1580)

Result Notes 24 hour HAZWOPER with 8 hour refreshers annually

Annual drills

Red Tag Drills on a monthly basis based on AOCs (11 Drills)

Response to loss of power, hydrocarbon detector alarm, etc

56. Question Result, ID, References Sat, EP.ETR.TRAININGREVIEW.R, 195.403(b)

Question Text *Have annual reviews of the emergency response training program been conducted and appropriate changes made as necessary to ensure it is effective?*

Assets Covered 86236 (1580)

Result Notes Annual review of AOC Manual

Reviewed records for 2020-2023

Rev 3 adopted in 2022

57. Question Result, ID, References Sat, EP.ETR.TRAININGSUPERVISE.R, 195.403(c)

Question Text *Do records indicate verification that supervisors are knowledgeable of emergency response procedures for which they are responsible?*

Assets Covered 86236 (1580)

Result Notes Supervisor reviews and signs off on annual review of emergency procedures

Supervisors oversee AOC Drills

8 hours complete 8 hour refresher annually

58. Question Result, ID, References NA, EP.ETR.TRAININGSUPERVISE.O, 195.403(c)

Question Text *Do emergency response supervisors demonstrate adequate skills and knowledge?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

FS.TSAPIINSPECT: Tanks and Storage - Inspection

59. Question Result, ID, References **NA, FS.TSAPIINSPECT.BOINSPECTION.R, 195.404(c)(3) (195.432(a))**
 Question Text *Do records document that breakout tanks that are not steel atmospheric or low pressure tanks or HVL steel tanks built according to API 2510 have been inspected at the proper interval and that deficiencies found during inspections have been corrected?*
 Assets Covered **86236 (1580)**
 Result Notes **Both Tanks are steel low pressure tanks**
60. Question Result, ID, References **Unsat, FS.TSAPIINSPECT.BOINSRVCINSP.R, 195.404(c)(3) (195.432(b))**
 Question Text *Do records document that steel atmospheric or low pressure breakout tanks have received routine in-service inspections at the required intervals and that deficiencies found during inspections have been documented?*
 Assets Covered **86236 (1580)**
 Result Issue Summary **API 653 Section 6.3 requires that routine in-service inspections are completed at intervals consistent with conditions at the particular site, but shall not exceed one month. Petrogas indicated that in-service inspections on the propane and butane breakout tanks are completed monthly however they could not provide records for 2022.**
 Standard Issues **B1 (Moderate or small impact/widespread occurrence) : 195.432(b) : No record/documentation.**
 Result Notes **Petrogas conducts monthly in-service inspections on the propane and butane breakout tanks. Petrogas provided records for inspections completed in 2023 but no records were available for 2022.**
61. Question Result, ID, References **Sat, FS.TSAPIINSPECT.BOEXTINSP.R, 195.404(c)(3) (195.432(b))**
 Question Text *Do records document that steel atmospheric or low pressure breakout tanks have received external inspections at the required intervals and that deficiencies documented during inspections have been corrected within a reasonable time frame?*
 Assets Covered **86236 (1580)**
 Result Notes **External inspections completed in conjunction with UT Testing**

UT Testing completed every 5 years

T1 done in 2020 and roof done in 2023

T2 done in 2018
62. Question Result, ID, References **Sat, FS.TSAPIINSPECT.BOEXTUTINSP.R, 195.404(c)(3) (195.432(b))**
 Question Text *Do records document that steel atmospheric or low pressure breakout tanks have received ultrasonic thickness inspections at the required intervals and that deficiencies found during inspections have been documented?*
 Assets Covered **86236 (1580)**
 Result Notes **UT Testing completed every 5 years**

T1 done in 2020 and roof done in 2023

T2 done in 2018
63. Question Result, ID, References **NA, FS.TSAPIINSPECT.BOINTINSP.R, 195.404(c)(3) (195.432(b))**
 Question Text *Do records document that steel atmospheric or low pressure breakout tanks have received formal internal inspections at the required intervals and that deficiencies found during inspections have been documented?*
 Assets Covered **86236 (1580)**
 Result Notes **No such requirement existed in the scope of inspection review.**

T1 last done in 2015

T2 last done in 2018

20 year inspections

64. Question Result, ID, References **NA, FS.TSAPIINSPECT.BOEXTINSPAPI2510.R, 195.404(c)(3) (195.432(c))**
 Question Text *Do records document that in-service pressure steel aboveground breakout tanks built to API Standard 2510 have received visual external inspections at the required intervals and that deficiencies found have been corrected?*
 Assets Covered **86236 (1580)**
 Result Notes **No API 2510 tanks**
65. Question Result, ID, References **NA, FS.TSAPIINSPECT.BOINTINSPAPI2510.R, 195.404(c)(3) (195.432(c))**
 Question Text *Do records document that in-service pressure steel aboveground breakout tanks built to API Standard 2510 received internal inspections at the required intervals and that deficiencies found have been corrected?*
 Assets Covered **86236 (1580)**
 Result Notes **No API 2510 tanks**

FS.FG: Facilities General

66. Question Result, ID, References **Sat, FS.FG.FACPROTECT.O, 195.436** (also presented in: PD.SN)
 Question Text *Are facilities adequately protected from vandalism and unauthorized entry?*
 Assets Covered **86236 (1580)**
 Result Notes **Valve site and facility are within locked gates**
Plant facility and breakout tanks are secured by locked gate and security guard
67. Question Result, ID, References **Sat, FS.FG.IGNITION.O, 195.438** (also presented in: PD.SN)
 Question Text *Is there signage that prohibits smoking and open flames around pump stations, launchers and receivers, breakout tank areas, or other applicable facilities?*
 Assets Covered **86236 (1580)**
 Result Notes **Signage throughout the facility looked good**
68. Question Result, ID, References **Sat, FS.FG.SIGNAGE.O, 195.434** (also presented in: PD.SN)
 Question Text *Are there operator signs around each pumping station, breakout tank area, and other applicable facilities?*
 Assets Covered **86236 (1580)**
 Result Notes **Signage throughout the facility looked good**
69. Question Result, ID, References **Unsat, FS.FG.FIREPROT.R, 195.404(c)(3) (195.430(a), 195.430(b), 195.430(c))**
 Question Text *Are records of inspections of firefighting equipment adequate?*
 Assets Covered **86236 (1580)**
 Result Issue Summary **Operators are required to maintain adequate firefighting equipment at each breakout tank area and the equipment must be in proper operating condition at all times. Petrogas completes monthly inspections of their firefighting equipment including fire extinguishers and remote-operated fire monitors however not all records were available. Petrogas could not provide records for monthly inspections from calendar year 2022, January 2023, July 2023 and October 2023.**
 Standard Issues **C (Documentation/administrative - no significant impact) : 195.404(c)(3) : Records are not available to indicate firefighting equipment is maintained in proper operating conditions at all times.**
 Result Notes **Reviewed records for 2023**
Missing records for 2022 and Jan/July/Oct 2023
70. Question Result, ID, References **NA, FS.FG.FIREPROT.O, 195.430(a) (195.430(b), 195.430(c), 195.262(e))**
 Question Text *Has adequate fire protection equipment been installed at pump station/breakout tank areas and is it maintained properly?*
 Assets Covered **86236 (1580)**
 Result Notes **No such relevant facilities/equipment existed in the scope of inspection review.**

FS.TS: Tanks and Storage

71. Question Result, ID, References **Sat, FS.TS.PRVTSTHVLBO.R, 195.404(c)(3) (195.428(b))**
Question Text *Do records document testing and inspection of relief valves on HVL pressure breakout tanks at the required frequency?*
Assets Covered **86236 (1580)**
Result Notes **4 PSV and Vacuum breakers on Tank T2**

5 PSV/Vacuum Breakers and 2 PSVs on Tank T1

Maintenance performed every 5 years

T2 done on 1/14/23

T1 done in 2019
72. Question Result, ID, References **Sat, FS.TS.PRVTSTHVLBO.O, 195.428(a)**
Question Text *Do pressure control devices installed on HVL pressure breakout tanks appear to be in satisfactory mechanical condition and to be functioning properly?*
Assets Covered **86236 (1580)**
Result Notes **Pressure relief and vacuum breaker on both tanks**
73. Question Result, ID, References **Sat, FS.TS.OVERFILLBO.R, 195.404(c)(3) (195.428(a), 195.428(c), 195.428(d))**
Question Text *Do records document the inspection and testing of overfill protection devices on aboveground breakout tanks at the required interval? [Note: This question applies to both non-HVL and HVL pressure breakout tanks.]*
Assets Covered **86236 (1580)**
Result Notes **Overfill PSV on both breakout tanks are tested every 3 years**

T1 done 9/28/22

T2 done 6/8/21
74. Question Result, ID, References **NA, FS.TS.OVERFILLBO.O, 195.428(c)**
Question Text *Do selected overfill protection systems on aboveground breakout tanks that were constructed or significantly altered after October 2, 2000 function properly and are they in good mechanical condition? [Note: This question applies to both non-HVL and HVL pressure breakout tanks.]*
Assets Covered **86236 (1580)**
Result Notes **No such relevant facilities/equipment existed in the scope of inspection review.**
75. Question Result, ID, References **Sat, FS.TS.BOINSPECTION.O, 195.432(a) (195.432(b), 195.432(c), 195.401(b))** (also presented in: FS.TSAPIINSPECT)
Question Text *Is the condition of steel atmospheric or low pressure tanks acceptable?*
Assets Covered **86236 (1580)**
Result Notes **No signs of settling or tank movement, foundation looked good, no visible corrosion, insulation good**
76. Question Result, ID, References **Sat, FS.TS.IGNITIONBO.R, 195.404(c) (195.405(a))**
Question Text *Do records indicate protection against ignitions arising out of static electricity, lightning, and stray currents during operation and maintenance activities of aboveground breakout tanks?*
Assets Covered **86236 (1580)**
Result Notes **Everything is grounded, if there is lightning within six miles then all work is put on hold and employees shelter in place**

EOHS-102 Manual Section 12.5

General Safe Practices

77. Question Result, ID, References **NA, FS.TS.FLOATINGROOF.R, 195.404(c) (195.405(b))**
 Question Text *Do records indicate access/egress onto floating roofs of in-service aboveground breakout tanks to perform inspection, service, maintenance, or repair activities of in-service tanks is performed consistent with API Publication 2026?*
 Assets Covered **86236 (1580)**
 Result Notes **No floating roofs**
78. Question Result, ID, References **Sat, FS.TS.IMPOUNDBO.R, 195.404(c) (195.264(b))**
 Question Text *If a breakout tank first went into service after October 2, 2000 do records indicate it has an adequate impoundment?*
 Assets Covered **86236 (1580)**
 Result Notes **Both tanks have dikes around tanks and secondary containment basin nearby**
79. Question Result, ID, References **NA, FS.TS.IMPOUNDBO.O, 195.264(b)**
 Question Text *If a breakout tank first went into service after October 2, 2000 does it have an adequate impoundment?*
 Assets Covered **86236 (1580)**
 Result Notes **No such relevant facilities/equipment existed in the scope of inspection review.**
80. Question Result, ID, References **NA, FS.TS.VENTBO.R, 195.404(c) (195.264(d))**
 Question Text *Do records indicate that normal/emergency relief venting and pressure/vacuum-relieving devices installed on aboveground breakout tanks after October 2, 2000 are adequate?*
 Assets Covered **86236 (1580)**
 Result Notes **No devices installed after 2000**
81. Question Result, ID, References **NA, FS.TS.PRESSTESTBO.R, 195.310(a) (195.310(b), 195.307)**
 Question Text *Have aboveground breakout tanks been pressure tested to their corresponding API or ASME Standard or Specification and do pressure test records contain the required information?*
 Assets Covered **86236 (1580)**
 Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**

MO.LO: Liquid Pipeline Operations

82. Question Result, ID, References **Sat, MO.LO.OMMANUALREVIEW.R, 195.402(a)**
 Question Text *Do records indicate annual reviews of the written procedures in the manual were conducted as required?*
 Assets Covered **86236 (1580)**
 Result Notes **O&M Procedures reviewed annually by operations crews and verified by Cody**

Total 42 Procedures

Reviewed a sample of documents to verify annual review completed
83. Question Result, ID, References **Sat, MO.LO.OMHISTORY.R, 195.404(a) (195.404(c), 195.9, 195.402(c)(1))**
 Question Text *Do records indicate current maps and records of the pipeline system are maintained and made available as necessary?*
 Assets Covered **86236 (1580)**
 Result Notes **All documents and maps are hosted on internal SharePoint site**

All Petrogas employees have access to these records
84. Question Result, ID, References **Sat, MO.LO.OMEFFECTREVIEW.R, 195.402(a) (195.402(c)(13), 195.404(a))**
 Question Text *Do records indicate periodic review of the work done by operator personnel to determine the effectiveness of the procedures used in normal operation and maintenance and corrective action taken where deficiencies are found?*

Assets Covered 86236 (1580)

Result Notes LOTO procedures are reviewed for safety and effectiveness by a qualified field supervisor before the work is done

MO.LMOPP: Liquid Pipeline Overpressure Protection

85. Question Result, ID, References NA, MO.LMOPP.PRESSREGTEST.R, 195.404(c) (195.428(a)) (also presented in: FS.PS)

Question Text *Do records indicate inspection and testing of each overpressure safety device on its non-HVL pipelines at intervals not to exceed 15 months, but at least once each calendar year?*

Assets Covered 86236 (1580)

Result Notes Both pipelines are HVL lines

MO.LOMOP: Liquid Pipeline MOP

86. Question Result, ID, References Sat, MO.LOMOP.MOPDETERMINE.R, 195.402(c)(3) (195.406(a), 195.406(b), 195.302(b), 195.302(c))

Question Text *Do records indicate the maximum operating pressure was established in accordance with 195.406?*

Assets Covered 86236 (1580)

Result Notes Appendix C has MOP Calculations

MO.LMOPP: Liquid Pipeline Overpressure Protection

87. Question Result, ID, References Sat, MO.LMOPP.PRESSREGTESTHVL.R, 195.404(c) (195.428(a)) (also presented in: FS.PS)

Question Text *Do records indicate inspection and testing of each overpressure safety device on HVL pipelines at intervals not to exceed 7.5 months, but at least twice each calendar year?*

Assets Covered 86236 (1580)

Result Notes Reviewed 2022 and 2023 records, completed 4/19/22, 10/10/22, 4/12/23 and 09/2023

Petrogas removes and replaces all Thermal Reliefs every six months

88. Question Result, ID, References NA, MO.LMOPP.PRESSREGTEST.O, 195.428(a) (also presented in: FS.PS)

Question Text *Are inspections of overpressure safety devices adequate (including HVL lines)?*

Assets Covered 86236 (1580)

Result Notes No such activity/condition was observed during the inspection.

89. Question Result, ID, References NA, MO.LMOPP.LAUNCHRECVRELIEF.O, 195.426 (also presented in: FS.PS)

Question Text *Are launchers and receivers equipped with relief devices?*

Assets Covered 86236 (1580)

Result Notes No launcher/receiver on Petrogas lines

90. Question Result, ID, References Sat, MO.LMOPP.SURGEANALYSIS.R,

Question Text *Do records indicate that a surge analysis was completed to ensure that the surge pressure does not exceed one hundred ten percent of the MOP?*

Assets Covered 86236 (1580)

Result Notes PSVs installed to ensure they don't exceed 110% of MOP

MO.RW: ROW Markers, Patrols, Monitoring and Analysis

91. Question Result, ID, References Sat, MO.RW.PATROL.R, 195.412(a) (195.412(b)) (also presented in: PD.RW)

Question Text *Do records indicate ROW surface conditions and crossings under navigable waterways were inspected, and reporting and appropriate mitigation performed?*

Assets Covered 86236 (1580)

Result Notes Operator Rounds completed twice per day, one day and one night shift, checking pipe conditions, psv status, etc.

Checked a sample of records from Sept 2023 and Feb 2022

92. Question Result, ID, References Sat, MO.RW.ROWCONDITION.O, 195.412(a) (also presented in: PD.RW)

Question Text Are the ROW conditions acceptable for the type of patrolling used?

Assets Covered 86236 (1580)

Result Notes Most of the pipe is above ground, operators perform rounds twice per day

MO.ABNORMAL: Liquid Pipeline Abnormal Operations

93. Question Result, ID, References Sat, MO.ABNORMAL.ABNORMAL.R, 195.404(b) (195.402(d)(1))

Question Text Do records indicate operator's personnel responded to indications of abnormal operations as required by the written procedures?

Assets Covered 86236 (1580)

Result Notes MOV 650 on Butane line not functioning in April 2022, created temporary operating procedure

Used manual isolation valve and left MOV open

Valves at tank are also associated with ESDs so system still could have been shut down

Bay Valve worked on MOV

Bad Thrust Base, tested torque and made repairs

MO.RW: ROW Markers, Patrols, Monitoring and Analysis

94. Question Result, ID, References Sat, MO.RW.ROWMARKER.O, 195.410(a) (195.410(b), 195.410(c)) (also presented in: PD.RW)

Question Text Are line markers placed and maintained as required?

Assets Covered 86236 (1580)

Result Notes Markers at road crossing and on fences at above ground pipe

MO.LM: Liquid Pipeline Maintenance

95. Question Result, ID, References Unsat, MO.LM.VALVEMAINT.R, 195.404(c) (195.420(a), 195.420(b)) (also presented in: FS.VA)

Question Text Do records indicate each mainline valve was inspected as required?

Assets Covered 86236 (1580)

Result Issue Summary Petrogas completes mainline valve inspections to ensure each valve is functioning properly twice per year. Petrogas provided valve inspection records for 2023 but records for 2022 were not available.

Standard Issues B2 (Moderate or small impact/limited occurrence) : 195.420(b) : No record/documentation.

Result Notes MOVs tested from control room and in the field

Reviewed record from 11/29/2023, 3/16/23, 5/25/23

Need to see records for 2022, not in Maximo

No PM task before Altagas takeover

Valve closed after receipt of product

Visual completed on operator rounds but no "testing done twice per year

No records for 2022

96. Question Result, ID, References **Sat, MO.LM.VALVEMAIN.T.O, 195.420(a) (195.420(c))** (also presented in: FS.VA)
Question Text *Do the pipeline system valves appear to be in good working order and are they protected from unauthorized operation?*
Assets Covered **86236 (1580)**
Result Notes **All valves are either secured within the facility or in a locked, fenced enclosure**

MO.ABNORMAL: Liquid Pipeline Abnormal Operations

97. Question Result, ID, References **Sat, MO.ABNORMAL.ABNORMALREVIEW.R, 195.404(b) (195.402(d)(5))**
Question Text *Do records indicate post-event reviews of actions taken by operator personnel to determine the effectiveness of the abnormal operation procedures and whether corrective actions were taken where deficiencies were found?*
Assets Covered **86236 (1580)**
Result Notes **MOV 650 on Butane line not functioning in April 2022, created temporary operating procedure**

Used manual isolation valve and left MOV open

Valves at tank are also associated with ESDs so system still could have been shut down

Bay Valve worked on MOV

Bad Thrust Base, tested torque and made repairs

MO.RW: ROW Markers, Patrols, Monitoring and Analysis

98. Question Result, ID, References **Sat, MO.RW.DEPTHSURVEY.R,**
Question Text *Do records indicate that depth of cover surveys were completed as required by WAC 480-75-640?*
Assets Covered **86236 (1580)**
Result Notes **Capture on Operator Rounds Checklist**

Measure pipe depth at road crossing

~2' on N side

~4.2' on S side
99. Question Result, ID, References **NA, MO.RW.CHANGEINCLASS.R,**
Question Text *Do records indicate that the operator reevaluated class location periodically, but not less often than once every five years?*
Assets Covered **86236 (1580)**
Result Notes **No changes in class location**

MO.LC: Liquid Conversion

100. Question Result, ID, References **NA, MO.LC.CONVERSION.R, 195.5(c) (195.5(a), 195.5(d))**
Question Text *Do records indicate the process was followed for converting any pipelines into Part 195 service?*
Assets Covered **86236 (1580)**
Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**

MO.EW: Extreme Weather

101. Question Result, ID, References **NA, MO.EW.EXTWEATHERINSPIMPL.R, 195.404(c) (195.414(a), 195.414(b), 195.414(c), 195.414(d))**

Question Text *Do records indicate the operator conducted the required inspection following and extreme weather or natural disaster event?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

102. Question Result, ID, References NA, MO.EW.EXTWEATHERINSPSAFE.O, 195.414(d)

Question Text *Are the pipeline facilities that were affected by an extreme weather or natural disaster event back to a safe operating condition?*

Assets Covered 86236 (1580)

Result Notes No such activity/condition was observed during the inspection.

PD.DP: Damage Prevention

103. Question Result, ID, References Sat, PD.DP.PROGRAM.R, 195.442(a)

Question Text *Do records indicate the damage prevention program is being carried out as written?*

Assets Covered 86236 (1580)

104. Question Result, ID, References NA, PD.DP.NOTICETOEXCAVATOR.R,

Question Text *Do records indicate that the operator provides the required information to excavators who damage pipeline facilities?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

105. Question Result, ID, References NA, PD.DP.COMMISSIONREPORT.R,

Question Text *Do records indicate the operator reports to the commission when the operator or its contractor observes or becomes aware of the activities described in WAC 480-75-630(6)?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

106. Question Result, ID, References NA, PD.DP.LOCATES.R,

Question Text *Do records indicate hazardous liquid pipeline locations have been marked in the timeframe outlined in RCW 19.122?*

Assets Covered 86236 (1580)

Result Notes No work has been completed on Unick Rd requiring locates

PD.PA: Public Awareness

107. Question Result, ID, References Sat, PD.PA.AUDIENCEID.R, 195.440(d) (195.440(e), 195.440(f), API RP 1162 Section 2.2, API RP 1162 Section 3)

Question Text *Do records identify the individual stakeholders in the four affected stakeholder audience groups: (1) affected public, (2) emergency officials, (3) local public officials, and (4) excavators, as well as affected municipalities, school districts, businesses, and residents to which it sends public awareness materials and messages?*

Assets Covered 86236 (1580)

Documents Reviewed 1. -- -- -- PA Plan

Result Notes Stakeholders identified in Appendix B of the Public Awareness Plan

108. Question Result, ID, References Sat, PD.PA.EDUCATE.R, 195.440(d) (195.440(f))

Question Text *Did delivered messages specifically include provisions to educate the public, emergency officials, local public officials, and excavators on: (1) Use of a one-call notification system prior to excavation and other damage prevention activities; (2) Possible hazards associated with unintended releases from a hazardous liquid or carbon dioxide pipeline facility; (3) Physical indications of a possible release; (4) Steps to be taken for public safety in the event of a hazardous liquid or carbon dioxide pipeline release; and (5) Procedures to report such an event?*

Assets Covered 86236 (1580)
Result Notes Example of PA letter reviewed

Includes all required elements

109. Question Result, ID, References Sat, PD.PA.LOCATIONMESSAGE.R, 195.440(e) (195.440(f))
Question Text *Were messages developed and delivered to advise affected municipalities, school districts, businesses, and residents of pipeline facility location?*
Assets Covered 86236 (1580)
110. Question Result, ID, References Unsat, PD.PA.MESSAGEFREQUENCY.R, 195.440(c) (API RP 1162 Table 2-1)
Question Text *Did the delivery of materials and messages meet or exceed the baseline delivery frequencies specified in API RP 1162, Table 2-1?*
Assets Covered 86236 (1580)
Result Issue Summary Petrogas has specified in the Public Awareness Plan that they will distribute print communication to affected stakeholders on an annual basis. Petrogas was able to provide records that this material was sent on December 20, 2023 but no record was available for 2022.
Standard Issues B2 (Moderate or small impact/limited occurrence) : 195.440(c) : No record/documentation.
Result Notes Petrogas has specified that in the Public Awareness Plan that they will distribute print communication to affected stakeholders on an annual basis. Petrogas was able to provide a records that this material was sent on December 20, 2023 but no record was available for 2022.
111. Question Result, ID, References Sat, PD.PA.LANGUAGE.R, 195.440(g) (API RP 1162 Section 2.3.1)
Question Text *Were materials and messages developed and delivered in other languages commonly understood by a significant number and concentration of non-English speaking populations in the operator's areas?*
Assets Covered 86236 (1580)
Result Notes Fliers developed in Spanish and English
112. Question Result, ID, References Sat, PD.PA.EVALIMPL.R, 195.440(c) (195.440(i), API RP 1162 Section 8.3)
Question Text *Has an audit or review of the public awareness program implementation been performed annually since the program was developed?*
Assets Covered 86236 (1580)
Result Notes Plan reviewed annually, reviewed records in Intelex
113. Question Result, ID, References Sat, PD.PA.AUDITMETHODS.R, 195.440(c) (195.440(i), API RP 1162 Section 8.3)
Question Text *Was one or more of the three acceptable methods (i.e., internal assessment, 3rd-party contractor review, or regulatory inspections) used to complete the annual audit or review of the public awareness program implementation?*
Assets Covered 86236 (1580)
Result Notes Plan reviewed annually, reviewed records in Intelex
114. Question Result, ID, References NA, PD.PA.PROGRAMIMPROVE.R, 195.440(c) (API RP 1162 Section 8.3)
Question Text *Were changes made to improve the program and/or the implementation process based on the results and findings of the annual audit(s)?*
Assets Covered 86236 (1580)
Result Notes No such event occurred, or condition existed, in the scope of inspection review.
115. Question Result, ID, References NA, PD.PA.EVALEFFECTIVENESS.R, 195.440(c) (API RP 1162 Sections 8.4)
Question Text *Have effectiveness evaluation(s) of the program been performed for all stakeholder groups in all notification areas along all systems covered by the program?*
Assets Covered 86236 (1580)
Result Notes No such event occurred, or condition existed, in the scope of inspection review.
116. Question Result, ID, References NA, PD.PA.MEASUREOUTREACH.R, 195.440(c) (API RP 1162 Section 8.4.1)
Question Text *In evaluating effectiveness, was actual program outreach for each stakeholder audience tracked?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

117. Question Result, ID, References NA, PD.PA.MEASUREUNDERSTANDABILITY.R, 195.440(c) (API RP 1162 Section 8.4.2)

Question Text *In evaluating program effectiveness, was the percentage of each stakeholder audience that understood and retained the key information from the messages determined?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

118. Question Result, ID, References NA, PD.PA.MEASUREBEHAVIOR.R, 195.440(c) (API RP 1162 Section 8.4.3)

Question Text *In evaluating program effectiveness, was evaluation made of whether appropriate preventive, response, and mitigative behaviors were understood and likely to be exhibited?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

119. Question Result, ID, References NA, PD.PA.MEASUREBOTTOM.R, 195.440(c) (API RP 1162 Section 8.4.4)

Question Text *Did the operator attempt to measure bottom-line results of the program by tracking third-party incidents and consequences including: (1) near misses, (2) excavation damages resulting in pipeline failures, (3) excavation damages that do not result in pipeline failures?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

120. Question Result, ID, References NA, PD.PA.CHANGES.R, 195.440(c) (API RP 1162 Section 2.7 (Step 12), API RP 1162 Section 8.5)

Question Text *Were needed changes and/or modifications to the program identified and documented based on the results and findings of the program effectiveness evaluations?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

RPT.RR: Regulatory Reporting (Traditional)

121. Question Result, ID, References Sat, RPT.RR.ANNUALREPORT.R, 195.49 (195.13(b), 195.15(b))

Question Text *Do the records indicate that complete and accurate Annual Reports have been submitted?*

Assets Covered 86236 (1580)

Result Notes Reviewed prior years annual reports, all info seems accurate

122. Question Result, ID, References NA, RPT.RR.GRAVITY.R, 195.49 (195.13(b))

Question Text *Do Annual Reports include applicable information for gravity lines?*

Assets Covered 86236 (1580)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

123. Question Result, ID, References NA, RPT.RR.REGONLYGATHER.R, 195.49 (195.15(b))

Question Text *Do Annual Reports include applicable information for regulated-only gathering lines?*

Assets Covered 86236 (1580)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

124. Question Result, ID, References NA, RPT.RR.ACCIDENTREPORT.R, 195.54(a) (195.50(a), 195.50(b), 195.50(c), 195.50(d), 195.50(e), 195.13(b), 195.15(b))

Question Text *Do records indicate the original accident reports were filed as required?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

125. Question Result, ID, References NA, RPT.RR.ACCIDENTREPORTSUPP.R, 195.54(b) (195.13(b), 195.15(b))

Question Text *Do records indicate accurate supplemental accident reports were filed and within the required timeframe?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

126. Question Result, ID, References NA, RPT.RR.IMMEDREPORT.R, 195.52(a) (195.52(b), 195.52(c), 195.52(d))

Question Text Do records indicate immediate notifications of accidents were made in accordance with 195.52?

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

127. Question Result, ID, References NA, RPT.RR.SRCR.R, 195.56(a) (195.55(a), 195.55(b), 195.56(b), 195.13(b), 195.15(b))

Question Text Do records indicate Safety-Related Condition Reports were filed as required?

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

128. Question Result, ID, References Sat, RPT.RR.NPMSANNUAL.R, 195.61(a) (195.61(b))

Question Text Do records indicate: NPMS submissions are completed each year, on or before June 15, representing all in service, idle and retired assets as of December 31 of the previous year, and if no modifications occurred an email to that effect was submitted?

Assets Covered 86236 (1580)

Result Notes Reviewed records for 2021 and 2022

No changes submitted in OSAVE

129. Question Result, ID, References NA, RPT.RR.PIPELINEMAPPING.R,

Question Text Do records indicate that accurate maps (or updates) are provided for pipelines operating over 250 PSIG to specifications developed by the commission and sufficient to meet the needs of first responders?

Assets Covered 86236 (1580)

Result Notes Not operating over 250 psig

130. Question Result, ID, References NA, RPT.RR.CONSTRUCTIONREPORT.R,

Question Text Do records indicate operator has reported all construction of new pipelines intended to operate at 20% SMYS or greater at least 45 days prior to construction?

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

131. Question Result, ID, References NA, RPT.RR.DIRTREPORTS.R,

Question Text Do records indicate that the operator has submitted reports of damage to the commission using the Damage Information Reporting Tool (DIRT) within 45 days?

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

TD.ATM: Atmospheric Corrosion

132. Question Result, ID, References Sat, TD.ATM.ATMCORRODEINSP.R, 195.589(c) (195.583(a), 195.583(b), 195.583(c))

Question Text Do records document inspection of aboveground pipe exposed to atmospheric corrosion?

Assets Covered 86236 (1580)

Result Notes Captured on Operator Round checklist which are completed twice per day

Reviewed a sample of forms from 2022 and 2023

Third party completes NDT and UT 20% of all piping every year

Third Party company is called TEAM

133. Question Result, ID, References **Sat, TD.ATM.ATMCORRODEINSP.O, 195.583(c) (195.581(a))**
Question Text *Is aboveground pipe that is exposed to atmospheric corrosion protected?*
Assets Covered **86236 (1580)**
Result Notes **All above ground pipe looked to be in good condition, no visible corrosion**

TD.CPBO: External Corrosion - Breakout Tank Cathodic Protection

134. Question Result, ID, References **NA, TD.CPBO.BO.R, 195.589(c) (195.573(d))**
Question Text *Do records adequately document when and how cathodic protection systems were inspected on breakout tanks?*
Assets Covered **86236 (1580)**
Result Notes **No CP on breakout tanks**

135. Question Result, ID, References **NA, TD.CPBO.BO.O, 195.573(d)**
Question Text *Are cathodic protection monitoring tests performed correctly on breakout tank bottoms?*
Assets Covered **86236 (1580)**
Result Notes **No CP on tanks**

136. Question Result, ID, References **NA, TD.CPBO.DEFICIENCYBO.R, 195.589(c) (195.573(e))**
Question Text *Do records document adequate operator actions taken to correct any identified deficiencies in breakout tank corrosion control?*
Assets Covered **86236 (1580)**
Result Notes **No CP on breakout tanks**

TD.CP: External Corrosion - Cathodic Protection

137. Question Result, ID, References **NA, TD.CP.NEWOPERATE.R, 195.589(c) (195.563(a))**
Question Text *Do records document when cathodic protection was operational on constructed, relocated, replaced, converted to service, or otherwise changed pipelines?*
Assets Covered **86236 (1580)**
Result Notes **No construction**

138. Question Result, ID, References **NA, TD.CP.UNPROTECT.R, 195.589(c) (195.573(b)(1), 195.573(b)(2))**
Question Text *Do records document the adequate re-evaluation of buried pipelines with no cathodic protection for areas of active corrosion?*
Assets Covered **86236 (1580)**
Result Notes **No unprotected lines**

139. Question Result, ID, References **Sat, TD.CP.ISOLATE.R, 195.589(c) (195.575(a), 195.575(b), 195.575(d))**
Question Text *Do records document adequate electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?*
Assets Covered **86236 (1580)**
Result Notes **Farwest Corrosion checks isolation flanges during annual survey**

Annual survey completed 11/21/23

140. Question Result, ID, References **NA, TD.CP.ISOLATE.O, 195.575(a) (195.575(b), 195.575(d))**
Question Text *Are measures performed to ensure electrical isolation of each buried or submerged pipeline from other metallic structures unless they electrically interconnect and cathodically protect the pipeline and the other structures as a single unit?*
Assets Covered **86236 (1580)**

Result Notes 3rd party CP technician not on site to perform testing

141. Question Result, ID, References NA, TD.CP.DEFICIENCY.R, 195.589(c) (195.573(e)) (also presented in: TD.CPMONITOR, TD.CPEXPOSED)

Question Text *Do records document adequate operator actions taken to correct any identified deficiencies in corrosion control?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

142. Question Result, ID, References Sat, TD.CP.MAPRECORD.R, 195.589(a) (195.589(b)) (also presented in: TD.CPMONITOR)

Question Text *Do maps and or records document cathodic protection system appurtenances that have been installed on pipelines that have been constructed, relocated, replaced, or otherwise changed or been converted to hazardous liquid service?*

Assets Covered 86236 (1580)

Result Notes Inspection by Farwest Corrosion documents all CP facilities on the system

Review Corrosion asset P&ID from Norton Corrosion

TD.CPMONITOR: External Corrosion - Cathodic Protection Monitoring

143. Question Result, ID, References NA, TD.CPMONITOR.TESTLEADINSTALL.R, 195.589(c) (195.567(b))

Question Text *Do records document that pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart H?*

Assets Covered 86236 (1580)

Result Notes No new installations

144. Question Result, ID, References NA, TD.CPMONITOR.TESTLEADINSTALL.O, 195.567(a) (195.567(b))

Question Text *Do pipelines with cathodic protection have electrical test leads installed in accordance with requirements of Subpart H?*

Assets Covered 86236 (1580)

Result Notes 3rd party CP technician not on site to perform testing

145. Question Result, ID, References Sat, TD.CPMONITOR.TESTLEADMAINT.R, 195.589(c) (195.567(c))

Question Text *Do records document that CP test lead wires have been properly maintained?*

Assets Covered 86236 (1580)

146. Question Result, ID, References NA, TD.CPMONITOR.TESTLEADMAINT.O, 195.567(c)

Question Text *Are CP test lead wires properly maintained?*

Assets Covered 86236 (1580)

Result Notes 3rd party CP technician not on site to perform testing

147. Question Result, ID, References NA, TD.CPMONITOR.MONITOR.O, 195.571

Question Text *Do the methods for taking CP monitoring readings allow for the application of appropriate CP monitoring criteria?*

Assets Covered 86236 (1580)

Result Notes 3rd party CP technician not on site to perform testing

148. Question Result, ID, References Sat, TD.CPMONITOR.TEST.R, 195.589(c) (195.573(a)(1))

Question Text *Do records adequately document required tests have been done on pipe that is cathodically protected?*

Assets Covered 86236 (1580)

Result Notes Reviewed annual survey for November 21, 2023 and October 27, 2022

Most reading were more negative than -850 mV

When a reading was low, Petrogas deferred to 100 mV shift with reference to their depolarized read from 2019

149. Question Result, ID, References **NA, TD.CPMONITOR.CIS.R, 195.589(c) (195.573(a)(2))**
Question Text *Do records document, when circumstances dictated a need for close interval surveys, dates of completed surveys, data from completed surveys and analysis of completed surveys?*
Assets Covered **86236 (1580)**
Result Notes **No such relevant facilities/equipment existed in the scope of inspection review.**
150. Question Result, ID, References **Sat, TD.CPMONITOR.CURRENTTEST.R, 195.589(c) (195.573(c))**
Question Text *Do records document adequate electrical checks of rectifiers, interference bonds, diodes, and reverse current switches and at the required intervals?*
Assets Covered **86236 (1580)**
Result Notes **Checked monthly, documented on paper in 2022 and moved to Maximo October 2022**

Volts, Amps and Rectifier condition documented monthly in Maximo and on paper

CP Tech from Farwest takes reading during annual survey
151. Question Result, ID, References **Sat, TD.CPMONITOR.CURRENTTEST.O, 195.573(c)**
Question Text *Are rectifiers, interference bonds, diodes, and reverse current switches properly maintained and are they functioning properly?*
Assets Covered **86236 (1580)**
Result Notes **One rectifier for DOT pipe, inspected monthly by operators, visual inspection noting volts and amps**

24 Volts, 7 Amps

C2 F1 Tap settings
152. Question Result, ID, References **Sat, TD.CPMONITOR.INTFRCURRENT.R, 195.589(c) (195.577(a))**
Question Text *Do records document that the operator has an effective program in place to minimize the detrimental effects of interference currents on their pipeline system, and is minimizing detrimental effects of interference currents from their CP systems on other underground metallic structures?*
Assets Covered **86236 (1580)**
Result Notes **Check for interference at isolation flanges during annual survey**

No concerns

TD.COAT: External Corrosion - Coatings

153. Question Result, ID, References **NA, TD.COAT.NEWPIPEINSPECT.R,**
Question Text *Do records indicate that the operator electrically inspected all new coated pipe using a holiday detector?*
Assets Covered **86236 (1580)**
Result Notes **No new pipe installed**
154. Question Result, ID, References **NA, TD.COAT.NEWPIPE.R, 195.589(c) (195.557(a), 195.559, 195.401(c))**
Question Text *Do records document that coatings for pipelines constructed, relocated, replaced, or otherwise changed meet the requirements of §195.559?*
Assets Covered **86236 (1580)**
Result Notes **No new pipe installed**
155. Question Result, ID, References **NA, TD.COAT.CONVERTPIPE.R, 195.589(c) (195.557(b), 195.559)**
Question Text *Do records document that pipelines that have been converted to liquid service and were constructed after the applicable date in 195.401(c) have external coating?*

Assets Covered 86236 (1580)

Result Notes No such relevant facilities/equipment existed in the scope of inspection review.

156. Question Result, ID, References NA, TD.COAT.COATAPPLY.O, 195.561(a) (195.561(b), 195.559(b), 195.252(b))

Question Text *Is protective coating adequately applied?*

Assets Covered 86236 (1580)

Result Notes No such activity/condition was observed during the inspection.

TD.CPEXPOSED: External Corrosion - Exposed Pipe

157. Question Result, ID, References NA, TD.CPEXPOSED.EXPOSEINSPECT.R, 195.589(c) (195.569)

Question Text *Do records document that exposed buried piping was adequately examined for corrosion and deteriorated coating?*

Assets Covered 86236 (1580)

Result Notes No pipe exposed

158. Question Result, ID, References NA, TD.CPEXPOSED.EXPOSEINSPECT.O, 195.569

Question Text *Verify that exposed buried piping is examined for corrosion and deteriorated coating.*

Assets Covered 86236 (1580)

Result Notes No such activity/condition was observed during the inspection.

159. Question Result, ID, References NA, TD.CPEXPOSED.EXTCORRODEREPAIR.R, 195.589(c) (195.585(a), 195.585(b))

Question Text *Do records document the repair or replacement of pipe that has been externally corroded to an extent that there is not sufficient remaining pipe wall strength?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

TD.ICP: Internal Corrosion - Preventive Measures

160. Question Result, ID, References NA, TD.ICP.INVESTREMED.R, 195.589(c) (195.579(a))

Question Text *Do records document investigation and mitigation of the corrosive effects of hazardous liquids or carbon dioxide being transported?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

161. Question Result, ID, References NA, TD.ICP.INHIBITOR.R, 195.589(c) (195.579(b)(1), 195.579(b)(2), 195.579(b)(3))

Question Text *Do records document that corrosion inhibitors have been used in sufficient quantity?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

162. Question Result, ID, References NA, TD.ICP.EXAMINE.R, 195.589(c) (195.579(c), 195.579(a))

Question Text *Do records document examination of removed pipe for evidence of internal corrosion?*

Assets Covered 86236 (1580)

Result Notes No removed pipe

163. Question Result, ID, References NA, TD.ICP.BOLINING.R, 195.589(c) (195.579(d))

Question Text *Do records document the adequate installation of breakout tank bottom linings?*

Assets Covered 86236 (1580)

Result Notes No linings installed during inspection period

TQ.PROT9: OQ Protocol 9

164. Question Result, ID, References **Sat, TQ.PROT9.TASKPERFORMANCE.O, 195.501(a) (195.509(a))**
 Question Text *Verify the qualified individuals performed the observed covered tasks in accordance with the operator's procedures or operator approved contractor procedures.*
 Assets Covered **86236 (1580)**
 Result Notes **OQs verified during the inspection**
165. Question Result, ID, References **Sat, TQ.PROT9.QUALIFICATIONSTATUS.O, 195.501(a) (195.509(a))**
 Question Text *Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.*
 Assets Covered **86236 (1580)**
 Result Notes **OQs verified during the inspection**
166. Question Result, ID, References **Sat, TQ.PROT9.AOCRECOG.O, 195.501(a) (195.509(a))**
 Question Text *Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.*
 Assets Covered **86236 (1580)**
 Result Notes **Discussed AOCs during tank visual inspections**
167. Question Result, ID, References **Sat, TQ.PROT9.VERIFYQUAL.O, 195.501(a) (195.509(a))**
 Question Text *Verify the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.*
 Assets Covered **86236 (1580)**
 Result Notes **OQs verified during the inspection**
168. Question Result, ID, References **NA, TQ.PROT9.CORRECTION.O, 195.501(a) (195.509(a))**
 Question Text *Have potential issues identified by the OQ plan inspection process been corrected at the operational level?*
 Assets Covered **86236 (1580)**
 Result Notes **No such event occurred, or condition existed, in the scope of inspection review.**

TQ.OQ: Operator Qualification

169. Question Result, ID, References **Sat, TQ.OQ.OQCONTRACTOR.R, 195.507(a) (195.507(b))**
 Question Text *Are adequate records containing the required elements maintained for contractor personnel?*
 Assets Covered **86236 (1580)**
 Result Notes **Reviewed qualifications for contractor personnel from TEAM who perform UT inspection throughout the facility**

API 570 Piping Inspector
170. Question Result, ID, References **Sat, TQ.OQ.RECORDS.R, 195.507(a) (195.507(b))**
 Question Text *Do records document the evaluation and qualifications of individuals performing covered tasks, and can the qualification of individuals performing covered tasks be verified?*
 Assets Covered **86236 (1580)**
 Result Notes **Reviewed a sample of OQs for Petrogas employees**

TQ.QU: Qualification of Personnel - Specific Requirements

171. Question Result, ID, References **Sat, TQ.QU.CORROSIONSUPERVISE.R, 195.589(c) (195.507(a), 195.507(b))** (also presented in: TD.CP)
 Question Text *Is qualification of supervisors in corrosion control procedures documented?*
 Assets Covered **86236 (1580)**

Result Notes Verified CP qualifications for Christopher Matthews from FarWest Corrosion

See Attached

TQ.QUOMCONST: Qualification of Personnel - Specific Requirements (O and M Construction)

172. Question Result, ID, References NA, TQ.QUOMCONST.INSPECTORQUAL.R, 195.204

Question Text *Do records indicate adequate qualification documentation for personnel who conduct pipe or pipeline system construction inspections? (TQ.QUOMCONST.INSPECTORQUAL.R) (detail)*

Assets Covered 86236 (1580)

Result Notes No construction completed

TQ.TROMCONST: Training of Personnel - O and M Construction

173. Question Result, ID, References NA, TQ.TROMCONST.NDT.R, 195.234(b)(2)

Question Text *Is training for personnel, who perform nondestructive testing of welds, documented and demonstrated?*

Assets Covered 86236 (1580)

Result Notes No NDT of DOT pipe

TDC.WELDPROCEDURE: New Tank Piping - Construction Welding Procedures (Re-Presented)

174. Question Result, ID, References Sat, DC.WELDPROCEDURE.WELDPROCEDURE.R, 195.214(b) (also presented in: DC.WELDPROCEDURE)

Question Text *Do records indicate welding procedures and qualifying tests recorded in detail?*

Assets Covered 86236 (1580)

Result Notes Two welds performed by Haskell

WPS No. 16GTA SMA 11-3 LT

PQR 16 GTA SMA

TDC.WELDERQUAL: New Tank Piping - Construction Welder Qualification (Re-Presented)

175. Question Result, ID, References Sat, DC.WELDERQUAL.WELDERQUAL.R, 195.222(a) (195.222(b), 195.214(a), API-1104 Section 6, ASME Boiler & Pressure Vessel Code Section IX) (also presented in: DC.WELDERQUAL)

Question Text *Do records indicate that welders are qualified in accordance with API-1104 or the ASME Boiler & Pressure Vessel Code?*

Assets Covered 86236 (1580)

Result Notes Haskell Corp Welder performed welding in 2022

Rajesh Jadhav

SMAW exp 11/11/22

TDC.WELDINSPECTION: New Tank Piping - Construction Weld Inspection (Re-Presented)

176. Question Result, ID, References Sat, DC.WELDINSPECTION.WELDINSPECTION.R, 195.228(a) (195.228(b), 195.234) (also presented in: DC.WELDINSPECTION)

Question Text *Do records indicate welds are inspected to ensure compliance with the requirements of 195.228?*

Assets Covered 86236 (1580)

Result Notes Two welds completed on Butane line

both passed visual inspection

177. Question Result, ID, **NA**, DC.WELDINSPECT.O, 195.228(a) (195.228(b), 195.234) (also presented in: References DC.WELDINSPECT.O)
Question Text *Are welds being inspected to ensure compliance with the requirements of 195.228?*
Assets Covered **86236 (1580)**
Result Notes **No such activity/condition was observed during the inspection.**
178. Question Result, ID, **Sat**, DC.WELDINSPECT.WELDNDT.R, 195.234(a) (195.234(b), 195.234(c)) (also presented in: References DC.WELDINSPECT.WELDNDT.R)
Question Text *Do records indicate adequate nondestructive testing and determination of standards of acceptability?*
Assets Covered **86236 (1580)**
Result Notes **UT performed by Haskell, 2 welds UT tested, both passed**

Radiograph completed by Acuren on 6/8/22

Both welds accepted
179. Question Result, ID, **NA**, DC.WELDINSPECT.WELDNDT.O, 195.234(a) (195.234(b), 195.234(c)) (also presented in: DC.WELDINSPECT.WELDNDT.O)
Question Text *Are NDT activities performed in accordance with approved processes?*
Assets Covered **86236 (1580)**
Result Notes **No such activity/condition was observed during the inspection.**
180. Question Result, ID, **Sat**, DC.WELDINSPECT.GIRTHWELDNDT.R, 195.234(d) (195.266(a)) (also presented in: DC.WELDINSPECT.GIRTHWELDNDT.R)
Question Text *Do records demonstrate at least 10% of all welds that are made by each welder during each welding day are nondestructively tested over the entire circumference of the welds or that more welds are tested per the operator's own procedures?*
Assets Covered **86236 (1580)**
Result Notes **UT performed by Haskell, 2 welds UT tested, both passed**

Radiograph completed by Acuren on 6/8/22

Both welds accepted
181. Question Result, ID, **Sat**, DC.WELDINSPECT.GIRTHWELDNDTLOCATE.R, 195.234(e) (195.266(a)) (also presented in: References DC.WELDINSPECT.GIRTHWELDNDTLOCATE.R)
Question Text *Do records demonstrate all girth welds installed each day in selected locations specified in 195.234(e) are nondestructively tested over their entire circumference?*
Assets Covered **86236 (1580)**
Result Notes **UT performed by Haskell, 2 welds UT tested, both passed**

Radiograph completed by Acuren on 6/8/22

Both welds accepted
182. Question Result, ID, **Sat**, DC.WELDINSPECT.GIRTHWELDNDTUSED.R, 195.234(f) (195.266(a)) (also presented in: DC.WELDINSPECT.GIRTHWELDNDTUSED.R)
Question Text *Do records demonstrate that when installing used pipe, 100% of the old girth welds are nondestructively tested?*
Assets Covered **86236 (1580)**
Result Notes **UT performed by Haskell, 2 welds UT tested, both passed**

Radiograph completed by Acuren on 6/8/22

Both welds accepted
183. Question Result, ID, **Sat**, DC.WELDINSPECT.GIRTHWELDNDTTIEIN.R, 195.234(g) (195.266(a)) (also presented in: DC.WELDINSPECT.GIRTHWELDNDTTIEIN.R)
Question Text *Do records demonstrate 100% of the girth welds have been nondestructively tested at selected pipe tie-ins?*

Assets Covered 86236 (1580)

Result Notes UT performed by Haskell, 2 welds UT tested, both passed

Radiograph completed by Acuren on 6/8/22

Both welds accepted

FS.TSAPIINSPECT: Tanks and Storage - Inspection

184. Question Result, ID, Sat, FS.TS.BOINSPECTION.O, 195.432(a) (195.432(b), 195.432(c), 195.401(b)) (also presented in: References FS.TS)

Question Text *Is the condition of steel atmospheric or low pressure tanks acceptable?*

Assets Covered 86236 (1580)

Result Notes No signs of settling or tank movement, foundation looked good, no visible corrosion, insulation good

FS.PS: Pump Stations

185. Question Result, ID, NA, MO.LMOPP.PRESSREGTEST.R, 195.404(c) (195.428(a)) (also presented in: MO.LMOPP) References

Question Text *Do records indicate inspection and testing of each overpressure safety device on its non-HVL pipelines at intervals not to exceed 15 months, but at least once each calendar year?*

Assets Covered 86236 (1580)

Result Notes Both pipelines are HVL lines

186. Question Result, ID, Sat, MO.LMOPP.PRESSREGTESTHVL.R, 195.404(c) (195.428(a)) (also presented in: MO.LMOPP) References

Question Text *Do records indicate inspection and testing of each overpressure safety device on HVL pipelines at intervals not to exceed 7.5 months, but at least twice each calendar year?*

Assets Covered 86236 (1580)

Result Notes Reviewed 2022 and 2023 records, completed 4/19/22, 10/10/22, 4/12/23 and 09/2023

Petrogas removes and replaces all Thermal Reliefs every six months

187. Question Result, ID, NA, MO.LMOPP.PRESSREGTEST.O, 195.428(a) (also presented in: MO.LMOPP) References

Question Text *Are inspections of overpressure safety devices adequate (including HVL lines)?*

Assets Covered 86236 (1580)

Result Notes No such activity/condition was observed during the inspection.

188. Question Result, ID, NA, MO.LMOPP.LAUNCHRECVRELIEF.O, 195.426 (also presented in: MO.LMOPP) References

Question Text *Are launchers and receivers equipped with relief devices?*

Assets Covered 86236 (1580)

Result Notes No launcher/receiver on Petrogas lines

FS.VA: Valves

189. Question Result, ID, Unsat, MO.LM.VALVEMAIN.T.R, 195.404(c) (195.420(a), 195.420(b)) (also presented in: MO.LM) References

Question Text *Do records indicate each mainline valve was inspected as required?*

Assets Covered 86236 (1580)

Result Issue Summary Petrogas completes mainline valve inspections to ensure each valve is functioning properly twice per year. Petrogas provided valve inspection records for 2023 but records for 2022 were not available.

Standard Issues B2 (Moderate or small impact/limited occurrence) : 195.420(b) : No record/documentation.

Result Notes MOVs tested from control room and in the field

Reviewed record from 11/29/2023, 3/16/23, 5/25/23

Need to see records for 2022, not in Maximo

No PM task before Altagas takeover

Valve closed after receipt of product

Visual completed on operator rounds but no "testing done twice per year

No records for 2022

190. Question Result, ID, References Sat, MO.LM.VALVEMAIN.T.O, 195.420(a) (195.420(c)) (also presented in: MO.LM)

Question Text *Do the pipeline system valves appear to be in good working order and are they protected from unauthorized operation?*

Assets Covered 86236 (1580)

Result Notes All valves are either secured within the facility or in a locked, fenced enclosure

PD.PA: Public Awareness

191. Question Result, ID, References Sat, EP.ERL.LIAISON.R, 195.402(a) (195.402(c)(12), 195.440(c), API RP 1162 Section 4.4) (also presented in: EP.ERL)

Question Text *Do records indicate that liaison has been established and maintained with appropriate fire, police, public officials, and utility owners?*

Assets Covered 86236 (1580)

Result Notes Tony Clizbe coordinates with Fire District 7, verifying that information in CAD is accurate

Environmental Specialist, attends LEPC meetings monthly

PD.RW: ROW Markers, Patrols, Monitoring

192. Question Result, ID, References Sat, MO.RW.PATROL.R, 195.412(a) (195.412(b)) (also presented in: MO.RW)

Question Text *Do records indicate ROW surface conditions and crossings under navigable waterways were inspected, and reporting and appropriate mitigation performed?*

Assets Covered 86236 (1580)

Result Notes Operator Rounds completed twice per day, one day and one night shift, checking pipe conditions, psv status, etc.

Checked a sample of records from Sept 2023 and Feb 2022

193. Question Result, ID, References Sat, MO.RW.ROWCONDITION.O, 195.412(a) (also presented in: MO.RW)

Question Text *Are the ROW conditions acceptable for the type of patrolling used?*

Assets Covered 86236 (1580)

Result Notes Most of the pipe is above ground, operators perform rounds twice per day

194. Question Result, ID, References Sat, MO.RW.ROWMARKER.O, 195.410(a) (195.410(b), 195.410(c)) (also presented in: MO.RW)

Question Text *Are line markers placed and maintained as required?*

Assets Covered 86236 (1580)

Result Notes Markers at road crossing and on fences at above ground pipe

PD.SN: Facilities Signage and Security

195. Question Result, ID, References Sat, FS.FG.FACPROTECT.O, 195.436 (also presented in: FS.FG)

Question Text *Are facilities adequately protected from vandalism and unauthorized entry?*

Assets Covered 86236 (1580)

Result Notes Valve site and facility are within locked gates

Plant facility and breakout tanks are secured by locked gate and security guard

196. Question Result, ID, References Sat, FS.FG.IGNITION.O, 195.438 (also presented in: FS.FG)

Question Text *Is there signage that prohibits smoking and open flames around pump stations, launchers and receivers, breakout tank areas, or other applicable facilities?*

Assets Covered 86236 (1580)

Result Notes Signage throughout the facility looked good

197. Question Result, ID, References Sat, FS.FG.SIGNAGE.O, 195.434 (also presented in: FS.FG)

Question Text *Are there operator signs around each pumping station, breakout tank area, and other applicable facilities?*

Assets Covered 86236 (1580)

Result Notes Signage throughout the facility looked good

TD.CP: External Corrosion - Cathodic Protection

198. Question Result, ID, References Sat, TQ.QU.CORROSIONSUPERVISE.R, 195.589(c) (195.507(a), 195.507(b)) (also presented in: TQ.QU)

Question Text *Is qualification of supervisors in corrosion control procedures documented?*

Assets Covered 86236 (1580)

Result Notes Verified CP qualifications for Christopher Matthews from FarWest Corrosion

See Attached

TD.CPMONITOR: External Corrosion - Cathodic Protection Monitoring

199. Question Result, ID, References NA, TD.CP.DEFICIENCY.R, 195.589(c) (195.573(e)) (also presented in: TD.CP, TD.CPEXPOSED)

Question Text *Do records document adequate operator actions taken to correct any identified deficiencies in corrosion control?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

200. Question Result, ID, References Sat, TD.CP.MAPRECORD.R, 195.589(a) (195.589(b)) (also presented in: TD.CP)

Question Text *Do maps and or records document cathodic protection system appurtenances that have been installed on pipelines that have been constructed, relocated, replaced, or otherwise changed or been converted to hazardous liquid service?*

Assets Covered 86236 (1580)

Result Notes Inspection by Farwest Corrosion documents all CP facilities on the system

Review Corrosion asset P&ID from Norton Corrosion

TD.CPEXPOSED: External Corrosion - Exposed Pipe

201. Question Result, ID, References NA, TD.CP.DEFICIENCY.R, 195.589(c) (195.573(e)) (also presented in: TD.CP, TD.CPMONITOR)

Question Text *Do records document adequate operator actions taken to correct any identified deficiencies in corrosion control?*

Assets Covered 86236 (1580)

Result Notes No such event occurred, or condition existed, in the scope of inspection review.

Except as required to be disclosed by law, any inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.