

PRELIMINARY SURVEY REPORT

<report date>

Your Ref.	:		Our Ref.	:	25-116128
Date of Assignment	:	<assignment date>	Inspected by	:	<Surveyor Name>
Date of Survey	:	<survey date>	Place of Survey	:	<survey address>
Vessel/Carrier	:	<vessel name>	Voyage	:	<voyage ID>
Port of Discharge	:	<port details	Date of Discharge	:	<date of discharge>
Consignment	:	<consignment details>			
Shipper Delivering Carrier	:	<shipper details>	Consignee Waybill No.	:	<consignee details> <way bill number>
Date of Delivery	:	<date of delivery>	Cargo Exceptions:	:	Wetting damages

Further to the request of XXX, we did attend survey of above shipment.

SURVEYOR'S FINDINGS:

The survey was attended by <attending surveyor name>, <surveyor post>, and <surveyor details>

A total of 76 bags from 2 x dry van containers were wet stained and were set aside for inspection, as per below.

Container <container1 id>	34bags
Container <constiner2 id>	42bags
Total	76 bags

Two containers were delivered and unloaded on <unload date>, at which time damage was observed and reported. Per the warehouse, upon opening the containers, moisture was observed due to condensation. There were no breaches in the containers. The warehouse crew found the desiccant bags were heavily saturated with moisture absorption. The water leaked from the bags, ran down the containers side walls and onto the coffee bags. Wet bags were only found at and around the desiccant bags and only along the side panels.

<container id1> is a 01/2024 mfd. 20ft standard dry van container with valid CSC safety approval. The container had four vents, and all were unobstructed. No holes or ruptures to the container were observed. Paper lining was stuck to the floor and container walls. The desiccant bags were not retained for inspection. The silver nitrate test was positive for chlorides. The silver Nitrate test on wet stained burlap bags was positive for chlorides.

<constiner id2> is a 08/2022 mfd. 20ft standard dry van container with valid CSC safety approval. The container had four vents, and all were unobstructed. No holes or ruptures to the container were observed. Paper lining was stuck to the floor and container walls. The desiccant bags were not retained for inspection. The silver nitrate test was positive for chlorides. The silver Nitrate test on wet stained burlap bags was positive for chlorides.

NATURE/CAUSE OF LOSS:

Wetting could have likely been caused by condensation inside the container. No breaches to container were observed. As this wetting appears to be occurring on a regular basis, it appears the desiccant bags placed in the containers are either of poor quality or inadequate in number to the intended transit.

PACKING:

Merchandise was packaged in burlap sacks.

SN TEST:

Container floor, paper lining and Burlap sacks were positive for chlorides. The test was likely positive due to reaction with calcium chloride used in desiccant bags.

RECOMMENDATIONS FOR MITIGATION OF LOSS:

Merchandise can be reconditioned.

EXTENT OF LOSS / RECOMMENDED LOSS RESERVE:

None

ADDITIONAL COMMENTS:

The surveyor requested the warehouse crew to retain the desiccant bags for any future shipments from this shipper that arrive with wet bags.

This report is based on the facts presently known to us and is submitted without prejudice to the rights of whom it may concern. All our findings and comments are subject to the underlying insurance policy conditions and/or provisions of the law. The right to amend or supplement this report at any time is reserved.

Limited Liability

It is expressly understood that all our services are rendered solely on behalf of the person or entity requesting same. Under no circumstances shall <surveyor company> be neither liable for any indirect or consequential losses, howsoever arising, nor to any person or entity other than the person or entity requesting such services.

It is expressly understood and agreed that in any event, the liability of <surveyor company> and of its employees, officers, or subcontractors is limited to the fee charged for all services rendered to subject assignment, but not to exceed \$1000.00. Any claim against <surveyor company> shall be submitted to commercial arbitration in accordance with the rules of the American Arbitration Association of New York and has to be submitted within 60 days of date of survey report or be time barred. The laws of the State of New Jersey shall govern all disputes and claims arising from the services of <Surveyoy company> under this agreement.

Very truly yours,

Container MSNU2057366



Container MSNU2057366 – vent unobstructed



Container MSNU2057366 – vent unobstructed



Container MSNU2057366 – empty container



Container MSNU2057366 – silver nitrate test was positive for chlorides



Container MSNU2057366 – paper lining adhered to side panel



Container MSNU2057366 – wet bags



Container MSNU2057366 – wet bags



Container MSNU2057366 – wet bags



Container MSNU2057366 – wet bags



Container MSNU2057366 – wet bags



Container MSNU2057366 – wet bags



Container MSNU2057366 – wet bags



Container MSNU2057366 – silver nitrate test was positive for chlorides



Container MSNU2057366 – silver nitrate test was positive for chlorides



Container MSMU2647688



Container MSMU2647688 – vent unobstructed



Container MSMU2647688 – vent unobstructed



Container MSMU2647688 – empty container



Container MSMU2647688 – paper lining adhered to floor panel



Container MSMU2647688 – silver nitrate test was positive for chlorides



Container MSMU2647688 – wet bags



Container MSMU2647688 – wet bags



Container MSMU2647688 – wet bags



Container MSMU2647688 – wet bags



Container MSMU2647688 – wet bags



Container MSMU2647688 – wet bags



Container MSMU2647688 – wet bags



Container MSMU2647688 – silver nitrate test was positive for chlorides



Container MSNU2057366 – silver nitrate test was positive for chlorides

