MOLD BUSTERS®
DECONTAMINATION EXPERTS | EST. 2005



VIRTUAL ASSESSMENT REPORT

Report Prepared for: [client name removed]

Address of the Inspected Property: **1500 Des Bassins St, Montreal, QC H3C 0N3**

Inspected by:



Luka Markovic, MSC ME, CMI
Indoor Environmental Inspector

Date: September 8, 2025

Created by:



Goran Petkoski
Administrative Client Support

Date: September 8, 2025

Reviewed by



Stefan Ivkovic
Administrative Client Support

Date: September 8, 2025

www.bustmold.com

TABLE OF CONTENTS

01

COMPANY PROFILE

02

VISUAL RESULTS

03

PHOTOGRAPHIC EVIDENCE

04

CONCLUSION AND RECOMMENDATION

⚠ Disclaimer

The results and interpretation of our inspection and sampling procedures are based on conditions present at the time of the assessment. All efforts were made to ensure accuracy in the collection, and observation of relevant data within the inspected area(s). Unless otherwise stated, the assessment is non-invasive in nature, and inaccessible areas (i.e., behind wall cavities, under sub-floor materials, etc.) may contain concerns not presented in this report due to the restrictions and limitations of the assessment provided. The information and recommendations presented in this report are based on data available at the time of the inspection. Any recommendations made in this report are made, in good conscience and in accordance with the following guidelines:

- Residential Mold Removal Guidelines, 1st Edition, Mold Busters, 2019;
- S520 Standard and Reference Guide for Professional Mold Remediation, IICRC, 2015;
- Mould Guidelines for the Canadian Construction Industry, Canadian Construction Association, 2004;
- ANSI/ASHRAE 62.2-2010, Ventilation for Acceptable Indoor Air Quality in Low-Rise Residential Buildings, American Society of Heating, Refrigeration, and Air-Conditioning Engineers, 2010

Health Canada considers indoor mould growth to be a significant health hazard. The level of concern depends on the extent of mould, how long it has been present and the sensitivity and overall health of the residents. Some people are more susceptible than others. Health Canada recommends controlling dampness indoors and cleaning up any mould regardless of the type of mould present.

01

COMPANY PROFILE

Mold Busters: Decontamination Experts

Mold Busters is a Canadian-owned and operated mold inspection, testing, and removal company that has been established since 2005.

Based in Ottawa, Mold Busters have been servicing residential, commercial, and government clients, promptly dealing with their indoor environmental concerns with professionalism and precision. Their dedication to providing excellent service to their customers have allowed them to grow, opening locations across Ontario, Quebec and the Asia-Pacific.

MOLD BUSTERS SPECIALIZES IN THE FOLLOWING SERVICES:

- Visual & diagnostic mold assessments
- Mold testing
- Comprehensive reports

- Mold removal
- Remediation
- Disinfection

- Non-viable, and viable air quality testing

- Odor removal

- Asbestos testing

- Ventilation
- Duct cleaning
- Air exchanger installation

- Thermal imaging inspections

Mold Busters does not sub-contract any inspection or remediation work, unless otherwise stated. All Mold Busters inspectors are trained through the National Association of Mold Professionals, InterNACHI, IAQA, or the IICRC.

Please visit our website for more information: www.bustmold.com

02

VISUAL RESULTS

Objectives

Mold Busters conducted a virtual inspection at 1500 Des Bassins St, Montreal, QC H3C 0N3, on September 8, 2025.

The objectives of the assessment were to:

1. Visually inspect areas of the property to identify any potential indoor environmental concerns;
2. Determine the source(s) and extent of these concerns, if present;
3. Establish an appropriate action plan and/or provide recommendations for improvement, if necessary.

Diagnostic Results

The technician made the following observations during his inspection of the property 1500 Des Bassins St, Montreal, QC H3C 0N3, ON:

LOCATION:affected

GENERAL OBSERVATIONS:

• The client initiated contact with Mold Busters due to concerns about potential mold presence in their apartment, indicating a proactive approach towards addressing possible indoor air quality issues.

• Health-related issues were reported by the client while residing on the property, which could be indicative of exposure to environmental factors such as mold that can affect health.

• The client also noted musty odors within the apartment. Musty odors are often associated with mold growth and suggest that there may be moisture problems or hidden mold present.

• During a virtual call inspection, visible discoloration was shown by the client. This discoloration might resemble something fungal in nature; however, without physical sampling and laboratory analysis, it cannot be conclusively identified as mold at this stage.

03

PHOTOGRAPHIC EVIDENCE

Photographs taken by the technician during the assessment

Location: 1500 Des Bassins St, Montreal, QC H3C 0N3

Date: September 8, 2025



Visible discoloration throughout the apartment #1



Visible discoloration throughout the apartment #2



Visible discoloration throughout the apartment #3

04

CONCLUSIONS & RECOMMENDATIONS

The following recommendations are based on the technician's visual observations at the time of the inspection within the property at 1500 Des Bassins St, Montreal, QC H3C 0N3.

• Consult with a medical doctor regarding any health-related issues that may arise from mold exposure. It is important to address potential health concerns promptly and seek professional medical advice tailored to individual circumstances.

• Engage a professional company specializing in Indoor Air Quality (IAQ) assessments for mold. A comprehensive evaluation by experts will help determine the extent of mold presence, identify sources, and provide guidance on necessary actions to improve air quality within the premises.

• Limit exposure and traffic in the area of concern until recommended steps are taken. Minimizing disturbance in affected areas can prevent further spread of mold spores and reduce potential health risks associated with inhalation or contact.

Please note that every individual will react differently to mold. The severity of the reaction will depend on factors such as the individual's immune system, exposure threshold, type of mold species present in the space, and duration of exposure. Health Canada considers indoor mold growth to be a "**significant health hazard**" and recommends that all mold, regardless of the species, be cleaned and that the underlying water or humidity problem be dealt with quickly to prevent potential health issues. (Source: *Addressing moisture and mold in your home; Canada.ca*)

If you have any questions regarding this report and the findings therein, please contact **Mold Busters** at 1-877-566-6653.



Luka Markovic, MSC ME, CMI

Indoor Environmental Inspector

05

APPENDIX - KNOWLEDGE BASE



Everything You Need to Know About Mold



The Mold Library



Residential Mold Removal Guidelines



Asbestos in Canada: A Homeowner's Handbook



The Ultimate Mold Prevention Guide



Indoor Air Quality



Mold Videos

Copyright © 2026 Bust Mold Inc. All rights reserved.