AndrewID: jdoe Date (MM/DD): 09/03

- no sensor redundancy
- MCAS had too much authority over horizontal tail
  - also, this authority wasn't documented and FAA didn't know
- Engineers assumed the worst case wouldn't occur b/c pilots would intervene
- ~~Bad~~ Inadequate training for pilots and no manual on MCAS.
- ~~Administration~~ Administrators and managers were pressured into doing things quickly.

AndrewID: asmith

Date (MM/DD): 09/03

Neglecting issues and rushing development can bring up a lot of problems and cause a worse product

AndrewID: r d a s

Date (MM/DD): 0 9 / 0 3

1. Lack of systematic testing
2. Missing edge cases that can go wrong.
3. Design itself is poor
4. Lack of real-time feedbacks / metrics during the incident.
5. Communications system
6. Backup system is bad.
7. No updates after initial sign of errors.