

Nonconformance report			NCR-No. 200347442		
Material No.	Ver		Material Description		
VOLS:10274160	AB		Case Compr ITM assy		
Program			Design Organization Drawing & issue	Total quantity	Order No
GTF IMC BA			5379995-AA	1	
Coordinator	Supplier cod	de	Design Organization Part number & version	Reference No.	
Johanna Jönsson			5379995-AA		

Decisions

Item	Serial number / batch	Item decision		
1	44ACT02001	Select code & write dispositon GKN		
		Select code & write dispositon Q		
2	44ACT02001	Select code & write dispositon GKN		
		Select code & write dispositon Q		
3	44ACT02001	Select code & write dispositon GKN		
		Select code & write dispositon Q		
4	44ACT02001	Select code & write dispositon GKN		
		Select code & write dispositon Q		

GKN Design
Digitally signed by: ,
Date: 00000000
Di

GKN reserves all of its rights under the agreement and at law.

The information contained in this document is GKN Aerospace Sweden AB proprietary information and it shall not - either in its original or in any modified form, in whole or in part - be reproduced, disclosed to a third party, or used for any purpose other than that for which it is supplied, without the written consent of GKN Aerospace Sweden AB. The information contained in this document may also be controlled by export control laws. Unathorized export or re-export is prohibited. Any infringement of these conditions will be liable to legal action.

[©] Copyright GKN Aerospace Sweden AB. All rights reserved.



Nonconformance	report					NCR-No. 200347442	
Material No. VOLS:10274160	Ver AB	Ver Material Description					
Program GTF IMC BA	Design Organization Drawing & issue 5379995-AA			T 1	Total Quantity	Order No	
Coordinator Johanna Jönsson		_	Design Organization Part number & version 5379995-AA			Reference No.	
Item No. 1							
Defect Class Define Defect Class	Pieces affected 1		Defect type Neg. Imperfections/Crack			Charact.No 05106	
Requirement Location PAGE-05 Zone	e J4						
Serial numbers affected							
44ACT02001,							
Description of Nonconformar							
Casting void on flange looking AFT: Depth 0,178 [.007]. Length 0,952 [.0375]. Width 0,584 [.023]. ***Update GANE6 4/8/ After blend area meast Depth 0.203 [.008] Length 9.626 [.379] Width 2.311 [.091] Cause of Nonconformance	['] 2023****	претох.					
Casting void							
Corrective Action (to avoid re	e-occurance of this I	Nonconforr	mance)	Planned finish: 2023-04	-20		
Send RCA to casting h Blend casting void.	ouse.						
GKN Disposition			Dig	gitally signed by:			
Quality Decision			Dig	gitally signed by:			

6650 Ver 9

The information contained in this document is GKN Aerospace Sweden AB proprietary information and it shall not - either in its original or in any modified form, in whole or in part - be reproduced, disclosed to a third party, or used for any purpose other than that for which it is supplied, without the written consent of GKN Aerospace Sweden AB. The information contained in this document may also be controlled by export control laws. Unathorized export or re-export is prohibited. Any infringement of these conditions will be liable to legal action.



Nonconformance repor	rt		NCR-No. 200347442	,		
Material No. VOLS:10274160	Ver AB	Material Description Case Compr ITM assy	200347442	•		
Program GTF IMC BA	Design Or 5379995	ganization Drawing & issue	Total Quantity 1	Order No		
Coordinator Johanna Jönsson	Design Or 5379995	ganization Part number & version 5-AA	Reference No	Reference No.		
Item No. 2						
Defect Class Define Defect Class Requirement Location PAGE-16 Zone D6	affected	Defect type Neg. Imperfections/Crack	Charact 16003	-		
Serial numbers affected 44ACT02001,						
Description of Nonconformance						
After blend of casting void loc Depth is 1,016 [.040]. Height & Width (diameter) is the It is also 0,134 [.0053] from each	5,588 [.220].	from TDC AFT looking FWD.				
Cause of Nonconformance						
Casting void						
Corrective Action (to avoid re-occurar	nce of this Nonconforr	mance) Planned finish: 2023-04-20)			
Send RCA to casting house Blend casting void						
GKN Disposition		Digitally signed by:				
Quality Decision		Digitally signed by:				

6650 Ver 9

The information contained in this document is GKN Aerospace Sweden AB proprietary information and it shall not - either in its original or in any modified form, in whole or in part - be reproduced, disclosed to a third party, or used for any purpose other than that for which it is supplied, without the written consent of GKN Aerospace Sweden AB. The information contained in this document may also be controlled by export control laws. Unathorized export or re-export is prohibited. Any infringement of these conditions will be liable to legal action.



Nonconformance	report			NCR-	No. 347442
Material No. VOLS:10274160		Ver AB	Material Description Case Compr ITM assy	2003	947442
Program GTF IMC BA		Design Org 5379995	ganization Drawing & issue	Total 1	Quantity Order No
		Design Organization Part number & version 5379995-AA		Refer	ence No.
Item No. 3					
Defect Class Define Defect Class Requirement Location PAGE-05 Zone	Pieces affected 1		Defect type Neg. Imperfections/Crack		Charact.No 05094
Serial numbers affected 44ACT02001,					
Description of Nonconformar Casting void located at Depth 0,284 [.0112]. Length 2,949 [.1161]. Width 2,689 [.1059].		TDC FW	/D looking AFT.		
Cause of Nonconformance Casting void					
Corrective Action (to avoid re Send RCA to casting h Blend casting void		Nonconform	nance) Planned finish: 2023-04-20)	
GKN Disposition			Digitally signed by:		
Quality Decision			Digitally signed by:		

6650 Ver 9

The information contained in this document is GKN Aerospace Sweden AB proprietary information and it shall not - either in its original or in any modified form, in whole or in part - be reproduced, disclosed to a third party, or used for any purpose other than that for which it is supplied, without the written consent of GKN Aerospace Sweden AB. The information contained in this document may also be controlled by export control laws. Unathorized export or re-export is prohibited. Any infringement of these conditions will be liable to legal action.



Nonconformance	report				NCR-No. 200347442	
Material No. VOLS:10274160		Ver AB	Material Description Case Compr ITM assy		200347442	
Program GTF IMC BA		Design Organization Drawing & issue 5379995-AA			Total Quantity	Order No
Coordinator Johanna Jönsson		Design Organization Part number & version 5379995-AA		Ī	Reference No.	
Item No. 4						
Defect Class Define Defect Class Requirement Location PAGE-05 Zone	Pieces affected 1 B13		Defect type Neg. Imperfections/Crack		Charact. 05070	No
Serial numbers affected 44ACT02001,						
Description of Nonconforman	се					
casting void located at width is 8,89 [.350]. depth is 1,651 [.065]. height is 1,956 [.077]	335° CW from	TDC, AF	T looking FWD			
Cause of Nonconformance						
Castin void						
Corrective Action (to avoid re	-occurance of this	Nonconform	mance) Planned finish: 2023-04	1-20		
Send RCA to casting h Blend casting void	ouse					
GKN Disposition			Digitally signed by:			
Quality Decision			Digitally signed by:			

6650 Ver 9

The information contained in this document is GKN Aerospace Sweden AB proprietary information and it shall not - either in its original or in any modified form, in whole or in part - be reproduced, disclosed to a third

party, or used for any purpose other than that for which it is supplied, without the written consent of GKN Aerospace Sweden AB. The information contained in this document may also be controlled by export control laws. Unathorized export or re-export is prohibited. Any infringement of these conditions will be liable to legal action.