
Quadratic Fit: $T = 8.213e + 02V^2 + (-3.641e + 03)V + (4.073e + 03)$



V	Т
2.0283	66.25
2.0332	64.4
2.0381	63.5
2.043	62.2
2.0479	61.2
2.0528	60.0
2.0577	58.8
2.0626	57.54
2.0674	55.77
2.0723	54.45
2.0821	51.85
2.087	50.2
2.0919	49.0
2.1114	45.06
2.1212	44.34
2.131	43.9
2.1408	42.8
2.1652	40.8
2.175	39.8
2.1799	38.76
2.1848	37.23
2.2092	36.58