ThunderMaster2 Release Note (2023/05/16)

V4.14

- Add RGB Control Rainbow light intensity and speed can be adjusted.
- Support RGB Control white LED.
- Fix minor issue.
- Update SaVBIOS.
- Update NVAPI R525.

V4.13

- Add RGB Control – "GPU Temperature" setting points can be adjusted.

V4.12

- Add "ONE TWO SYNC" function
- Optimize UI operation
- Update "tool-tips"
- Fix minor issue

V4.11

- Adding new ARGB LED lighting effect (need to upgrade on-board MCU F/W)

V4.10

- Fix "set to default" issue, RTX 20 series and RTX 30 GamingPro series
- Fix minor issue

V4.9

- Fix "User defined fan curve" issue
- Update multi-language for "tool-tips"
- Fix minor issue

V4.8

- Fix LED "GPU Temperature" issue
- Fix some bugs

V4.7

- Fix some bugs

V4.6

- Adding "FanStop ON/OFF" feature under "User Defined Fan Curve"
- Fix some bugs

V4.5

- Adding "Change Screen Size" feature
- Adding "Saving LED Control to Board" feature
- Fix some bugs

V4.4

- Fix "Frame Rate Target can not change issue"
- Fix "OC memory, STATUS GPU display error issue"

- Remove "F/W upgrade available"

V4.3

- "OC SCAN" bug fixed
- Some minor bugs fixed

V4.21

- Adding multiple language support

V4.2

- Added RTX 30 series support

V4.1

- Added "disable warning message option 75C+0RPM and 85C"
- Default "profile 1"