

PAY IT FORWARD ...

Chúng tôi không sáng tạo ra câu nói này.

Pay it forward...

Hãy tri ân người giúp mình bằng cách giúp đỡ người khác Cho đi không phải để nhận lại.

Câu chuyện bắt đầu từ một cậu bé, và một ý tướng có thể làm thay đổi thế giới... PAY IT FORWARD

Đó là khi bạn giúp đỡ 3 người bạn không quen biết, dũ là bằng thời gian, hay công sức, hay kinh nghiệm, hay kiến thức, hay tiến bạc, ...

Mà không chờ đợi một sự báo ân nào.


của mình.

Chi cần mỗi người trong 3 người đó, lại đem những gì mình có, mà người khác cần, tiếp tục giúp đỡ thêm 3 người nữa.

Chính những người-giúp-đỡ, và người-được-giúp-đỡ, sẽ là những người góp phần thay đổi thế giới...

Một thế giới sẻ chia kiến thức - và yêu thương ...

PAY IT FORWARD



I2C

COMMUNICATION

Revision: 12/07/2013



payitforward.edu.vn I²C (Inter-Integrated Circuit) ["eye-squared cee" or "eye-two-cee"] + 5V $R_{PULL-UP}$: 1.8 $k\Omega - 47 k\Omega$ +3.3V1K8 4K7 10K VCC Serial Clock SCL **BUT: SDA** 16 reserved addresses Serial Data maximum 112 nodes can Line **MCU** communicate on the same bus Slave Device address: **7-bit** or 10-bit addressing PAY IT FORWARD 1 Master 128 devices

127 Slaves

MODE

One Master – One Slave

One Master – Multi-slave

Multi-master - Multi-slave

SPEED

Standard mode: 100 kbit/s

Low-speed mode: 10kbit/s

Fast mode: 400 kbit/s


Fast mode plus: 1 Mbit/s

High Speed mode: 3.4 Mbit/s





💃 payitforward.edu.vn






payitforward.edu.vn

I²C (Inter-Integrated Circuit)

Read 1 byte



AK

PAY IT FORWARD

AK


AK (ACK): Acknowledge = "0"

AK


NAK (NACK): Not Acknowledge = "1"
























Real-Time Clock DS1307 Module





TRIAC Module






MCU can be Master or Slave on I2C Bus

7-bit and 10-bit addressing


DS1307 ADDRESS MAP

DS1307 Slave address: 0x68





Các chân I2C của MSP430G2533 PDIP20



NOTE: Rút jumper P1.6 ra!



I²C functions in *I2C.h*(MSP430G2553)

```
// Initialize i2c module
void i2c init(unsigned char sla add);
// Read data Slave
void i2c read(unsigned char AddRes, unsigned char
numbyte, unsigned char *poirev);
// Write data Slave
void i2c wirte(unsigned char AddRes, unsigned char
numbyte, unsigned char *poisend);
```





i2c_init function in I2C.c(MSP430G2553)

```
void i2c_init(unsigned char sla_add)
P1SEL |= BIT6 + BIT7; // Assign I2C pins to USCI_B0
P1SEL2 = BIT6 + BIT7; // Assign I2C pins to USCI_B0
UCB0CTL1 |= UCSWRST; // Enable SW reset
UCB0CTL0 =UCMST+UCMODE_3+UCSYNC; // I2C Master, synchronous
mode
UCB0CTL1 = UCSSEL 2+UCSWRST; // Use SMCLK, keep SW reset
                           // fSCL = SMCLK/12 = ~100kHz
UCB0BR0 = 12;
UCBOBR1 = 0;
UCB0I2CSA = sla_add; // Set slave address
UCB0CTL1 &= ~UCSWRST; // Clear SW reset, resume operation
```





```
How to write CCS C code for I<sup>2</sup>C module
#include "i2c.h"
void main()
unsigned char datawr[]=\{0x00,0x08,0x03,0x05,0x15,0x11,0x12\};
// khai báo data write
unsigned char datarev[8];
//khai báo data read
i2c_init(0x68);
i2c_write(0x00,7, datawr); //write multi – byte
While(1)
i2c_read(0x00,8,datarev);//read multi – byte
```

TMP100: Serial Digital Thermal Sensor

Digital Temperature Sensing: SOT-23 Packages

RESOLUTION: 9- to 12-Bits, User-


Selectable


Simple SMBus/I2C™ Serial Port Interface

Supply Voltage of 2.7V to 5.5V


Table 11. Address Pins and Slave Addresses for the TMP100

ADD1	ADD0	SLAVE ADDRESS
0	0	1001000
0	Float	1001001
0	1	1001010
1	0	1001100
1	Float	1001101
1	1	1001110
Float	0	1001011
Float	1	1001111






PIN CONFIGURATION



Slave **Address** PAY IT FORWARD



payitforward.edu.vn