Multisim Convergence Assistant Summary Report

Convergence Assistant Summary Report

## Outcome:

The Convergence Assistant was unable to correct the problem. Consult the help documentation for information about simulation errors and how to correct them.

Multisim Convergence Assistant Log

Step 1: Verifying Error Scenario ...completed.

Step 2: Setting parameter Integration Method (METHOD) to Gear Simulating...

...completed. Simulation error still occurs.

Step 3: Setting parameter Initial Conditions to Set To Zero Simulating...

...completed. Simulation error still occurs.

Step 4: Setting parameter Maximum Timestep (TMAX) to 1.0000e-04 Simulating...

...completed. Simulation error still occurs.

Step 5: Setting parameter Maximum Timestep (TMAX) to 1.0000e-03 Simulating...

...completed. Simulation error still occurs.

Step 6: Setting parameter Relative error tolerance (RELTOL) to 1.0000e-02 Simulating...

...completed. Simulation error still occurs.

Step 7: Setting parameter Shunt resistance from analog nodes to ground (RSHUNT) to 100000000 Simulating...

...completed. Simulation error still occurs.

Step 8: Setting parameter Shunt resistance from analog nodes to ground (RSHUNT) to 100000000 Simulating...

...completed. Simulation error still occurs.

Step 9: Setting parameter Shunt resistance from analog nodes to ground (RSHUNT) to 10000000 Simulating...

...completed. Simulation error still occurs.

Step 10: Setting parameter DC iteration limit (ITL1) to 200 Simulating...

...completed. Simulation error still occurs.

Step 11: Setting parameter DC iteration limit (ITL1) to 300 Simulating...

...completed. Simulation error still occurs.

Step 12: Setting parameter Minimum conductance (GMIN) to 1.0000e-07 Simulating...

...completed. Simulation error still occurs.

Step 13: Setting parameter Maximum Timestep (TMAX) to 1.0000e-04 Simulating...

...completed. Simulation error still occurs.

Step 14: Setting parameter Maximum Timestep (TMAX) to 1.0000e-05 Simulating...

...completed. Simulation error still occurs.

Convergence Assistant completed unsuccessfully.