```
.model small
.data
n dw 4
r dw 2
ncr dw 0
.code
mov ax,@data
mov ds,ax
mov ax,n
mov bx,r
call ncrpro
call disp
jmp final
ncrpro proc near
    cmp ax,bx ;r=n
   je res1
    cmp bx,0 ;r=0
   je res1
                           ; 3c2 +3c1
    cmp bx,1 ;r=1
   je resn
    dec ax
            ;r=n-1
    cmp bx,ax
    je incr
    push ax
    push bx
    call ncrpro
pop bx
pop ax
```

```
dec bx
push ax
push bx
call ncrpro
pop bx
pop ax
ret
res1:inc ncr
ret
incr:inc ncr
resn:add ncr,ax ;1+2 3+3=6
ret
ncrpro endp
disp proc near
mov bx,ncr
add bx,3030h
mov dl,bh
mov ah,02h
int 21h
mov dl,bl
mov ah,02h
int 21h
ret
disp endp
final: mov ah,4ch
  int 21h
  end
```

```
51756 + 464788 Bytes symbol space free

3 Warning Errors
5 Severe Errors

C:\MASM\masm ncr;;
Microsoft (R) Macro Assembler Version 5.00
Copyright (C) Microsoft Corp 1981-1985, 1987. All rights reserved.

51758 + 464786 Bytes symbol space free

0 Warning Errors
0 Severe Errors

C:\MASM\link ncr;;

Microsoft (R) Overlay Linker Version 3.60
Copyright (C) Microsoft Corp 1983-1987. All rights reserved.

LINK: warning L4021: no stack segment

C:\MASM\ncr
96
C:\MASM\ncr
```