```
.model small
.code
mov cl,00
mov ah,00h
mov al,03h
int 10h
back:mov bh,00h
  mov dh,00h
  mov dl,00h
  mov ah,02h
  int 10h
  mov al,cl
  add al,00h
  aam
  add ax,3030h
  mov ch,al
  mov dl,ah
  mov ah,02h
  int 21h
  mov dl,ch
  mov ah,02h
  int 21h
  call delay
  inc cl
  xor ax,ax
  cmp cl,100d
  jne back
  je last
```

```
delay proc near
push ax
push bx
push cx
mov cx,00ffh
ag:mov bx,0000h
ag1:nop
  dec bx
  jnz ag
  рор сх
  pop bx
  pop ax
  ret
  delay endp
last:mov ah,4ch
 int 21h
 end
   DOSBox 0.74-3, Cpu speed:
                             3000 cycles, Frameskip 0, Progra...
```

