

Monthly QA Intelligence Report

Reporting Period: December 2025 | Generated: 2026-07-07 12:30:21

Executive Summary

During the period of December 2025, a total of **100** failure claims were logged in the system. The breakdown of models, outbreaks by country, and critical trouble codes indicates the current quality distribution across manufacturing bases.

Quality Distribution Metrics

Outbreaks by Country	Claims by Product Model
- Nepal: 21 claims - Saudi Arabia: 20 claims - India: 17 claims - Sri Lanka: 15 claims - UAE: 14 claims - South Africa: 9 claims - Indonesia: 4 claims	- YNC: 15 claims - YJD: 14 claims - YNB: 13 claims - YJC: 11 claims - YHB: 11 claims - YMB: 10 claims - YMA: 9 claims - YEC: 9 claims - YHC: 8 claims

Top Failure Trouble Codes (DTC)

Trouble Code	Claims Count
P0505	8
P0301	8
P0300	8
B2477	8
U0100	7

Sample Quality Cases & Technical Summaries

FTIR No: FTIR/2024/1018 | Dealer: Nexa Chennai | Quality rating: **Good**

Subject: MIL warning light glowing, DTC P0500 Vehicle Speed Sensor Malfunction showing current, warm engine both idle and driving conditions, causal part oxygen sensor

Summary: Issue reported was 'MIL warning light glowing, DTC P0500 Vehicle Speed Sensor Malfunction showing current, warm engine both idle and driving conditions, causal part oxygen sensor', related to causal part solenoid valve. Checked results found 'SDT scan confirmed DTC P0500 current', and technician action was 'Replaced transmission solenoid valve assembly (Part No: 28260RNAA14)'.

FTIR No: FTIR/2024/5085 | Dealer: Nexa Chennai | Quality rating: **Needs Rework**

Subject: Engine problem

Summary: Issue reported was 'Engine problem', related to causal part engine part. Checked results found 'Vehicle checked — problem exists', and technician action was 'Will repair later'.

FTIR No: FTIR/2024/9076 | Dealer: Maruti Arena Delhi | Quality rating: **Poor**

Subject: Customer complaint

Summary: Issue reported was 'Customer complaint', related to causal part none. Checked results found 'No abnormality found', and technician action was 'Under investigation'.

FTIR No: FTIR/2024/9070 | Dealer: Maruti Pune | Quality rating: **Poor**

Subject: Problem in vehicle

Summary: Issue reported was 'Problem in vehicle', related to causal part none. Checked results found 'Unable to reproduce', and technician action was 'Part not available'.

FTIR No: FTIR/2024/5122 | Dealer: Suzuki Workshop Mumbai | Quality rating: **Needs Rework**

Subject: Vehicle issue observed

Summary: Issue reported was 'Vehicle issue observed', related to causal part engine part. Checked results found 'As mentioned above', and technician action was 'Not repaired'.