

Thermodynamics

First Law: energy cannot be created or destroyed; change in internal energy equals heat minus work. Second Law: entropy of an isolated system never decreases. Third Law: entropy approaches zero at absolute zero temperature. Carnot efficiency sets the upper limit for heat engines. Enthalpy $H = U + PV$. Gibbs free energy $G = H - TS$ determines reaction spontaneity.