for S32K344 HSE Firmware 0.2.40.0

Rev. 1.0 — 16 August 2023

Release notes COMPANY CONFIDENTIAL

1 Getting Started

IMPORTANT NOTES:

This is the Standard Package variant of the HSE Firmware for S32K344 device.

1.1 Package content

This package contains the NXP S32K344 HSE Firmware 0.2.40.0:

- FULL MEM HSE Firmware: encrypted binary
- AB SWAP HSE Firmware: encrypted binary
- · HSE Firmware interface files
- HSE Service API RM
- HSE_FW_S32K344_0_2_40_0_ReleaseNotes.pdf this file
- The license.txt file and the uninstall.exe utility for removing the HSE Firmware binaries

Note:

Demo Application is provided separately and contains details on how to provision HSE Firmware on new device from factory and demonstrates common use cases of its security features. For this release, RM can be provided On-Demand.

SBAF Encrypted Binary will be added in a separate .exe by the end of August 2023. Using this binary, the SBAF can be updated on a device using the service ID HSE_SRV_ID_SBAF_UPDATE.

One can access via NXP DocStore (https://www.docstore.nxp.com) the following associated documentation:

HSE Firmware Reference Manual VERSION 2.2

1.2 Installation

Follow the installation steps in the demo application.



2 Release Details

This is the HSE Firmware 0.2.40.0 Service Release.

The provided example code shows how to setup and use the HSE Firmware and to perform basic cryptographic operations (refer to the documentation that comes with demo application). The examples will show how to:

- Boot the demo-application (secure mode)
- · Install the Firmware
- Load the key(s)
- Perform cryptographic operations

This release was developed and tested using:

- Chip: E5 P32K344EHVMMS
- Motherboard: X-S32K2XX-MB (700-31431 REV X3)
- Mini-Module: X-S32K3XXCVB-Q257 (700-47020 REV X2)

Implemented Errata:

N/A

2.1 Supported Derivatives

The software described in this document is intended to be used with the following microcontroller devices of NXP:

- S32K344
- S32K324
- S32K314

2.2 Device Bricking scenario for HSE Firmware

• No bricking scenario identified in CUST DEL lifecycle.

2.3 Security Aspects

Current release of HSE Firmware implements partial counter-measures against logical attacks (e.g. input parameter checking, address ranges). The code contained in this release was not subject to penetration testing / vulnerability attacks verification.

3 Changes in 0.2.40.0

Added

 Added new service (HSE_SRV_ID_ERASE_FW) to remove HSE Firmware and sys image from the device (only allowed in CUST_DEL lifecycle). This will enable reconfiguration of the device.

Updated

- Improved interface comments for Erase NVM Data and updated placement order of service IDs
- Added and updated description of HSE GPR status bits related to sys image sector getting erased by HSE FW when corruption happens.

Removed

- Disabled following services to increase available code flash for HSE FW:
 - Burmester Desmedt (HSE SPT BURMESTER DESMEDT)
 - Extend Key Catalogs (HSE SPT EXTEND KEY CATALOG)
 - Classic DH (HSE_SPT_CLASSIC_DH)
 - App Specific Data Attribute (HSE SPT APP SPECIFIC DATA ATTR)
 - CMAC with Counter (HSE SPT CMAC WITH COUNTER)
- Removed the support macro <code>HSE_SPT_ECC_COMPRESSED_KEYS</code>. The feature is still present in HSE FW.

4 Changes in 0.2.32.0

Added

- This release candidate contains ECC error handling change request for both Secure-BAF and HSE Firmware. In full memory configuration, to get the ECC error handling feature in Secure-BAF, the user must update the Secure-BAF using the service ID
 HSE SRV ID SBAF UPDATE.
- Added the sys image integrity feature in HSE_SRV_ID_FW_INTEGRITY_CHECK service.

Updated

- · Increment counter is made as heavy job internally instead of fast job.
- First service depending on monotonic counters will take more time. After that they will be executed in normal way. This is done to save boot time and handle possible ECC errors in monotonic counter flash area.
- Removed HSE_SPT_NXP_ROM_PUB_KEYS and added

 HSE SPT NXP ROM RSA PUB KEYS and HSE SPT NXP ROM ECC PUB KEYS
- Renamed FW Type macro in hse_target.h (STANDARD -> HSE STANDARD FW)
- Added and updated description of HSE GPR status bits related to sys image sector getting erased by HSE FW when corruption happens because of ECC error.
- While configuring the ADKP via attribute <code>HSE_APP_DEBUG_KEY_ATTR_ID</code>, <code>HSE Firmware returns error <code>HSE_SRV_RSP_INVALID_PARAM</code>, if filled with all <code>0x00</code> and <code>0xFF</code>.</code>

Issues Fixed

• HSE Firmware always returned <code>HSE_SRV_RSP_OK</code> for HMAC using SHA384 verification and HMAC using SHA512 verification.

for S32K344 HSE Firmware 0.2.40.0

5 Changes in 0.2.31.0

Added

· Add Support for SHA3 functionality

6 Changes in 0.2.12.0

Added

- Added the partial AB swap feature. Applicable only for S32K358 devices.
- JDC Disable support added for S32K358 devices.

Issues Fixed

• smrEntryInstallStatus is not getting updated even after getting ERC_NO_ERR for SMR entry erase service.

7 Changes in 0.2.7.0

Added

- · Support for KM catalog extend service.
- Support for ECC ROM keys for all devices involving trust center. Please contact NXP for more details on this.
- Support to store app data inside HSE FW.
- Support for SHA 384 and SHA 512 in ANSI 9.63 KDF.
- Provided the flexibility in firmware and SBAF to not use JDC for debug authorization on request. This is applicable only for S32K396 device family.
- Support of Deletion of SMR Entry & CR Entry.

Updated

• Updated the window time for time slice mechanism. Fast jobs will have 4 times more execution time as compared to heavy jobs.

Issues Fixed

• Master secret computation fails using TLS 1.2 PRF for DHE PSK.

for S32K344 HSE Firmware 0.2.40.0

8 Changes in 0.2.8.0

N/A

9 Changes in 0.2.6.0

Updated

- Firmware Update service for same Firmware Type in FULL MEM configuration will be allowed only if code size and sys image size is equal or higher than the current Firmware code size and sys-image size installed in the system.
- In the case of streaming mode, if firmware input length given has already exceeded the
 expected pink image length, then error will be thrown, and firmware update process will
 be terminated.
- In case there is firmware update request from standard to custom firmware for FULL MEM configuration, and there is change in sys image or code size, then also firmware update request will be allowed only in one shot mode.
- In case of change in sys image or code size change in new HSE Firmware image, then Firmware Update will be allowed only in one shot mode.

Issues Fixed

- Monotonic Counter Increment Service when run in parallel to Asymmetric Services (RSA & ECC) causes failures in both services and causes HSE FW to go into shutdown.
- Monotonic Counter Increment Service when ran in parallel to HASH/HMAC services causes failures in both services and causes HSE FW to go into shutdown.
- Fast CMAC without scatter gather given after Fast CMAC with scatter gather always fails with CAAM hardware error.
- HSE Firmware Update does not complete when XRDC is enabled by the host application. This issue is not applicable for S32K344 devices.

10 Changes in 0.2.1.0

Added

- Added the feature of calculating and verifying the GMAC using random IV in IVT, Base secure boot and secure recovery image
- Support for compressed ECC keys hseEccKeyFormat_t
- Key verify service hseKeyVerifySrv_t generates a hash/MAC over a symmetric key from HSE key store
- AAD support for encrypted SMR hseSmrDecrypt_t
- Enable the support of NXP ROM keys to allow the import of first user root key in secure manner. Please contact NXP support team for more details.
- Added support for Publish Sys Image and Attribute to allow user to program multiple keys in the flash once. This will help in reduction in time to store multiple keys in flash
- NVM Erase to be done in case junk data is present in the device and inform the status to the user.
- Added the support of software based HMAC-384 and HMAC-512 functionality.
- AES block mode mask as part of the AES key info. It restricts the usage of an AES key only to those specified by hseAesBlockModeMask_t member. If set to 0 then no restrictions apply
- · Added the support of TLS RSA master secret key feature
- Enabled the support of Diffie-Hellman key exchange support.
- Added the support of address translation logic in SMR verification service for AB swap configuration. hseSmrVerificationOptions_t, hseSmrVerifySrv_t
- Added the support of scatter gather entries in service
 "HSE_SRV_ID_CMAC_WITH_COUNTER" hseCmacWithCounterSrv_t
- The key derive copy restrictions on starting offset and number of bytes extracted hseKeyDeriveCopyKeySrv t

Updated

- Improve the flash programming check logic in interface level function. HSE Firmware will return an error at the time of accepting the request only when flash programming is in progress on the same code flash block where HSE Firmware is executing.
- · Updated the comments in interface files.
- Minimum MAC length to 8 bytes for MAC service
- · Include the MU instance in streaming context
- Policy on encrypted keys import/export. If encrypted, it must also be authenticated
- Minimum MAC length to 16 bytes for plain SMR initial authentication proof, authenticated key import/export and system authorization services
- RNG re-initialization is done for one time when first heavy job is requested after HSE Firmware initialization is completed.

Updated the ITCM and DTCM memory address range for output address for S32K314 device.

Issues Fixed

- HSE status and error bits are not updated on the application side (MU.FSR and MU.GSR) until HSE STATUS INIT OK is set
- Flash Read while Write Issue is observed in Firmware if Flash Operation is ongoing on the device.

HSE_FW_S32K344_0_2_40_0_ReleaseNotes

All information provided in this document is subject to legal disclaimers.

© 2023 NXP B.V. All rights reserved.

for S32K344 HSE Firmware 0.2.40.0

Removed

- XRDC configuration in SBAF to improve the boot time.
- Specific fatal error events for tamper violations hseError_t
- SHA1 support for key derivation services
- HMAC and CMAC support as PRF for NXP key derivation scheme

for S32K344 HSE Firmware 0.2.40.0

11 Changes in 0.1.2.1 (hotfix)

Issues Fixed

• HSE goes into the exception due to RWW(read while write error) while handling watchdog ISR, if the Host is performing the flash operation (programming/ erase) on the same block on which HSE Firmware is executing. (ASHF-4611)

12 Changes in 0.1.2.0

Added

- Service HSE_SRV_ID_IMPORT_EXPORT_STREAM_CTX. This service is used for Import/Export streaming context for the symmetric operation.
- Enhanced the synchronization logic for the Flash read and write operation between the Host application and the HSE core. For every flash block, Status bit in the GPR register are provided which indicates to the Host application that HSE core is performing read or write operation on a specific block. For more details (Refer to HSE Firmware reference manual V1.2)
- Added the <code>HSE_RAM_PUB_KEY_IMPORT_POLICY_ATTR_ID</code> attribute which allows the importing of public keys in RAM without authentication.
- · Added the SMR rollback protection feature.
- Added the support of glitch filter enablement for the Active Tamper.

Updated

- · Interface comments.
- Key Import:
- Only authentication is required for importing the RAM provision keys. These keys can be used to import only RAM keys.
- NVM provisioning keys can be imported/updated without authentication only having SuperUser rights.
- · Key Export:
- NVM keys cannot be exported using RAM provision keys.
- NVM and RAM symmetric keys can be exported only encrypted and authentication is optional.

Issues Fixed

- User Keys in the NVM are getting erased after giving a reset. (ASHF-4435)
- TLS 1.2 KDF output is not correct when secret key length is greater than the block size of the Hash Algo. (ASHF-4303)

13 Change logs in 0.1.1.0

Added

- Service <code>HSE_SRV_ID_IMPORT_EXPORT_STREAM_CTX</code>. This service is used for Import/Export streaming context for the symmetric operation.
- Enhanced the synchronization logic for the Flash read and write operation between the Application and the HSE core. For every flash block, Status bit in GPR are provided which indicates to host application that HSE core is performing read or write operation on a specific block. For more details (Refer to HSE Firmware reference manual V1.1)

Updated

· Interface comments.

14 Change logs in 0.0.12.0

Added

- Added the <code>HSE_RAM_PUB_KEY_IMPORT_POLICY_ATTR_ID</code> attribute which allows the importing the public keys in RAM without authentication.
- Added the SMR rollback protection feature.
- Added the support of glitch filter enablement in case of active tamper and updated the description for the same in interface file.

Updated

- Interface comments and enhancement. Some items have been moved to new headers (to decongest some headers).
- Key Import:
 - Only authentication is required for importing the RAM provision keys. These keys can be used to import only RAM keys.
 - NVM provisioning keys can be imported/updated without authentication only having SuperUser rights.
- · Key Export:
 - NVM keys cannot be exported using RAM provision keys.
 - NVM and RAM symmetric keys can be exported only encrypted and authentication is optional.

15 Change logs in 0.0.10.0

Added

- Streaming support in HSE Firmware update service.
- The size of HSE MAX RAM STORE SIZE increased to 6144 bytes from 4096 bytes.
- Service <code>HSE_SRV_ID_FW_INTEGRITY_CHECK</code>. This service checks the integrity of active HSE Firmware in code flash area and backup image in data flash area.
- Service <code>HSE_SRV_ID_BURMESTER_DESMEDT</code>. This service implements the ECC Burmester-Desmedt Protocol to calculate the shared secret between multiple nodes i.e., more than 2.
- Service <code>HSE_SRV_ID_SBAF_UPDATE</code>. This service is used to update the SBAF on the device whenever the Firmware image is not compatible with SBAF present in the system.
- Service <code>HSE_SRV_ID_CMAC_WITH_COUNTER</code>. This service is used to calculate and verify the CMAC by appending the monotonic counter in input message.
- Handling of tamper violations: clock monitoring (CMU) and physical tamper.
- Service <code>HSE_SRV_ID_ON_DEMAND_CORE_RESET</code>. This service allows configuring CR entries and their associated SMR to be processed at run-time, on-demand
- Event <code>HSE_WA_SMR_PERIODIC_CHECK_FAILED</code>. This event signals the host that a periodic check SMR failed (the verification failed).
- Event <code>HSE_WA_DATA_FLASH_INTEGRITY_FAIL</code>. This event signals the host that valid backup of HSE Firmware is not present in data flash.
- Register HSE GPR for tamper status. This register is updated by HSE when a tamper is configured. It can be read by the host to check what tampers are configured.
- Prevention of the accesses to shared memory of other cores via HSE (see hseAttrAllMuMemRegions t attribute).
- Service versioning using a byte from the service ID to encode the version for each service.
- Scatter-Gather support for RSA and ECDSA signature (refer to hseSignSrv_t)
- Added support for Adkp Provisioning via Key Handle.
- Added <code>HSE_CORE_RESET_RELEASE_ATTR_ID</code> attribute to configure the core release-from-reset strategy:
 - all-at-once (cores are release all at once after all boot SMRs (Secure Memory Region) are verified).
 - one-by-one (cores are release one by one as soon as the boot SMR(s) verification passed for that core)
- New HSE attributes (see hseAttrId t):
 - HSE PHYSICAL TAMPER ATTR ID Enablement of physical tamper.
 - → HSE_MEM_REGIONS_PROTECT_ATTR_ID Configure memory regions accessible through each MU.
 - HSE_SECURE_RECOVERY_CONFIG_ATTR_ID Enablement of the secure recovery mechanism.
 - HSE CORE RESET RELEASE ATTR ID Release core from reset.

Updated

- Interface comments.
- The minimum value of Rollover Protection bits in monotonic counter is set to 32 bits and the size of Rollover Protection bits must be multiple of 8 bits.
- The configuration of monotonic counter can be done using only Super User rights.

HSE_FW_S32K344_0_2_40_0_ReleaseNotes

All information provided in this document is subject to legal disclaimers.

© 2023 NXP B.V. All rights reserved.

- SHE keys catalog formatting must be configured for <code>HSE_KEY_OWNER_ANY</code> group owner.
- HSE SRV ID GET RANDOM NUM macro value updated.
- Firmware is not functional if <code>HSE_FIRC_DIVIDER_CONFIG_ATTR_ID</code> is received with request to divide by 16.
- HSE_ENABLE_BOOT_AUTH_ATTR_ID attribute is not enabled if GMAC tag is not programmed in any of the IVT locations on the device.
- The <code>HSE_SRV_ID_ERASE_HSE_NVM_DATA</code> service does not require resetting the device to re-use the firmware services. This service is allowed only in CUST-DEL lifecycle.
- Secure Memory Regions (SMR) (see hseSmrEntry t):
 - Added support for encrypted SMR. The SMRs can be encrypted using GCM or CTR.
 - Removed the SMR verification method field (hseSmrVerifMethod t).
 - The SMR periodic tick has been updated from 10ms to 100ms (at 120 MHz frequency).
 - SMR version number added to provide the anti-rollback protection for the image against attacks during update.
- Core Reset (CR) (see hseCrEntry t):
 - Included PRE-BOOT, ALT_PRE_BOOT and POST-BOOT SMR bit map in Core Reset entries.
 - Included hseCrStartOption_t option: auto-start (automatically release the core from reset at start-up) or on-demand (the core boot is triggered on demand by another application core).
 - For unsecure boot (BOOT_SEQ=0), the SMRs are not loaded at boot time.
 Application can use the hseSmrVerifySrv_t service to load and verify the SMR (for validation purpose).
 - Updated the SHE Secure Boot used with SMR entry#0 (see hseSmrEntryInstallSrv t comments).
- Updated hseSmrVerifySrv_t service to: Verify any SMR using service ID HSE SRV ID SMR VERIFY.
- Fast CMAC:
 - Use input and tag length in bits.
 - Included HSE_FAST_CMAC_MIN_TAG_BIT_LEN_ATTR_ID attribute to configure the minimum tag bit-length that can be used for Fast CMAC verify / generate.
- HSE errors reported to HOST are divided into warnings and errors.
- Error events reported by HSE (see <code>hseError_t</code>). To clear the errors, the host must read the MUB_GSR register and write back the register value (W1C)
- Application header for Basic Secure Boot: "tag address" and "key type" fields were removed; "core ID" field not used; core booted is specified by BOOT_TARGET in IVT; the tag must be placed after the application code (see hseAppHeader_t, hseBootDataImageSignSrv t)
- Import/Export key to support GCM and CCM: AAD, Tag and IV should be specified in the AEAD scheme, and the keyInfo (key proprieties) must be within AAD (see hseImportKeySrv t, hseExportKeySrv t)
- HMAC to support key sizes greater than hash block size (updated hseMacSrv_t service)
- Erase service to delete the SHE keys only if system authorization was performed beforehand using MASTER_ECU key. Other keys (non-SHE keys) can be erased if the authorization operation was performed using any key type, including MASTER_ECU key (see hseEraseKeySrv_t)

HSE_FW_S32K344_0_2_40_0_ReleaseNotes

All information provided in this document is subject to legal disclaimers.

© 2023 NXP B.V. All rights reserved.

- Load ECC service to save the ECC user-curve domain parameters in SYS-IMG (which
 needs to be published). The host needs Super User rights to be able to load an ECC
 user-defined curve. The loaded ECC user-defined curves must have the private key
 size equal to or greater than 192 bits
- SYS Authorization feature (see hseSysAuthorizationReqSrv_t) to perform the authorization using the SHE MASTER_ECU_KEY. SHE keys can be erased only if the host is authorized with MASTER ECU KEY.
- The host must call the <code>HSE_SRV_ID_ACTIVATE_PASSIVE_BLOCK service</code> to load new HSE Firmware after successful execution of the HSE Firmware update service in case of AB swap configuration.
- The SYS-IMG configured for 0.0.8.3 Firmware release is not compatible with this release. The Host must reconfigure the SYS-IMG.
- The size of HSE Firmware increased from 80KB to 128KB, the implications of this change would be:
- AB swap firmware cannot be installed through older version of Secure BAF (Boot Assist Flash).
- The Host must free up 40KB from DATA Flash out of 128KB. Hence, DATA Flash range that can be used by the Host is [0x10000000 – 0x10015FFF].
- The Host must free up 168KB from CODE Flash memory,
- Available CODE Flash range in FULL MEM configuration [0x400000 – 0x7D3FFF].
- Available CODE Flash range in AB SWAP configuration ACTIVE BLOCK: [0x400000 – 0x5D3FFF]
 PASSIVE BLOCK: [0x600000 – 0x7D3FFF]
- Removed
 - All TDES support.
 - IV Length parameter from symmetric cipher (see hseSymCipherSrv t)
 - HSE_KDF_SP800_108_FEEDBACK and HSE_KDF_SP800_108_PIPELINE KDF SP800 modes. Only Counter Mode remained supported.
 - The restriction on allowing an SMR to be updated, in advanced life cycles
 (OEM PROD, IN FIELD), only if it is already verified successfully. (ASHF-3433)

for S32K344 HSE Firmware 0.2.40.0

16 Known Issues

• N/A

17 List of Limitations

- The HSE Firmware is operational when HSE CLK is between 24MHz to 120MHz.
- User should restart the device once Firmware Update is completed in FULL_MEM configuration.
- In GCM operations, it is recommended to use IV values of exactly 12 bytes. For any IV size different from 12 bytes, the authentication tag generated by the GCM encryption operation might not be correct. In GCM decryption operations, the authentication check might fail.

18 HSE Firmware Version and S32K3XX Device Compatibility

The Table below explains the HSE Firmware version number compatibility with the S32K3 family devices.

Table 1. HSE FW Version Compatibility with S32K3 Devices

S.NO	HSE Firmware version number [<configtype>_ <soctypeid>_ <fwtypeid>_ <majorversion>_ <minorversion>_ <patchversion>]</patchversion></minorversion></majorversion></fwtypeid></soctypeid></configtype>	Remarks	Applicable HSE Firmware reference manuals	Release Date
1	s32k3xx_hse_fw_0.5.0_0.8.3_pb200928.bin (FullMem) s32k3xx_hse_fw_1.5.0_0.8.3_pb200928.bin(AB Swap)	HSE Firmware Standard EAR release compatible with S32K344 Device. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual - V0 - Draft J	30th-Sep- 2020
2	s32k3x4_hse_fw_0.5.0_0.10.0_pb210630.bin (FullMem) s32k3x4_hse_fw_1.5.0_0.10.0_pb210630.bin(AB Swap)	HSE Firmware Standard EAR2 release compatible with S32K344 Device. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual - V0 - Draft K	30th-June- 2021
3	s32k3x2_hse_fw_0.13.0_0.11.0_pb210726.bin (FullMem) s32k3x2_hse_fw_1.13.0_0.11.0_pb210726.bin (AB Swap)	HSE Firmware Standard EAR release compatible with S32K311 Device. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual - V0 - Draft M	16 th -Aug- 2021
4	s32k3x4_hse_fw_0.5.0_0.12.0_pb210903.bin (FullMem) s32k3x4_hse_fw_1.5.0_0.12.0_pb210903.bin (AB Swap)	HSE Firmware Standard BETA release compatible with S32K344 Device. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual - V1.0	3 rd -Sep- 2021
5	s32k3x4_hse_fw_0.5.0_1.1.0_pb211004.bin (FullMem) s32k3x4_hse_fw_1.5.0_1.1.0_pb211004.bin (AB Swap)	HSE Firmware Standard RTM release compatible with S32K344 Device. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual - V1.1	13 th -Oct- 2021
6	s32k3x2_hse_fw_0.13.0_0.14.0_pb211207.bin (FullMem) s32k3x2_hse_fw_1.13.0_0.14.0_pb211207.bin (AB Swap)	HSE Firmware Standard EAR release compatible with S32K342/S32K341/S32 K322 Devices. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual - V1.1	30th-Nov- 2021
7	s32k3x2_hse_fw_0.13.0_1.2.0_pb211228.bin (FullMem) s32k3x2_hse_fw_1.13.0_1.2.0_pb211228.bin (AB Swap)	HSE Firmware Standard BETA release compatible with S32K311 Device. This release supports	HSE-B Firmware Reference	18 th -Jan- 2022

Table 1. HSE FW Version Compatibility with S32K3 Devices...continued

Table	1. HSE FW Version Compatibility with 532K3 Devicesco	both Full Mem/AB Swap configuration.	Manual - V1.2	
8	s32k3x2_hse_fw_0.13.0_1.2.1_pb220205.bin (FullMem) s32k3x2_hse_fw_1.13.0_1.2.1_pb220205.bin (AB Swap)	HSE Firmware Standard hotfix release compatible with S32K312 Device. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual - V1.2	07 th -Feb- 2022
9	s32k3x4_hse_fw_0.5.0_2.1.0_pb220607.bin (FullMem) s32k3x4_hse_fw_1.5.0_2.1.0_pb220607.bin (AB Swap)	HSE Firmware Standard RTM release compatible with S32K344 Device. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual – V2.0	30 th -June- 2022
10	s32k3x2_hse_fw_0.13.0_2.6.0_pb221129.bin (FullMem) s32k3x2_hse_fw_1.13.0_2.6.0_pb221129.bin (AB Swap)	HSE Firmware Standard RTM release compatible with S32K311 Device. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual – V2.0	9 th -Dec- 2022
11	s32k3x2_hse_fw_0.13.0_2.8.0_pb221129.bin (FullMem) s32k3x2_hse_fw_1.13.0_2.8.0_pb221129.bin (AB Swap)	HSE Firmware Standard RTM release compatible with S32K342/S32K341/S32 K322 Devices. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual – V2.0	9 th -Dec- 2022
12	s32k3x6_hse_fw_0.15.0_2.7.0_pb221207.bin (FullMem) s32k3x6_hse_fw_0.15.0_2.7.0_pb221207.bin (AB Swap)	HSE Firmware Standard EAR release compatible with S32K396 Devices. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual – V2.1	9 th -Dec- 2022
13	s32k3x8_hse_fw_0.14.0_2.12.0_pb221206.bin (FullMem) s32k3x8_hse_fw_0.14.0_2.12.0_pb221206.bin (AB Swap)	HSE Firmware Standard EAR release compatible with S32K358 Devices. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual – V2.1	9 th -Dec- 2022
14	s32k342_hse_fw_0.13.0_2.31.0_pb230524.bin (FullMem) s32k342_hse_fw_1.13.0_2.31.0_pb230524.bin (AB Swap)	HSE Firmware Standard Code Drop release compatible with S32K342 Devices. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual – V2.1	30 th -May- 2023
15	s32k312_hse_fw_0.13.0_2.32.0_pb230620.bin (FullMem) s32k312_hse_fw_1.13.0_2.32.0_pb230620.bin (AB Swap)	HSE Firmware Standard Code Drop release compatible with S32K312 Devices. This release supports both Full Mem/AB Swap configuration.	HSE-B Firmware Reference Manual – V2.1	20 th -Jun- 2023
16	s32k312_hse_fw_0.13.0_2.40.0_pb230730.bin (FullMem) s32k312_hse_fw_0.13.0_2.40.0_pb230730.bin (AB Swap)	HSE Firmware RTM release compatible with S32K312 Devices. This release	HSE-B Firmware Reference	2 nd -Aug- 2023

HSE_FW_S32K344_0_2_40_0_ReleaseNotes

All information provided in this document is subject to legal disclaimers.

© 2023 NXP B.V. All rights reserved.

Table 1. HSE FW Version Compatibility with S32K3 Devices...continued

		supports both Full Mem/AB Swap configuration.	Manual – V2.2	
17	s32k311_hse_fw_0.12.0_2.40.0_pb230730.bin (FullMem) s32k311_hse_fw_0.12.0_2.40.0_pb230730.bin (AB Swap)	HSE Firmware RTM release compatible with S32K311 Devices. This release integrates the latest SBAF releases for both Full Mem and AB Swap configurations.	HSE-B Firmware Reference Manual – V2.2	7 th -Aug- 2023
18	s32k344_hse_fw_0.5.0_2.40.0_pb230807.bin (FullMem) s32k344_hse_fw_1.5.0_2.40.0_pb230807.bin (AB Swap)	HSE Firmware SR release compatible with S32K342 Devices. New AB Swap is included with this release.	HSE-B Firmware Reference Manual – V2.2	16 th -Aug- 2023

19 List of Services Available

All available HSE features/services are also listed in the *hse_b_config.h* file (from HSE Interface). All other features not listed in the table below (or enabled in *hse_b_config.h* file) **are NOT supported**. All available services applicable for both configuration device.

Table 2. Available HSE Features/Services

Table 2. Availai	ole HOL I eathres/dervices	
Service Class	HSE Service ID	Description/Notes
Administrative	HSE_SRV_ID_SET_ATTR	Set an HSE attribute. Attributes related to UTEST memory can be written only once (e.g. Debug Key) or can only be advanced (e.g. Life cycle). Care must be taken.
	HSE_SRV_ID_GET_ATTR	Get an HSE attribute.
	HSE_SRV_ID_CANCEL	Cancel a one-pass or streaming service on a specific channel. An HSE service request can be cancelled if it is in the processing queue and NOT passed to the hardware to be executed.
	HSE_SRV_ID_FIRMWARE_ UPDATE	HSE Firmware update This service covers the following things: 1. Firmware update in FullMem configuration for Standard Firmware with one-pass/streaming mode 2. Firmware update in ABSwap configuration for Standard Firmware with one-pass/streaming mode
	HSE_SRV_ID_SBAF_ UPDATE	Secure-BAF update in FullMem configuration for Standard Firmware with one-pass/streaming mode
	HSE_SRV_ID_SYS_AUTH_ REQ	SYS Authorization request used to request the Super User rights (CUST/OEM).
	HSE_SRV_ID_SYS_AUTH_ RESP	SYS Authorization response (response to SYS Authorization Request)
	HSE_SRV_ID_BOOT_DATA_ IMAGE_SIGN	Generate the signature on Boot Header & XRDC image using ADKP
	HSE_SRV_ID_BOOT_DATA_ IMAGE_VERIFY	Verify the signature on Boot Header & XRDC image using ADKP
	HSE_SRV_ID_IMPORT_ EXPORT_STREAM_CTX	Import and Export service for the crypto streaming context.
	HSE_SRV_ID_ERASE_HSE_ NVM_DATA	Erase HSE Data Flash only in customer delivery lifecycle
	HSE_SRV_ID_ERASE_FW	Erase the HSE Firmware in code flash, back up area and sys image
	HSE_SRV_ID_FW_ INTEGRITY_CHECK	Triggers the integrity check of HSE Firmware code flash and data flash area.
	HSE_SRV_ID_PUBLISH_ NVM_KEYSTORE_RAM_TO_ FLASH	Application requests the firmware to write the NVM keys from RAM mirrored keystore into the data flash. This service has no parameters.
Key Management	HSE_SRV_ID_LOAD_ECC_ CURVE	Load the domain parameters for a Weierstrass ECC curve. This service can be used to support additional Weierstrass ECC curves (Not supported by default). The loaded ECC curve domain parameters are persistent.
	HSE_SRV_ID_FORMAT_ KEY_CATALOGS	Format key application key catalogs (RAM & NVM).

Table 2. Available HSE Features/Services...continued

Service Class	HSE Service ID	Description/Notes
	HSE_SRV_ID_ERASE_KEY	Erase NVM/RAM key(s). Erase key service depends on authorization rights. One or multiple keys can be erased. Selected key group can also be erased
	HSE_SRV_ID_GET_KEY_ INFO	Get key proprieties (flags).
	HSE_SRV_ID_IMPORT_KEY	Import a key. Uses all algorithms supported by HSE firmware: * Plain form or AES / RSA encrypted. * MAC authenticated (refer to supported MAC algorithms) or RSA / ECDSA signed. * Import key restrictions depends on sys authorization rights. The restrictions are described by the service in the interface.
	HSE_SRV_ID_EXPORT_KEY	Export a key. Uses all algorithms supported by HSE firmware: * Plain form (only public keys) or AES / RSA encrypted. * MAC authenticated (refer to supported MAC algorithms) or RSA / ECDSA signed. * Export key restrictions depends on authorization rights. The restrictions are described by the service in the interface.
	HSE_SRV_ID_KEY_ GENERATE	Request to generate a symmetric/asymmetric key. * Random symmetric key generation * RSA and ECC key pair generation
	HSE_SRV_ID_DH_ COMPUTE_SHARED_ SECRET	* Montgomery curve: CURVE25519 * 1 user-defined ECC curves (see Load ECC curve service)
	HSE_SRV_ID_KEY_DERIVE	Perform a key derivation function: * NXP Generic KDF, SP800_56C One Step, SP800_56C Two Step, ANSI_X963, SP800_108 (Only Counter Mode), ISO/IEC 18033 KDF1, ISO/IEC 18033 KDF2, PBKDF2HMAC, HKDF, TLS12PRF
	HSE_SRV_ID_KEY_DERIVE_ COPY	Extract a key from the derived key material to a key slot.
	HSE_SRV_ID_KEY_VERIFY	Computes a hash/MAC over a symmetric key inside HSE key store.
	HSE_SRV_ID_SHE_LOAD_ KEY	Load a SHE key using the SHE memory update protocol.
	HSE_SRV_ID_SHE_LOAD_ PLAIN_KEY	Loads SHE specification-based RAM key as plain text.
	HSE_SRV_ID_SHE_ EXPORT_RAM_KEY	Exports RAM key as per SHE specification.
	HSE_SRV_ID_SHE_GET_ID	GETUID as per SHE specification.
	HSE_SRV_ID_SHE_BOOT_ OK	The command is used to mark successful boot verification for later stages than CMD_SECURE_BOOT. For more details, see SHE specification

Table 2. Available HSE Features/Services...continued

	ole HSE Features/Servicescom	
Service Class	HSE Service ID	Description/Notes
	HSE_SRV_ID_SHE_BOOT_ FAILURE	The command will impose the same sanctions as if CMD_SECURE_ BOOT would detect a failure but can be used during later stages of the boot process. For more details, see SHE specification.
ROM Keys	N/A	Support for ROM keys (only AES keys).
Cryptographic	HSE_SRV_ID_HASH	Hash service (one-pass and streaming): * SHA1 * SHA-224, SHA-256, SHA-384, SHA-512, SHA-512/224, SHA-512/256 * Miyaguchi-Preneel compression function (SHE specification support)
	HSE_SRV_ID_MAC	Request to generate/verify a Message Authentication Code (MAC): * AES-CMAC, AES-GMAC * HMAC_(SHA1, SHA_224, SHA_256, SHA_384, SHA_512)
	HSE_SRV_ID_FAST_CMAC	Low latency, high performance CMAC generate/verify request
	HSE_SRV_ID_SYM_CIPHER	Symmetric encryption/decryption (one-pass and streaming): * AES-128/-192/-256: ECB, CBC, CTR, OFB, CFB
	HSE_SRV_ID_AEAD	AEAD encryption/decryption: * AES-CCM-128/-192/-256 (one-pass, no streaming support) * AES-GCM-128/-192/-256 (one-pass and streaming)
	HSE_SRV_ID_SIGN	Request a Digital Signature Generation/Verification (one-pass and streaming): * RSASAA_PSS (1024, 2048, 3072, 4096) * RSASAA_PKCS1-v1_5(1024, 2048, 3072, 4096) * ECDSA (all supported ECC curves) * EDDSA (for ED25519 curve)
	HSE_SRV_ID_RSA_CIPHER	RSA encryption/decryption: * RSAES-PKCS1-v1_5 (1024, 2048, 3072, 4096) * RSAES-OEAP (1024, 2048, 3072, 4096)
RNG	HSE_SRV_ID_GET_ RANDOM_NUM	Get a random number. AIS31 and FIPS 140-2 compliant
Counters	HSE_SRV_ID_INCREMENT_ COUNTER	Incrementing Non-volatile counter.
	HSE_SRV_ID_READ_ COUNTER	Read Non-volatile counter.
	HSE_SRV_ID_CONFIG_ COUNTER	Configure the secure counter.
Advance Secure Booting (SMR/CR)	HSE_SRV_ID_SMR_ENTRY_ INSTALL	Install a Secure Memory Region (SMR) table entry.
	HSE_SRV_ID_SMR_VERIFY	Verify (on demand) a Secure Memory Region (SMR) table entry.
	HSE_SRV_ID_CORE_ RESET_ENTRY_INSTALL	Install a Core Reset (CR) table entry.
	HSE_SRV_ID_ON_ DEMAND_CORE_RESET	On-demand release a core from a reset after loading and verification

Table 2. Available HSE Features/Services...continued

Se	ervice Class	HSE Service ID	Description/Notes
		HSE_SRV_ID_SMR_ENTRY_ ERASE	Erase an SMR Entry.
		HSE_SRV_ID_CORE_ RESET_ENTRY_ERASE	Erase a CR Entry.

The service below is applicable only for AB SWAP configuration device.

Table 3. Services for AB SWAP Configuration Device

Service Class	HSE Service ID	Description/Notes
	HSE_SRV_ID_ACTIVATE_ PASSIVE_BLOCK	Switch to passive area. Using this service application can switch to passive area.

20 Legal information

20.1 Definitions

Draft — A draft status on a document indicates that the content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included in a draft version of a document and shall have no liability for the consequences of use of such information.

20.2 Disclaimers

Limited warranty and liability — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information. NXP Semiconductors takes no responsibility for the content in this document if provided by an information source outside of NXP Semiconductors.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms and conditions of commercial sale of NXP Semiconductors.

Right to make changes — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

Suitability for use — NXP Semiconductors products are not designed, authorized or warranted to be suitable for use in life support, life-critical or safety-critical systems or equipment, nor in applications where failure or malfunction of an NXP Semiconductors product can reasonably be expected to result in personal injury, death or severe property or environmental damage. NXP Semiconductors and its suppliers accept no liability for inclusion and/or use of NXP Semiconductors products in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk.

Applications — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

Customers are responsible for the design and operation of their applications and products using NXP Semiconductors products, and NXP Semiconductors accepts no liability for any assistance with applications or customer product design. It is customer's sole responsibility to determine whether the NXP Semiconductors product is suitable and fit for the customer's applications and products planned, as well as for the planned application and use of customer's third party customer(s). Customers should provide appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on any weakness or default in the customer's applications or products, or the application or use by customer's third party customer(s). Customer is responsible for doing all necessary testing for the customer's applications and products using NXP Semiconductors products in order to avoid a default of the applications and the products or of the application or use by customer's third party customer(s). NXP does not accept any liability in this respect.

Terms and conditions of commercial sale — NXP Semiconductors products are sold subject to the general terms and conditions of commercial sale, as published at http://www.nxp.com/profile/terms, unless otherwise agreed in a valid written individual agreement. In case an individual agreement is concluded only the terms and conditions of the respective agreement shall apply. NXP Semiconductors hereby expressly objects to applying the customer's general terms and conditions with regard to the purchase of NXP Semiconductors products by customer.

Export control — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from competent authorities.

Suitability for use in non-automotive qualified products — Unless this document expressly states that this specific NXP Semiconductors product is automotive qualified, the product is not suitable for automotive use. It is neither qualified nor tested in accordance with automotive testing or application requirements. NXP Semiconductors accepts no liability for inclusion and/or use of non-automotive qualified products in automotive equipment or applications.

In the event that customer uses the product for design-in and use in automotive applications to automotive specifications and standards, customer (a) shall use the product without NXP Semiconductors' warranty of the product for such automotive applications, use and specifications, and (b) whenever customer uses the product for automotive applications beyond NXP Semiconductors' specifications such use shall be solely at customer's own risk, and (c) customer fully indemnifies NXP Semiconductors for any liability, damages or failed product claims resulting from customer design and use of the product for automotive applications beyond NXP Semiconductors' standard warranty and NXP Semiconductors' product specifications.

Translations — A non-English (translated) version of a document, including the legal information in that document, is for reference only. The English version shall prevail in case of any discrepancy between the translated and English versions.

Security — Customer understands that all NXP products may be subject to unidentified vulnerabilities or may support established security standards or specifications with known limitations. Customer is responsible for the design and operation of its applications and products throughout their lifecycles to reduce the effect of these vulnerabilities on customer's applications and products. Customer's responsibility also extends to other open and/or proprietary technologies supported by NXP products for use in customer's applications. NXP accepts no liability for any vulnerability. Customer should regularly check security updates from NXP and follow up appropriately. Customer shall select products with security features that best meet rules, regulations, and standards of the intended application and make the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP.

NXP has a Product Security Incident Response Team (PSIRT) (reachable at PSIRT@nxp.com) that manages the investigation, reporting, and solution release to security vulnerabilities of NXP products.

20.3 Trademarks

Notice: All referenced brands, product names, service names, and trademarks are the property of their respective owners.

NXP — wordmark and logo are trademarks of NXP B.V.

HSE_FW_S32K344_0_2_40_0_ReleaseNotes

All information provided in this document is subject to legal disclaimers.

© 2023 NXP B.V. All rights reserved.

NXP Semiconductors

Release Notes

for S32K344 HSE Firmware 0.2.40.0

Tables

Tab. 1.	HSE FW Version Compatibility with S32K3	Tab. 3.	Services for AB SWAP Configuration	
	Devices21		Device	27
Tab. 2.	Available HSE Features/Services24			

for S32K344 HSE Firmware 0.2.40.0

Contents

1	Getting Started	1
1.1	Package content	
1.2	Installation	
2	Release Details	2
2.1	Supported Derivatives	2
2.2	Device Bricking scenario for HSE Firmware	
2.3	Security Aspects	
3	Changes in 0.2.40.0	
4	Changes in 0.2.32.0	
5	Changes in 0.2.31.0	
6	Changes in 0.2.12.0	e
7	Changes in 0.2.7.0	7
8	Changes in 0.2.8.0	
9	Changes in 0.2.6.0	
10	Changes in 0.2.1.0	10
11	Changes in 0.1.2.1 (hotfix)	12
12	Changes in 0.1.2.0	13
13	Change logs in 0.1.1.0	14
14	Change logs in 0.0.12.0	15
15	Change logs in 0.0.10.0	16
16	Known Issues	19
17	List of Limitations	20
18	HSE Firmware Version and S32K3XX	
	Device Compatibility	21
19	List of Services Available	24
20	Legal information	28

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.