INSTRUCTIONS FOR CREATING SUBFORM: 3.4-LPRP-Annual

Follow these steps to create the form fields:

STEP 1: Create a Single Select field

Contractor: UNITY

Description: 3.4-A-LPRP-1: Visually inspect for dirt, debris, moisture. Vacuum and wipe down dirty surfaces. Test overcurrent devices if moisture

found and replace if required

Options: Yes, No