

Device test report

Measurements, limits and declared outcomes

MODEL	SERIAL NUMBER
SLX-CTRL-01	SLX-00042
TEST DATE	OPERATOR
2026-10-05	Example operator
STATION	PROCEDURE REVISION
BENCH-01	A

OVERALL OUTCOME

FAIL · INVALID DATA · INCOMPLETE

15 tests · 10 passed · 2 failed · 1 skipped · 2 invalid



Report ID: TR-20261005-131829-973-001

2026-10-05 15:18:29 GMT+2

CSV: demo.csv

SHA-256: 0cb22100cc70c52eaa497252179433c88d2f8628de8b61ebdfcc78b7b0fe12d5

Test profile: demo-profile.json · revision A

Profile SHA-256: c07fac8f9e27f49f147aea639742ab5144b773e6747ecc83ec5ed73e30b5de87

TEST	VALUE	UNIT	MIN / MAX	OUTCOME
Input supply	12.08	V	11.8 / 12.2	Pass
5 V output	5.04	V	4.9 / 5.1	Pass
Idle current	0.21	A	0 / 0.3	Pass
Output ripple	18	mV	0 / 25	Pass
Board temperature	42	°C	0 / 70	Pass
ADC reference	2.498	V	2.48 / 2.52	Pass
Auxiliary; output voltage	3.31	V	3.2 / 3.4	Pass
Load current	0.42	A	0 / 0.3	Fail
Above profile upper limit · CSV line 9				
Insulation resistance	—	MΩ	100 / —	Invalid data
Missing measurement · CSV line 10				

Test results · SLX-00042

TEST	VALUE	UNIT	MIN / MAX	OUTCOME
Oscillator frequency	1001	kHz	990 / 1010	Pass
Reverse leakage	0.02	mA	— / 0.05	Pass
Barcode readability	—	—	— / —	Pass
Scanner read confirmed · CSV line 13				
Relay switching	—	—	— / —	Fail
Functional check failed · Contact did not close · CSV line 14				
Firmware programming	—	—	— / —	Skipped
Not executed · Awaiting approved image · CSV line 15				
Status LED	—	—	— / —	Invalid data
Required test absent from CSV · Required by profile				

Evidence notes

TEST 8 · CSV LINE 9

Load current
Above profile upper limit

TEST 9 · CSV LINE 10

Insulation resistance
Missing measurement

TEST 12 · CSV LINE 13

Barcode readability
Scanner read confirmed

TEST 13 · CSV LINE 14

Relay switching
Functional check failed · Contact did not close

TEST 14 · CSV LINE 15

Firmware programming
Not executed · Awaiting approved image

TEST 15 · REQUIRED BY PROFILE

Status LED
Required test absent from CSV