* Can select each function for any PIN

For POT object can use any PIN with ANALOG support.

For LAMP can use any PIN with OUTPUT support.

For SW, ROTARY, ENCODER can use any PIN with INPUT support.

For drive gauge motors use pins marked as STP1-4 and PWM.

The system will set function based on the operation selected.

64KB LRU0000

Left pin	Label		Right label	Right pin
VDD	P01	PWR & CANBus	PWR & CANBus VDD	P40
VSS	P02		VSS	P39
CANL	P03		CANL	P38
CANH	P04		CANH	P37
INPUT/OUTPUT/RX/D7	P05	INPUT OUTPUT UART2	OUTPUT PWM UART1 OUTPUT/RX/PWM4/C7	P36
INPUT/OUTPUT/TX/D6	P06		OUTPUT/TX/PWM3/C6	P35
INPUT/OUTPUT/D5	P07		OUTPUT SPI OUTPUT/SDO/C5	P34
INPUT/OUTPUT/D4	P08		OUTPUT/SDI/C4	P33
INPUT/OUTPUT/D3	P09		OUTPUT/SCK/C3	P32
INPUT/OUTPUT/D2	P10	INPUT OUTPUT	OUTPUT PWM OUTPUT/PWM2/C2	P31
INPUT/OUTPUT/D1	P11		OUTPUT/C1	P30
INPUT/OUTPUT/D0	P12		OUTPUT/C0	P29
INPUT/OUTPUT/B7	P13		OUTPUT/ANALOG/A5	P28
INPUT/OUTPUT/B6	P14		OUTPUT/ANALOG/STP4/A3	P27
INPUT/OUTPUT/PWM5/B5	P15	INPUT OUTPUT ANALOG PWM	OUTPUT ANALOG OUTPUT/ANALOG/STP3/A2	P26
INPUT/OUTPUT/ANALOG/B4	P16		OUTPUT/ANALOG/STP2/A1	P25
INPUT/OUTPUT/ANALOG/B1	P17		OUTPUT/ANALOG/STP1/A0	P24
INPUT/OUTPUT/ANALOG/B0	P18		INPUT/OUTPUT INPUT/OUTPUT/E2	P23
VSS	P19	GND	LEDS OUTPUT OUTPUT/LEDR/E1	P22
INPUT/E3	P20	INPUT	OUTPUT/LEDG/E0	P21