

ABC COMPANY Instruction/Comment Report

	Description	Priority	Instruction	Comment	Wave File
40	Fire input 7 is triggered	Normal			
\1	Fire input 8 is triggered	Normal			
\2	Fire Alarm all triggered	Normal			
AC	Alarm Is Triggered	Normal			
	Alarm Relay is Triggered	Normal			
٩i	Duress Alarm is triggered	Normal			
٩k	Reader is tampered	Normal			
ΑI	Digital input 1 is triggered	Normal			
٩m	Digital input 2 is triggered	Normal			
An	Digital input 3 is triggered	Normal			
٩٥	Digital input 4 is triggered	Normal			
Αр	Supervise input 1 is triggered	Normal			
Αq	Supervise input 2 is triggered	Normal			
Ar	Supervise input 3 is triggered	Normal			
As	Supervise input 4 is triggered	Normal			
At	Fire Alarm is triggered	Normal			
Αu	Fire input 1 is triggered	Normal			
٩v	Fire input 2 is triggered	Normal			
٩w	Fire input 3 is triggered	Normal			
٩x	Fire input 4 is triggered	Normal			
Ау	Fire input 5 is triggered	Normal			
Az	Fire input 6 is triggered	Normal			
BD	SD Card Not Found	Normal			
BE	Invalid SD Card	Normal			
Вс	Reader Down	Normal			
Вi	AC Power Fail	Normal			
Bk	Battery Low	Normal			
Во	N-MINI Comm. Down	Normal			
Вq	P2P Apb Fail	Normal			
Bz	Battery Cut Off	Normal			
СВ	GT Duress Alarm	Normal			
Dd	Door is forced open	Normal			
De	Door is left open	Normal			
Dn	Access Limits Full	Normal			
E3	Harddisk Full	Normal			
G3	Disarm Zone - Fail	Normal			
G5	Arm Board - Fail	Normal			

Printed on: 10/08/2018 17:14:41 Page: 1

Code	Description	Priority	Instruction	Comment	Wave File
G7	Disarm Board - Fail	Normal			
G9	Arm Zone - Fail	Normal			
Gb	Trigger Output - Fail	Normal			
Gc	Input Triggered	Normal			
Gh	Reset Output - Fail	Normal			
Gp	Reset Board - Fail	Normal			
Gs	Output Reset (Keypad) - Fail	Normal			
Gu	Reset Zone - Fail	Normal			
Gv	Daughter Board Not Exists	Normal			
Hb	Reserved	Normal			
Hg	Fire Input Is Triggered	Highest	Test Instruction	Test Comments	
Hi	Reader Is Tampered	Normal			
н	GP Input Is Triggered	Normal			
lp	DRB Down	Normal			
lr	Gateway DRB Comm. Down	Normal			
It	OSDP DRB Comm. Down	Normal			
lv	OSDP I/O Board Comm. Down	Normal			
lx	Gateway IOB Comm. Down	Normal			
S6	Input Trigger (Software)	Normal			
S7	Zone Trigger (Software)	Normal			
SB	Connection Lost	Normal			
SK	Controller Down	Normal			
SS	Thread Stopped	Normal			
SV	I/O Board Down	Normal			
Tj	P1 Enterprise Down	Normal			

Printed on: 10/08/2018 17:14:41 Page: 2