QPU Instruction Set

opcode

0

Op Add

Instruction

nop

ror

shl

min

max

and

Table 12: Op Add Instructions

DescriptionNo operation

fadd	1	Floating point add
lauu		Floating point add
fsub	2	Floating point subtract
fmin	3	Floating point min
fmax	4	Floating point max
fminabs	5	Floating point min of absolute values
fmaxabs	6	Floating point max of absolute values
ftoi	7	Floating point to signed integer
itof	8	Signed integer to floating point
_	9–11	Reserved
add	12	Integer add
sub	13	Integer subtract
shr	14	Integer shift right
asr	15	Integer arithmetic shift right

16

17

18 19

20

Integer rotate right

Integer shift left

Integer min

Integer max

Bitwise AND