ALUOp		Funct field						
ALUOp1	ALUOp0	F5	F4	F3	F2	F1	FO	Operation
0	0	Х	Х	Х	Х	Х	Х	0010
X	1	Х	Х	Х	Х	Х	Х	0110
1	X	Х	Х	0	0	0	0	0010
1	X	Х	Х	0	0	1	0	0110
1	X	Х	Х	0	1	0	0	0000
1	X	Х	Х	0	1	0	1	0001
1	X	Х	Х	1	0	1	0	0111

FIGURE 4.13 The truth table for the 4 ALU control bits (called Operation). The inputs are the ALUOp and function code field. Only the entries for which the ALU control is asserted are shown. Some don't-care entries have been added. For example, the ALUOp does not use the encoding 11, so the truth table can contain entries 1X and X1, rather than 10 and 01. Note that when the function field is used, the first 2 bits (F5 and F4) of these instructions are always 10, so they are don't-care terms and are replaced with XX in the truth table.

Copyright © 2021 Elsevier Inc. All rights reserved