

FIGURE C.6.2 Double precision fused-multiply-add (FMA) unit. Hardware to implement fl oatingpoint $A \times B + C$ for double precision.